$$F = \frac{mv^{2}}{r} = mr \omega^{2}$$

$$F = 0.2 (0.5) (100^{2}) = 1000 N$$

$$T = 1000 \times 0.25 = 250 Nm.$$

