

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form	Effective 10-JUL-2026
Location Houston (Corporate)		ETX ID 3.100.019.F01	
Printed by qchen@eagleanalytical.com from https://app.zenqms.com on 08-Sep-2026 at 8:45:15 PM UTC			Page 1 of 6

OOS Number: OOS- 261814

Phase I

Section A – Test Details					
Initiator:	Sonal Uprety (Written by: Qiyue Chen)	Test Date:	07-Aug-2026	Date Initiated:	07-Aug-2026
Date of Incident:	07-Aug-2026	Test Name:	Scan RDI Sterility Test	Sample ID:	ETX-260805-0189
Name of Analyst who Performed the Test:	Prepper: Elysse Nioupin (EN)	Sample / Active Name	Tirzepatide/B12 25/1mg/mL Injectable	Lot #:	18468
	Processor: Sonal Uprety (SU)				
	Changeover Processor: Gerald Anyangwe (GA)	Dosage Form	Injectable		
	Reader: Varsha Subramanian (VV)				
Description of Incident:	On 07Aug26, sample ETX-260805-0189 was found positive for viable microorganisms after ScanRDI testing.		☒ Client Care notified of OOS ☒ Sterility and Endotoxin test related OOS; Client must be notified within 24 hours of OOS		
	SOP / Test Method # MICRO-SOP-12 (16) ENG-SOP-4 (05)	Effective Date: 24Jul26 24Jul26	SOP / Test Method Rev: Rev: 16 Rev: 05	Limits/Specification: <1 event	
Manager notified	Manager/designee name: Kathan Parikh	Date: 07-Aug-2026	Quality Assurance Department notified:	Yes ☒ No ☐	
Section B – Investigation and Root Cause Analysis					
Personnel Discrepancy			Comments		
Analyst interviewed?	☒ Yes ☐ No ☐ N/A		Yes, analysts Elysse Nioupin, Sonal Uprety, Gerald Anyangwe, and Varsha Subramanian were interviewed comprehensively.		
Correct samples analyzed?	☒ Yes ☐ No ☐ N/A		Yes, ETX-260805-0189		
Correct SOP / Test Method used/followed?	☒ Yes ☐ No ☐ N/A		Yes, as per MICRO-SOP-12, ENG-SOP-4		
Correct sample collection/technique?	☒ Yes ☐ No ☐ N/A		Yes, as per MICRO-SOP-12, ENG-SOP-4		
Are the Test Result Records Attached & Calculations Verified and Correct?	☒ Yes ☐ No ☐ N/A		Yes, See 080726-1040-2 for more information.		
Is the analyst qualified to perform the test?	☒ Yes ☐ No ☐ N/A		Yes, all analysts are trained and qualified by quality to perform the test.		
Is formula worksheet provided and verified?	☐ Yes ☐ No ☒ N/A		Not Applicable		
Does the processing method/method set conform to the required specification?	☐ Yes ☐ No ☒ N/A		Not Applicable		
Was the sample stored appropriately?	☒ Yes ☐ No ☐ N/A		Yes, Information is available in Eagle Trax Sample Location History under ETX-260805-0189		
Material Discrepancy			Lot Number	Expiry Date	
Is the integrity of the sample(s) questionable?	☐ Yes ☒ No ☐ N/A				
Was the sample transported appropriately?	☒ Yes ☐ No ☐ N/A				
Are the other test results from this run under investigation?	☐ Yes ☒ No ☐ N/A				

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form	Effective 10-JUL-2026
Location Houston (Corporate)		ETX ID 3.100.019.F01	
Printed by qchen@eagleanalytical.com from https://app.zenqms.com on 08-Sep-2026 at 8:45:15 PM UTC			Page 2 of 6

OOS Number: OOS- 261814

Appropriate/correct glassware used?	☐ Yes ☐ No ☒ N/A		
Are reagents stored in proper condition and not expired?	☒ Yes ☐ No ☐ N/A	Scan Consumables: See the attached data packet Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly cleaning logs	Scan Consumables: See the attached data packet Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly cleaning logs
Standard Used	A. brasiliensis	05222026-16404-AB	22May28
Solvent Used	Not Applicable	Not Applicable	Not Applicable
Is the standard the source of the root cause?	☐ Yes ☐ No ☒ N/A		
Has the analyst been instructed to keep the original test solution for possible retesting?	☐ Yes ☐ No ☒ N/A		
Equipment Discrepancy		Equipment ID	Calibration Due Date
Was the instrument set up correctly?	☒ Yes ☐ No ☐ N/A	E001040	Oct 2026
Is the clean room facility certified?	☒ Yes ☐ No ☐ N/A	E001737 (CR115) & E001978 (L-Suite)	Dec 2026
System Performance Check (if applicable)?	☒ Yes ☐ No ☐ N/A	E001040	Oct 2026
System Suitability RSD < 2% (PDA)?	☐ Yes ☐ No ☒ N/A	Not Applicable	Not Applicable
System Suitability RSD < 10% (QDA, CAD)?	☐ Yes ☐ No ☒ N/A	Not Applicable	Not Applicable
Do the environmental monitoring results conform to required standards?	☒ Yes ☐ No ☐ N/A	See Phase I Summary	See Phase I Summary
Do the controls (i.e., positive, negative, etc.) conform to the required standards?	☒ Yes ☐ No ☐ N/A	See Phase I Summary	See Phase I Summary
Is equipment/instrument functional and calibrated/qualified/certified/PM?	☒ Yes ☐ No ☐ N/A	Incubator E001034 (Sensor E001501) Incubator E001031 (Sensor E001505)	Aug 2026 Feb 2027 Aug 2026 Feb 2027

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form	Effective 10-JUL-2026
Location Houston (Corporate)		ETX ID 3.100.019.F01	
Printed by qchen@eagleanalytical.com from https://app.zenqms.com on 08-Sep-2026 at 8:45:15 PM UTC			Page 3 of 6

OOS Number: OOS- 261814

Are chromatogram/spectra/raw data correct?		☐ Yes ☐ No ☒ N/A	Not Applicable	Not Applicable
Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)				
☒ N/A ☐ Re-injection of sample vial ☐ Re-injection of original standard vial ☐ Re-vialing of original working standard solution		☐ Re-vialing of original working sample solution ☐ Re-dilution of a working sample solution from the original stock ☐ Re-dilution of a working standard solution from the original stock standard ☐ Other: <u>N/A QYC 14Sep26</u>		
Section D – Phase I Summary				
Phase I Summary: All analysts involved in the prepping, processing, changeover, and reading of the samples – Elysse Niupin, Sonal Uprety, Gerald Anyangwe, and Varsha Subramanian – were interviewed and their answers are recorded throughout this document. The sample was stored upon arrival according to the Client ' s instructions. Analysts Elysse Niupin and Sonal Uprety confirmed the integrity of the samples throughout both the preparation and processing stages. No leaks or turbidity were observed at any point, verifying the integrity of the sample. All reagents and supplies mentioned in the material section above were stored according to the suppliers ' recommendations, and their integrity was visually verified before utilization. Moreover, each reagent and supply had valid expiration dates. During the preparation phase, Elysse Niupin disinfected the samples using acidified bleach and placed them into a pre-disinfected storage bin. On 07Aug26, prior to sample processing, Sonal Uprety performed a second disinfection with acidified bleach, allowing a minimum contact time of 10 minutes before transferring the samples into the cleanroom suites. A final disinfection step was completed immediately before the samples were introduced into the ISO 5 Biological Safety Cabinet (BSC), E001313, located within the middle ISO 7 buffer room, (Suite 115A). All activities were performed in accordance with MICRO-SOP-12, Rapid Scan RDI® Test using FIFU Method. The cleanroom used for testing (E001737) consists of three interconnected sections: the innermost ISO 7 cleanroom (115B), which opens into the middle ISO 7 buffer room (115A), and then into the outermost ISO 8 anteroom (115). A positive air pressure system is maintained throughout the suite to ensure controlled, unidirectional airflow from 115B through 115A and into 115. The cleanroom used for changeover (L-Suite) consists of four interconnected rooms: the innermost ISO 7 cleanroom E001979 (145), which opens into the adjacent ISO 7 buffer cleanroom E001978 (144), followed by ISO 8 anteroom E001977 (143) and the outermost ISO 8 room E001976 (142). A positive air pressure system is maintained throughout the suite to ensure controlled, unidirectional airflow from 145 through 144 and 143 into 142. The ISO 5 BSC E001313, located in the middle ISO 7 buffer room, (Suite 115A), and ISO 5 BSC E001937, located in the adjacent ISO 7 buffer cleanroom, (L-Suite), were thoroughly cleaned and disinfected prior to their respective procedures in accordance with MICRO-SOP-9, Cleaning and Disinfecting Procedure for Microbiology. Furthermore, the BSCs used throughout testing, E001313 for sample processing and E001937 for the changeover step, were certified and approved by both the Engineering and Quality Assurance teams. Sample processing was conducted within the ISO 5 BSC in the middle ISO 7 buffer room (Suite 115A, BSC E001313) by Sonal Uprety and the changeover step was conducted within the ISO 5 BSC in the adjacent ISO 7 buffer cleanroom (L-Suite, BSC E001937) by Gerald Anyangwe on 07Aug26. The analyst, Varsha Subramanian, confirmed that the equipment was set up as per ENG-SOP-4 (Scan RDI® System – Operations (Standard C3 Quality Check and Microscope Setup) and Maintenance), and the negative control and the positive control for the analyst, Varsha Subramanian, yielded expected results.				

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form	Effective 10-JUL-2026
Location Houston (Corporate)		ETX ID 3.100.019.F01	
Printed by qchen@eagleanalytical.com from https://app.zenqms.com on 08-Sep-2026 at 8:45:15 PM UTC			Page 4 of 6

OOS Number: OOS- 261814

Phase I Summary (continued):

On 07Aug26, a rapid sterility test was conducted on the sample using the ScanRDI method. The sample was initially prepared by analyst Elysse Nioupin, processed by Sonal Uprety, and subsequently read by Varsha Subramanian. The test revealed 4 rod-shaped viable microorganisms, see Table 1.

During the OOS investigation and subsequent review of the testing records, a result-transposition event was identified involving ETX-260805-0189 and ETX-260804-0101. Processing analyst Sonal Uprety completed ScanRDI sterility testing for sample ETX-260804-0101, associated with DCA Pharmacy (E12860), and sample ETX-260805-0189, associated with GoGoMeds Select (E10747), in accordance with MICRO-SOP-12, ScanRDI Sterility Testing Process. During sample reading and result verification using the ScanRDI instrument, second shift reading analyst Varsha Subramanian determined that ETX-260804-0101 met the established acceptance criteria and generated a passing result, whereas ETX-260805-0189 generated a failing result. During subsequent result entry, analyst Varsha Subramanian inadvertently transposed the results between the two samples. As a result, the passing result generated for ETX-260804-0101 was incorrectly assigned to ETX-260805-0189, while the failing result generated for ETX-260805-0189 was incorrectly assigned to ETX-260804-0101. During the subsequent data review, reviewer Olugbenga Ajayi did not identify the result transposition and approved the incorrectly assigned failing result for ETX-260804-0101. Consequently, ETX-260804-0101, which had actually met the acceptance criteria, was placed on hold pending an investigation.

Review of the original ScanRDI testing and instrument-generated data confirmed that the testing process itself was performed as intended and that the instrument results were correctly generated for each sample. The discrepancy occurred after testing, during manual result transcription and subsequent review, and did not reflect an analytical failure or an actual failing result for ETX-260804-0101. The event was therefore identified as an unintentional result-transposition error during data entry that was not detected during the initial data review. The original instrument-generated result for ETX-260804-0101 was confirmed as passing, while ETX-260805-0189 was confirmed as the sample associated with the failing ScanRDI result. Following confirmation of the correct result attribution, the investigation proceeded to evaluate potential laboratory sources of the microbial recovery for ETX-260805-0189.

Table 2 (see attached tables) presents the environmental monitoring results for ETX-260805-0189. The environmental monitoring (EM) plates were incubated for no less than 48 hours at 30 – 35°C and for no less than an additional five days at 20 – 25°C, as per SOP 2.600.002, Environmental Monitoring of the Clean-room Facility.

Upon review of the environmental monitoring data associated with the sterility test, no microbial growth was recovered from any of the four ISO 5 work surface monitoring locations within BSC E001313 (Suite 115A) or BSC E001937 (L-Suite Room 144) on the date of testing. In addition, no microbial growth was observed on the changeover personnel monitoring (analyst Gerald Anyangwe) or settling plates within BSC E001937. Low level microbial recoveries were identified from processing personnel and settling-plate monitoring within BSC E001313, as well as from routine weekly monitoring of the surrounding cleanroom areas.

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form	Effective 10-JUL-2026
Location Houston (Corporate)		ETX ID 3.100.019.F01	
Printed by qchen@eagleanalytical.com from https://app.zenqms.com on 08-Sep-2026 at 8:45:15 PM UTC			Page 5 of 6

OOS Number: OOS- 261814

Phase I Summary (continued):

One CFU was recovered from processing analyst Sonal Uprety's right-hand touch plate and submitted for microbial identification under sample ID ETX-260817-0447. The isolate was identified as *Micrococcus luteus*. This recovery was not microbiologically consistent with the organism observed in the test sample: *Micrococcus luteus* is coccid in morphology, whereas the microorganism recovered from the test sample exhibited rod-shaped morphology. Accordingly, the personnel monitoring result does not support direct transfer of the recovered right-glove organism to the test sample. In contrast, personnel monitoring for changeover analyst Gerald Anyangwe yielded no microbial growth.

Two CFUs were also recovered from settling plate Settling 1 within BSC E001313 and submitted for microbial identification under sample ID ETX-260817-0507. The isolates were identified as *Sporisorium graminicola* and *Ustilago maydis*. These microorganisms are fungal species, which are taxonomically and morphologically distinct from the bacterial rod-shaped microorganisms recovered from the test sample. Additionally, the settling plate was documented as desiccated at the 5-day read. Therefore, no microbiological match exists between the settling-plate isolates and the test-sample contaminant. Settling plates within changeover BSC E001937 yielded no growth. This finding was evaluated in conjunction with the remaining contemporaneous environmental monitoring data, including the complete absence of microbial recovery from all ISO 5 work surfaces within both BSC E001313 and BSC E001937.

Routine weekly facility monitoring during the week of testing recovered 1 CFU of Gram-positive short rods from active air monitoring in ISO 8 Cleanroom 115 (ETX-260817-0370) and 2 CFUs identified as *Bacillus megaterium* from the floor of ISO 7 Suite 115A (ETX-260817-0366). In the L-Suite, routine weekly surface sampling of cleanroom Room 144 (CR1978) yielded no microbial growth, while active air monitoring recovered typical human-associated flora (*Staphylococcus*, *Micrococcus*, *Corynebacterium* spp.) strictly confined to lower-classified background areas (ISO 8 anteroom 143 and outer room 142). All of these recoveries occurred in lower-classified background areas physically separated from the critical ISO 5 testing zones. Furthermore, the positive pressure cascade (flowing outwards from ISO 7 rooms 145 and 144 toward ISO 8 rooms 143 and 142) and the transfer of samples in disinfected, closed containers provide robust barriers preventing ingress of airborne contaminants into the ISO 5 work areas. The complete absence of microbial recovery on all ISO 5 critical surfaces within both BSCs further demonstrates that environmental controls effectively prevented transfer into the critical testing zone.

Monthly cleaning and disinfection, using H₂O₂, of the cleanrooms (ISO 7) and their containing Biosafety Cabinets (BSCs, ISO 5) were performed on 26Jul26, as per MICRO-SOP-9, Cleaning and Disinfecting Procedure for Microbiology. It was documented that all H₂O₂ indicators passed.

Analyzing a 6-month sample history for GoGoMeds Select (E10747), this specific analyte "Tirzepatide/B12 25/1mg/mL Injectable" has had no prior failures using the Scan RDI method during this period.

To evaluate the potential for sample-to-sample contamination, all samples processed on the same day were reviewed. All other samples processed by the same analyst and by other analysts on that day yielded negative results, indicating that cross-contamination is unlikely.

Based on the cumulative evidence, it is highly unlikely that the failing results were due to reagents, supplies, the cleanroom environment, the process, or analyst involvement. Consequently, the possibility of laboratory error contributing to this failure is minimal. Therefore, the original test result is deemed valid.



CORP-FORM-21
v11.1

Category: Form Corporate
Name: Laboratory OOS Investigation Form

Effective
10-JUL-2026

Location
Houston (Corporate)

ETX ID
3.100.019.F01

Printed by qchen@eagleanalytical.com from https://app.zenqms.com on 08-Sep-2026 at 8:45:15 PM UTC

Page 6 of 6

OOS Number: OOS- 261814

Has root cause been identified as a possible laboratory error?

Note: Root cause must be conclusive, verifiable, and well-documented.

☐ Yes

☐ If retesting is **required**, complete Phase II of the OOS (initiate Form 3.100.019.F02).

☒ No, the OOS result is valid.

Reviewer comment(s):

Prepared by (Print):

Qiyue Chen

Signature/Date:

Qiyue Chen

Digitally signed by Qiyue Chen
DN: OU=Eagle Analytical Services, O=Strerie Lab, CN=Qiyue Chen, E=qchen@eagleanalytical.com
Location: Houston, TX
Date: 2026.09.14 15:46:15-05'00'
Foxit PDF Editor Version: 13.2.6

Lab Manager/Designee (Print):

Signature/Date:

Section E – Quality Disposition

Can investigation be closed?

☐ Yes

☐ Original result is valid.

☐ No, initiate Form 3.100.019.F02.

Approved by QA Representative (Print):

Signature/Date:

Table 1: Information for ETX-260805-0189 under investigation

Processing Analyst	Reading Analyst	Sample ID	Events	Confirmed Microbial Events	Morphology Description
Sonal Uprety	Varsha Subramanian	ETX-260805-0189	187	4	Rod-shaped Morphology

Table 2: Environmental Monitoring from Testing Performed on 07Aug26

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMM YY)	Analyst (Initials)	Day /Week(s)	Observation*	Environmental Monitoring Plate ETX ID	Microbial ID	Notes
Personnel EM Bracketing								
Personal (Left Touch and Right Touch)	Daily	07Aug26	SU	Date of Testing Scan	1 CFU on right touch	ETX-260817-0447	Micrococcus luteus	Plate was desiccated on 5 day read
Personal (Left Touch and Right Touch)	Daily	07Aug26	GA	Date of Testing ScanC/O	No growth	N/A	N/A	None
Biological Safety Cabinet EM Bracketing Biological Safety Cabinet (BSC) E001313 and E001937								
Surface Sampling of ISO 5 E001313 (4 locations)	Daily	07Aug26	SU	Date of Testing Scan	No growth	N/A	N/A	None
Surface Sampling of ISO 5 E001937 (4 locations)	Daily	07Aug26	GA	Date of Testing ScanC/O	No growth	N/A	N/A	None
Settling Sampling of ISO 5 E001313 (2 locations)	Daily	07Aug26	SU	Date of Testing Scan	2 CFUs on Sett1	ETX-260817-0507	Sporisorium graminicola Ustilago maydis	Plate was desiccated on 5 day read
Settling Sampling of ISO 5 E001937 (2 locations)	Daily	07Aug26	GA	Date of Testing ScanC/O	No growth	N/A	N/A	None
Weekly Active Air Sampling Bracketing - Cleanroom 115 - CR1737								
Active Air Sampling of Cleanrooms	Weekly	06Aug26	SMO	Week of testing Scan	1 CFU on ISO 8 115	ETX-260817-0370	Gram (+) short rods	None
Weekly Active Air Sampling Bracketing - Cleanroom 144 - CR1978 (L-Suite)								
Active Air Sampling of Cleanrooms	Weekly	07Aug26	SMO	Week of testing ScanC/O	6 CFUs on 143 SecI air ISO 8 32 CFUs on 143 SecII air ISO 8, and 12 CFUs on 142 air ISO 8	ETX-260817-0416 ETX-260817-0422 ETX-260817-0429	Staphylococcus epidermidis Staphylococcus capitis Micrococcus luteus Kocuria palustris Corynebacterium segmentosum Staphylococcus hominis Staphylococcus aureus Corynebacterium aurimucosum Kytococcus sedentarius	None
Surface Sampling of Anteroom and Cleanroom Bracketing - Cleanroom 115 - CR1737								
Surface Sampling of Cleanrooms	Weekly	06Aug26	SMO	Week of testing Scan	2 CFU on floor in ISO 7 115A	ETX-260817-0366	Bacillus megaterium	None
Surface Sampling of Anteroom and Cleanroom Bracketing - Cleanroom 144 - CR1978 (L-Suite)								
Surface Sampling of Cleanrooms	Weekly	07Aug26	SMO	Week of testing ScanC/O	No growth	N/A	N/A	None