OOS Number: OOS- 262329

Phase II

Section A – Sample Detail					
Sample Name:	Sermorelin 0.9mg/ml	**Re-Test Date:**	21-Oct-2026	**Original Result:**	Fail
Name of Analyst who Performed Re-Test:	Prepping: Elysse Nioupin (EN) Processing: Ayomide Odugbesi (AOD) Reading: Andrew Carrillo (ANC)	**Sample ID:**	Original: ETX-260624-0251 (BUD-T90) Retest: ETX-261021-0445	**Re-Test Result:**	Pass

Section B – Investigation and Root Cause				
Investigation	Is the test conducted in accordance with the same method /process?	☑ Yes ☐ No	SOP#: MICRO-SOP-5	If the answer is NO to any of the investigation item(s), mark the item(s) with sequential number starting with one (1) and comment here: Not Applicable
	Is reagents (reference standards, solvent, etc.) stored in proper condition and not expired?	☑ Yes ☐ No	Lot #: TSB: Please see Consumables section under the submission on EagleTrax FTM: Please see Consumables section under the submission on EagleTrax	
			Exp. Date: TSB: Please see Consumables section under the submission on EagleTrax FTM: Please see Consumables section under the submission on EagleTrax	
	Equipment/Instruments Used:	Are they functional and calibrated/PM?	Calibration / PM due date	
	ISO 5 BSC E001314	☑ Yes ☐ No	Jun 2027	
	CR 115 (E001737)	☑ Yes ☐ No	Dec 2026	
	Incubator E001356 (Sensor E001450)	☑ Yes ☐ No	Jan 2027, Feb 2027	
	Incubator E001357 (Sensor E001449)	☑ Yes ☐ No	Jan 2027, Feb 2027	
	Incubator E001034, Sensor E001501 Incubator E001031, Sensor E001505	☑ Yes ☐ No	Aug 2027, Feb 2027 Aug 2027, Feb 2027	
	Is the clean room facility certified?	☑ Yes ☐ No ☐ N/A	Certified due date: 31-Dec-2026	
	Do the controls (i.e. positive, negative, C3, etc.,) conform to the required standards?	☑ Yes ☐ No ☐ N/A	See Phase II Summary	
	Do the environmental monitoring results conform to required standards?	☑ Yes ☐ No ☐ N/A	SOP#: See Phase II Summary	
	System Performance Check (if applicable)	☐ Yes ☐ No ☑ N/A		
	System Suitability RSD < 2% (PDA)	☐ Yes ☐ No ☑ N/A		
	System Suitability RSD <10 % (QDA,CAD)	☐ Yes ☐ No ☑ N/A		

OOS Number: OOS- 262329

	Is the analyst trained to perform the test?	☑ Yes ☐ No
	Are the Test Result Records Attached & Calculations Verified and Correct?	☑ Yes ☐ No
	Does the processing method/ method set conform to the required specification?	☑ Yes ☐ No
	Re-Testing from the same vial?	☐ Yes ☑ No ☐ N/A
	Is formula worksheet provided and verified?	☐ Yes ☑ No

Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)

- ☐ N/A
- ☐ Re-injection of sample vial
- ☐ Re-injection of original standard vial
- ☐ Re-vialing of original working standard solution
- ☐ Re-vialing of original working sample solution
- ☐ Re-dilution of a working sample solution from the original stock
- ☐ Re-dilution of a working standard solution from the original stock standard
- ☑ Other: Retest of additional sample vials from same

Section D – Phase II Summary

All analysts involved in the initial testing and Phase II retesting - initial prepping analyst Elysse Nioupin, initial processing analyst Guanchen Li, subculture analyst Ayomide Odugbesi, initial reading analyst Andrew Carrillo, retest processing analyst Ayomide Odugbesi, and retest reading analyst Andrew Carrillo - were interviewed comprehensively. Their responses are documented throughout this report. This investigation was performed in accordance with MICRO-SOP-53, Sterility Test Out-of-Specification Investigation Procedure.

INITIAL TEST UNDER SUBMISSION ETX-260624-0251 (BUD-T90):
Upon arrival on 24Jun26, the sample was stored refrigerated in accordance with the client's instructions as part of a beyond-use date study (BUD-T90). Prepping analyst Elysse Nioupin and processing analyst Guanchen Li verified the physical integrity and packaging of the sample throughout the preparation and processing stages. No leaks, cracks, or visible turbidity were observed, verifying container closure integrity prior to testing.

All reagents and supplies mentioned in the material section above were stored according to supplier recommendations, and their integrity was visually verified before utilization. Moreover, all reagents, culture media, and consumables had valid expiration dates. The functionality of all equipment was confirmed by reviewing data generated by our comprehensive in-house continuous monitoring system.

The cleanroom suite (CR 115) used for processing procedures comprises three interconnected sections: the innermost ISO 7 cleanroom (115B), which connects to the middle ISO 7 buffer room (115A), and then to the outermost ISO 8 anteroom (115). Outward-cascading positive air pressure differentials are continuously maintained across the suite to ensure controlled, unidirectional airflow from 115B through 115A and into 115.

The ISO 5 Biological Safety Cabinet (BSC) E001314, located in innermost ISO 7 room 115B, was used for sample processing steps. It was thoroughly cleaned and disinfected prior to each procedure in accordance with MICRO-SOP-2 (Environmental Monitoring of the Clean-room Facility) and MICRO-SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). Additionally, BSC E001314 was certified and approved by Engineering and Quality Assurance.

On 22Sep26, sample prep was performed by Elysse Nioupin. On 23Sep26, sample vials for ETX-260624-0251 (BUD-T90) were retrieved from controlled refrigerated storage and brought into the sterile microbiology suite. Sample container surfaces were sprayed with acidified bleach disinfectant, placed into pre-disinfected transfer bins, and allowed a verified 10-minute contact time. Secondary disinfection with acidified bleach was performed in the ISO 8 anteroom (115) with an additional 10-minute contact time. Inside innermost ISO 7 cleanroom 115B, processing analyst Guanchen Li performed a final disinfection step before transferring the containers into the ISO 5 BSC E001314.

Inside BSC E001314, containers were aseptically accessed with minimal exposure to the ISO 5 environment. Testing was executed by direct inoculation in strict accordance with approved method suitability ETX-260401-0599 and MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test). Specifically, 15 mL of sterile Tween 80 and 5 mL of sample were directly inoculated into 200 mL media bottles of Tryptic Soy Broth and Fluid Thioglycollate Medium. Matching direct inoculation negative control bottles were prepared concurrently and manipulated identically. The inoculated media bottles were transferred into calibrated incubators E001356 (20-25 °C) and E001357 (30-35 °C) to commence incubation.

OOS Number: OOS- 262329

Phase II Summary (continued):

On 07Oct26 (Day 14 read), initial test results were recorded as Inconclusive due to formulation-induced turbidity inherent to the concentrated Sermorelin sample matrix. In accordance with USP <71> and laboratory procedure for turbid samples, aliquots were aseptically subcultured into fresh media bottles on 07Oct26 by analyst Ayomide Odugbesi and returned to incubation.

On 12Oct26 (Day 18 of original bottles and Day 4 of subculture aliquots), microbial growth was observed and confirmed in both original TSB bottle and subcultured TSB bottle (2 x 200mL TSB, Original and Subculture Bottles) by reading analyst Andrew Carrillo and verified by laboratory supervisor. The FTM media bottles (original and subculture) remained clear and negative (No Growth) throughout incubation. Positive TSB bottles were submitted for Differential Staining and Microbial Identification under submission ETX-261012-0367. Differential staining indicated Gram-positive rods. Definitive identification confirmed the isolate as Bacillus megaterium, as detailed in Table 1.

All culture media and consumables utilized were within their valid manufacturer expiration dates. Negative control media bottles for direct inoculation were manipulated and incubated alongside the test samples under identical conditions; both TSB and FTM negative controls demonstrated complete absence of microbial growth (No Growth), verifying media sterility and aseptic technique.

ENVIRONMENTAL MONITORING (EM) RESULTS:

Attached Table 2 and Table 3 detail the environmental monitoring data associated with sample processing on 23Sep26 and subculture on 07Oct26 . Environmental monitoring plates were incubated in accordance with MICRO-SOP-2, Environmental Monitoring of the Clean-room Facility.

ISO 5 BSC and Personnel EM results for Initial Processing - 23Sep26:
Review of contemporaneous personnel monitoring (left- and right-hand touch plates for analyst Guanchen Li) and ISO 5 BSC E001314 monitoring (surface contact plates and settling plates) demonstrated No Growth across all sampling locations on the date of testing (23Sep26), the date before testing (22Sep26), and the date after testing (24Sep26).

ISO 5 BSC and Personnel EM results for Subculture - 07Oct 26:
Similarly, no growth across all sampling locations on the date of the subculture (07Oct26).These data confirm that processing personnel and the ISO 5 BSC were maintained in an optimal state of microbiological control and were not a source of contamination during both the initial processing and subculturing activities.

Cleanroom EM Results for Initial Processing - 23Sep26:
Routine weekly surface sampling of Cleanroom Suite 115 performed on 23Sep26 demonstrated No Growth. Weekly active-air sampling of the outermost ISO 8 Room 115 recovered 6 CFUs (ETX-261001-0625). Microbial identification confirmed these isolates as Micrococcus luteus, Kocuria indica, Kocuria rhizophila, and one pending fungal isolate (Pending FunITS, exhibiting hyphae morphology).

Cleanroom EM Results for Subculture- 07Oct26:
Routine weekly surface sampling of Cleanroom Suite 115 performed on 06Oct26 demonstrated No Growth. Weekly active-air sampling of the buffer ISO 7 Room 115A recovered 1 CFUs (ETX-261013-0297). Microbial identification confirmed the isolate to be Corynebacterium segmentosum.

Crucially, all environmental isolates recovered during the investigation were limited to locations external to the critical processing environment. Room 115 functions as an ISO 8 anteroom, while Room 115A serves as an ISO 7 buffer room; both are physically separated from the innermost ISO 7 processing room (115B), which contains the ISO 5 BSC, by cascaded airlocks and established positive-pressure airflow controls. Environmental monitoring data demonstrated no microbial recovery from the critical ISO 7 processing room (115B), personnel glove samples, or ISO 5 BSC surface monitoring sites. The absence of microbial recovery throughout all critical processing areas provides objective evidence that microorganisms detected in peripheral support spaces remained confined to those locations and did not penetrate the aseptic processing environment. The complete absence of microbial recovery from the ISO 7 processing room 115B , personnel gloves for both analysts, and ISO 5 BSC surfaces confirms that room air contaminants did not enter the ISO 5 critical work area during either the initial processing or subculture.

Monthly cleaning and disinfection of the cleanrooms (ISO 7) and their containing biosafety cabinets (ISO 5) were performed on 13Sep26 for Suite 115, as per MICRO-SOP-9, Cleaning and Disinfecting Procedure for Microbiology. It was documented that all chemical indicators passed, which confirmed the efficient monthly cleaning of all cleanrooms in Suite 115.

Analyzing a 6-month sample history for GoGoMeds Select (E10747), this specific analyte "Sermorelin 0.9mg/ml" has had no prior Out-of-Specification (OOS) occurrences under USP <71> sterility testing.

To assess the potential for sample-to-sample contamination contributing to the positive results, a comprehensive review was conducted of all samples processed on the same day. All other samples processed by the analyst that day tested negative. These findings suggest that cross-contamination between samples is highly unlikely. Consequently, the Phase I laboratory investigation did not identify any assignable laboratory cause contributing to the initial failure, and the original result is considered valid.

OOS Number: OOS- 262329

Phase II Summary (continued):

RETEST UNDER SUBMISSION ETX-261021-0445 (BUD-T90 STABILITY STUDY):
In accordance with Phase II investigation procedures under CORP-FORM-22 and follow-up communications regarding the BUD-T90 stability study for Lot 17009, the client requested an associated Phase II retest of additional vials from the same lot. Retest testing was initiated under submission ETX-261021-0445 to evaluate the sterility status of the remaining stability sample vials. The analysts involved in prepping, processing, and reading the retest sample—Elysse Nioupin, Ayomide Odugbesi, and Andrew Carrillo—confirmed no deviations from standard testing procedures.

Like the original testing under ETX-260624-0251 (BUD-T90), the retest sample was processed following comparable disinfection procedures, certified cleanroom environmental controls, and strict aseptic techniques. All reagents and supplies used for ETX-261021-0445 were stored according to manufacturers' recommendations, with visual integrity and valid expiration dates verified prior to use. For the retest, culture media bottles of Tryptic Soy Broth (TSB) and Fluid Thioglycollate Medium (FTM) were within their validated expiry periods. During testing by direct inoculation in ISO 5 BSC E001314 within Cleanroom Suite 115, negative control media bottles were inoculated, handled, and incubated under identical conditions. Complete absence of microbial growth was observed in all negative controls, confirming procedural and media integrity.

Additionally, the retest sample was cleaned, transferred into Cleanroom Suite 115, processed, and inoculated as per MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test) on 21 Oct 2026. Inoculated media bottles were transferred into designated incubators E001356 (20-25 °C) and E001357 (30-35 °C) under identical incubation parameters as initial testing. Submission ETX-261021-0445 passed the sterility test after 14 days of incubation with No Growth observed across all media.

No laboratory-related errors were identified during the investigation of the passing results reported under ETX-261021-0445 or the initial failing result reported under ETX-260624-0251 (BUD-T90). Therefore, both the initial failing result associated with ETX-260624-0251 (BUD-T90) and the passing retest result associated with ETX-261021-0445 are considered valid. The discrepancy between the initial and retest findings reflects a low-level, non-uniform distribution of microbial contamination (Bacillus megaterium) within stability Lot 17009. Final beyond-use dating (BUD) determination, stability protocol evaluation, and lot disposition remain at the discretion of the client.

OOS Number: OOS- 262329

Has root cause been identified? ☑ Yes ☐ No	The most probable cause is: The discrepancy between the original and retest results may be attributed to non-uniform microbial distribution, particularly when microorganisms are present at low concentrations within the batch. Client Care notified: Yes☑ No☐

Section E – Corrective and Preventive Action

Corrective Action(s): N/A QYC 04Nov26	**OOS cause (select all)** ☐ Equipment Error ☐ Procedure ☐ Analyst ☐ Training ☐ System ☑ External Phenomena ☐ Other: N/A QYC 04Nov26
Preventive Action(s) N/A QYC 04Nov26	CAPA required: ☐ Yes, CAPA # N/A QYC ☑ No

FOLLOW-UP REQUIRED: ☐ Yes ☑ No	FOLLLOW-UP DATE:

Section F – Acknowledgement and Closure

Prepared by:	Print Name: Qiyue Chen Digitally signed by Qiyue Chen DN: OU=Eagle Analytical Services, O=Strerie Lab, CN=Qiyue Chen, E=qchen@eagleanalytical.com Location: Houston, TX Date: 2026.11.05 09:23:41-06'00' Foxit PDF Editor Version: 13.2.7	Date: 04-Nov-2026
Reviewed by:	Print Name:	Date:
Approved by (QA):	Print Name:	Date:

Table 1: Information for ETX-260624-0251 (BUD-T90) and ETX-261021-0445 under investigation

Processing Analyst	Reading Analyst	Sample ID	Related Microbial ID	Media with microbial growth	Sterility Result	Microbial ID
Guanchen Li	Andrew Carrillo	ETX-260624-0251 (BUD-T90)	ETX-261012-0367	2 x 200mL TSB (Original and Subculture Bottles)	Fail	*Bacillus megaterium* (Gram (+) rods)
Ayomide Odugbesi	Andrew Carrillo	ETX-261021-0445	Not Applicable	No Growth	Pass	None

Table 2: Environmental Monitoring from Testing Performed on 23Sep26

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMMYY)	Analyst	Day /Week(s)	Observation	EM Plate ETX Number	Microbial ID	Notes
Personnel EM								
Personnel (Left Touch and Right Touch)	Daily	22Sep26	GL	Date Before Testing	No Growth	Not Applicable	Not Applicable	None
Personnel (Left Touch and Right Touch)	Daily	23Sep26	GL	Date of Testing	No Growth	Not Applicable	Not Applicable	None
Personnel (Left Touch and Right Touch)	Daily	24Sep26	GL	Date After Testing	No Growth	Not Applicable	Not Applicable	None
Biological Safety Cabinet EM for E001314								
Surface Sampling of ISO 5 (4 locations)	Daily	22Sep26	AOD	Date Before Testing	No Growth	Not Applicable	Not Applicable	None
Surface Sampling of ISO 5 (4 locations)	Daily	23Sep26	GL	Date of Testing	No Growth	Not Applicable	Not Applicable	None
Surface Sampling of ISO 5 (4 locations)	Daily	24Sep26	AOD	Date After Testing	No Growth	Not Applicable	Not Applicable	None
Settling Sampling of ISO 5 (2 locations)	Daily	22Sep26	AOD	Date Before Testing	No Growth	Not Applicable	Not Applicable	None
Settling Sampling of ISO 5 (2 locations)	Daily	23Sep26	GL	Date of Testing	No Growth	Not Applicable	Not Applicable	None
Settling Sampling of ISO 5 (2 locations)	Daily	24Sep26	AOD	Date After Testing	No Growth	Not Applicable	Not Applicable	None
Weekly Active Air Sampling of Cleanroom Suite 115 (E001737) with Processing BSC								
Active Air Sampling of Cleanrooms	Weekly	23Sep26	SMO	Week of Testing	6 CFUs (ISO 8 115)	ETX-261001-0625	*Micrococcus luteus* *Kocuria indica* *Kocuria rhizophila* Pending FunITS (Hyphae)	None
Weekly Surface Sampling of Cleanroom Suite 115 (E001737) with Processing BSC								
Surface Sampling of Cleanrooms	Weekly	23Sep26	SMO	Week of Testing	No Growth	Not Applicable	Not Applicable	None

Table 3: Environmental Monitoring from Day 18+ Subculture Performed on 07 Oct 26

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMMYY)	Analyst	Day /Week(s)	Observation	EM Plate ETX Number	Microbial ID	Notes
Personnel EM								
Personnel (Left Touch and Right Touch)	Daily	07Oct26	AOD	Date of Testing	No Growth	Not Applicable	Not Applicable	None
Biological Safety Cabinet EM for E001314								
Surface Sampling of ISO 5 (4 locations)	Daily	07Oct26	AOD	Date of Testing	No Growth	Not Applicable	Not Applicable	None
Settling Sampling of ISO 5 (2 locations)	Daily	07Oct26	AOD	Date of Testing	No Growth	Not Applicable	Not Applicable	None
Weekly Active Air Sampling of Cleanroom Suite 115 (E001737) with Processing BSC								
Active Air Sampling of Cleanrooms	Weekly	06Oct26	SMO	Week of Testing	1 CFU (ISO 7 115A)	ETX-261013-0297	*Corynebacterium segmentosum*	None
Weekly Surface Sampling of Cleanroom Suite 115 (E001737) with Processing BSC								
Surface Sampling of Cleanrooms	Weekly	06Oct26	SMO	Week of Testing	No Growth	Not Applicable	Not Applicable	None