

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form	Effective 10-JUL-2026
Location Houston (Corporate)		ETX ID 3.100.019.F01	
Printed by rseymour@eagleanalytical.com from https://app.zenqms.com on 04-Sep-2026 at 10:16:36 PM UTC			Page 1 of 6

OOS Number: OOS- 262098

Phase I

Section A – Test Details					
Initiator:	Alex Saravia (Written by: C)	Test Date:	04-Sep-2026	Date Initiated:	10-Sep-2026
Date of Incident:	10-Sep-2026	Test Name:	USP <71> / EP 2.6.1 Sterility (Every Day	Sample ID:	ETX-260902-0505, ETX-260914-0470
Name of Analyst who Performed the Test:	Prepping Analyst: Alex Saravia (ES), Andrew Carrillo (AC)	Sample / Active Name	GLP3R/Cagrilinitide	Lot #:	2608-216
	Processing Analyst: Alex Saravia (ES), Abayomi Odugbesi (AO)	Dosage Form	Liquid		
Description of Incident:	On 10 Sep 2026, sample ETX-260902-0505 was confirmed positive and on 21 Sep 2026, sample ETX-260914-0470 was confirmed positive for viable microorganisms (1 x 100mL TSB each) after USP <71> sterility testing. Both samples belong to lot 2608-216 under investigation in OOS-262098. ☒ Client Care notified of OOS ☒ Sterility and Endotoxin test related OOS; Client must be notified within 24 hours of OOS				
	SOP / Test Method # MICRO-SOP-5	Effective Date: 24Jul2026	SOP / Test Method Rev: 19	Limits/Specification: Pass/Fail	
Manager notified	Manager/designee name: Kathan Parikh	Date: 10-Sep-2026	Quality Assurance Department notified:	Yes ☒ No ☐	
Section B – Investigation and Root Cause Analysis					
Personnel Discrepancy			Comments		
Analyst interviewed?	☒ Yes ☐ No ☐ N/A		Yes. Analysts Alex Saravia, Elyse Niupin, Andrew Carrillo, and Abayomi Odugbesi were interviewed comprehensively. Handling error was refuted by identical repeat recovery.		
Correct samples analyzed?	☒ Yes ☐ No ☐ N/A		Yes, sample IDs: ETX-260902-0505 and ETX-260914-0470		
Correct SOP / Test Method used/followed?	☒ Yes ☐ No ☐ N/A		Yes, as per MICRO-SOP-5		
Correct sample collection/technique?	☒ Yes ☐ No ☐ N/A		Yes, as per MICRO-SOP-5		
Are the Test Result Records Attached & Calculations Verified and Correct?	☒ Yes ☐ No ☐ N/A		Yes, information is available on EagleTrax under ETX-260902-0505 and ETX-260914-0470		
Is the analyst qualified to perform the test?	☒ Yes ☐ No ☐ N/A		Yes, the analysts are trained and qualified by quality to perform the test		
Is formula worksheet provided and verified?	☐ Yes ☐ No ☒ N/A		Not Applicable		
Does the processing method/method set conform to the required specification?	☐ Yes ☐ No ☒ N/A		Not Applicable		
Was the sample stored appropriately?	☒ Yes ☐ No ☐ N/A		Yes, both samples were stored as per client's instructions. Information is available in EagleTrax Sample Location History under ETX-260902-0505 and ETX-260914-0470		
Material Discrepancy			Lot Number	Expiry Date	
Is the integrity of the sample(s) questionable?	☐ Yes ☒ No ☐ N/A				
Was the sample transported appropriately?	☒ Yes ☐ No ☐ N/A				
Are the other test results from this run under investigation?	☐ Yes ☒ No ☐ N/A				

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form	Effective 10-JUL-2026
Location Houston (Corporate)		ETX ID 3.100.019.F01	
Printed by rseymour@eagleanalytical.com from https://app.zenqms.com on 04-Sep-2026 at 10:16:36 PM UTC			Page 2 of 6

OOS Number: OOS- 262098

Appropriate/correct glassware used?	☐ Yes ☐ No ☒ N/A		
Are reagents stored in proper condition and not expired?	☒ Yes ☐ No ☐ N/A	Process Consumables: ETX-260902-0505: FTM Lot 2567320, TSB Lot 2548010, Fluid D Lot 685561 ETX-260914-0470: FTM Lot 2567320, TSB Lot 2567280, Fluid D Lot 687774, Bacteriostatic Water NM7681 Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly cleaning logs	Process Consumables: ETX-260902-0505: FTM Lot 2567320, TSB Lot 2548010, Fluid D Lot 685561 ETX-260914-0470: FTM Lot 2567320, TSB Lot 2567280, Fluid D Lot 687774, Bacteriostatic Water NM7681 Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly cleaning logs
Standard Used	Not applicable	Not applicable	Not applicable
Solvent Used	Not applicable	Not applicable	Not applicable
Is the standard the source of the root cause?	☐ Yes ☐ No ☒ N/A		
Has the analyst been instructed to keep the original test solution for possible retesting?	☐ Yes ☐ No ☒ N/A		
Equipment Discrepancy		Equipment ID	Calibration Due Date
Was the instrument set up correctly?	☒ Yes ☐ No ☐ N/A	ISO 5 BSC E001316, ISO 5 BSC E001314	Jun 2027, Jun 2027
Is the clean room facility certified?	☒ Yes ☐ No ☐ N/A	CR 114 (E001736)	Dec 2026
System Performance Check (if applicable)?	☐ Yes ☐ No ☒ N/A	Not applicable	Not applicable
System Suitability RSD < 2% (PDA)?	☐ Yes ☐ No ☒ N/A	Not applicable	Not applicable
System Suitability RSD < 10% (QDA, CAD)?	☐ Yes ☐ No ☒ N/A	Not applicable	Not applicable
Do the environmental monitoring results conform to required standards?	☒ Yes ☐ No ☐ N/A	See Phase I Summary	See Phase I Summary
Do the controls (i.e., positive, negative, etc.) conform to the required standards?	☒ Yes ☐ No ☐ N/A	See Phase I Summary	See Phase I Summary
Is equipment/instrument functional and calibrated/qualified/certified/PM?	☒ Yes ☐ No ☐ N/A	Incubator E001356 (Sensor E001450) Incubator E001357 (Sensor E001449) Incubator E001034 (Sensor E001501) Incubator E001031 (Sensor E001505)	Jan 2027 / Feb 2027 Jan 2027 / Feb 2027 Aug 2027 / Feb 2027 Aug 2027 / Feb 2027

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form	Effective 10-JUL-2026
Location Houston (Corporate)		ETX ID 3.100.019.F01	
Printed by rseymour@eagleanalytical.com from https://app.zenqms.com on 04-Sep-2026 at 10:16:36 PM UTC			Page 3 of 6

OOS Number: OOS- 262098

Are chromatogram/spectra/raw data correct?				☐ Yes ☐ No ☒ N/A	Not applicable	Not applicable
Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)						
☒ N/A		☐ Re-vialing of original working sample solution				
☐ Re-injection of sample vial		☐ Re-dilution of a working sample solution from the original stock				
☐ Re-injection of original standard vial		☐ Re-dilution of a working standard solution from the original stock standard				
☐ Re-vialing of original working standard solution		☐ Other: <u>N/A QYC 08Oct26</u>				
Section D – Phase I Summary						
Phase I Summary: All analysts involved in the prepping, processing, and reading of both samples – Alex Saravia, Elysse Nioupin, Andrew Carrillo, and Abayomi Odugbesi – were interviewed comprehensively. Their answers are recorded throughout this document. Upon arrival, both sample submissions (ETX-260902-0505 and ETX-260914-0470) were stored in accordance with the Client 's instructions. Analysts verified the integrity of the sample containers throughout both preparation and processing stages. No leaks, cracks, or turbidity were observed prior to testing, verifying container integrity. All reagents and supplies mentioned in the material section above were stored according to suppliers ' recommendations, and their integrity was visually verified before utilization. Moreover, all culture media, rinses, and supplies possessed valid expiration dates. The functionality of all equipment was confirmed by reviewing continuous monitoring data. The cleanroom suite (CR 114) comprises three interconnected sections: the innermost ISO 7 cleanroom (114B), the middle ISO 7 buffer room (114A), and the outermost ISO 8 anteroom (114). A positive air pressure cascade is maintained throughout the suite to ensure controlled, unidirectional airflow outward from 114B through 114A and into 114. Initial sample ETX-260902-0505 was received on 02 Sep 2026 and processed on 04 Sep 2026 by Alex Saravia in certified ISO 5 BSC E001316 (Cleanroom 114B) as per MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test). Prior to entry, vials were disinfected with acidified bleach allowing a 10-minute contact time at each transfer boundary. Membrane filtration was performed (3 vials filtered). Media bottles were transferred into designated incubators E001356 and E001357. On 10 Sep 2026 (Day 6 of incubation), turbidity was observed in 1 x 100mL TSB bottle by reading analyst Elysse Nioupin and confirmed by supervisor Robin Seymour. The positive bottle was submitted for Microbial Identification under ETX-260910-0290, which definitively identified the isolate as Microbacterium sp. PM5 (Gram (+) rods). Concurrent negative controls remained sterile. Secondary sample ETX-260914-0470 was prepped on 14 Sep 2026 by Andrew Carrillo and processed on 15 Sep 2026 by Abayomi Odugbesi in certified ISO 5 BSC E001314 in Cleanroom suite CR 114 as per MICRO-SOP-5 via membrane filtration (4 vials / 60 gm filtered). Standard multi-barrier disinfection and strict aseptic techniques were maintained. Media bottles were incubated in incubators E001356 and E001357. On 21 Sep 2026 (Day 6 of incubation), turbidity was observed in 1 x 100mL TSB bottle by reading analyst Andrew Carrillo and confirmed by supervisor Robin Seymour. The positive bottle was submitted for Microbial Identification under ETX-260921-0498, which definitively identified the identical isolate, Microbacterium sp. PM5 (Gram (+) short rods). Concurrent negative controls remained sterile.						

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form	Effective 10-JUL-2026
Location Houston (Corporate)		ETX ID 3.100.019.F01	
Printed by rseymour@eagleanalytical.com from https://app.zenqms.com on 04-Sep-2026 at 10:16:36 PM UTC			Page 4 of 6

OOS Number: OOS- 262098

Phase I Summary (continued):

ISO 5 BSC Environmental Monitoring Results Evaluation:
 After reviewing the Environmental Monitoring (EM) records for both testing dates (04 Sep 2026 and 15 Sep 2026), no microbial growth was detected on operator personnel fingertip touch plates, settling plates, or ISO 5 BSC surface contact plates for either session, nor on preceding or subsequent testing days.

Cleanroom Environmental Monitoring Results Evaluation:
 No microbial growth was recovered from weekly active surface sampling on 04 Sep 2026. Weekly active air sampling in ISO 8 cleanroom 114 on 04 Sep 2026 recovered 2 CFUs (ETX-260914-0487), identified as *Corynebacterium ureicelerivorans* and *Mycobacterium grossiae*. These environmental isolates differed distinctly in genus and morphology from the sample isolate (*Microbacterium* sp. PM5). All testing occurred within certified ISO 5 BSCs (E001316 and E001314) located in ISO 7 cleanrooms separated by positive pressure cascades. Test containers were transferred in disinfected, lidded bins. Therefore, the cleanroom air recovery was not related to the sample contamination.

The complete absence of contamination across all analyst glove touch plates, settling plates, and ISO 5 work surfaces across both processing sessions confirms that the ISO 5 critical zones remained in optimal control. Full compliance with MICRO-SOP-9 and MICRO-SOP-5 was verified. Monthly cleaning and disinfection of Cleanroom suite CR114 was performed on 30 Aug 2026 as per MICRO-SOP-9, with all chemical H2O2 indicators passing.

A 6-month historical review for client Solyn LLC (E75000) confirmed that analyte GLP3R/Cagrilinitide had no prior sterility failures. Batch cross-contamination reviews were conducted for all samples processed on 04 Sep 2026 (where ETX-260902-0505 was 3rd in the batch) and 15 Sep 2026. All other client samples processed during both testing sessions tested negative, ruling out cross-contamination.

Importantly, the investigation evaluated why the prior rapid ScanRDI sterility test on this lot (ETX-260807-0602) yielded a passing result. In compounded parenteral products, low-level bioburden is characteristically non-uniformly distributed across individual vials. Under low-concentration non-uniform contamination, random unit sampling naturally results in some vials containing zero viable cells—as occurred with the vials sampled for ScanRDI under ETX-260807-0602—while other vials harbor low-level viable bioburden. Furthermore, no method suitability was on file for ScanRDI with this formulation. When low-level viable organisms were introduced into the 14-day USP <71> membrane filtration enrichment process, the microorganisms were successfully enriched and recovered in TSB on Day 6 in both independent testing events (ETX-260902-0505 and ETX-260914-0470), yielding the identical strain (*Microbacterium* sp. PM5). The successful replication across different processing analysts (Alex Saravia vs. Abayomi Odugbesi) and different BSCs (E001316 vs. E001314) conclusively refutes the preliminary hypothesis of analyst handling error during reconstitution. The passing ScanRDI result and both failing USP <71> results are scientifically consistent with non-uniform microbial distribution. Consequently, inherent product contamination in Lot 2608-216 is confirmed, and Lot 2608-216 fails USP <71> sterility requirements.

OOS Number: OOS- 262098

Phase I Summary (continued):
N/A QYC 08Oct26

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form	Effective 10-JUL-2026
Location Houston (Corporate)		ETX ID 3.100.019.F01	
Printed by rseymour@eagleanalytical.com from https://app.zenqms.com on 04-Sep-2026 at 10:16:36 PM UTC			Page 6 of 6

OOS Number: OOS- 262098

Has root cause been identified as a possible laboratory error? <i>Note: Root cause must be conclusive, verifiable, and well-documented.</i> ☒ Yes ☒ If <u>retesting</u> is required , complete Phase II of the OOS (initiate Form 3.100.019.F02). ☐ No, the OOS result is valid.	
Reviewer comment(s): Inherent product contamination in Lot 2608-216, confirmed by independent dual-sample recovery of identical strain Microbacterium sp. PM5 on Day 6 in TSB under ETX-260902-0505 and ETX-260914-0470.	
Prepared by (Print): Qiyue Chen	Signature/Date:
Lab Manager/Designee (Print):	Signature/Date:
Section E – Quality Disposition	
Can investigation be closed? ☐ Yes ☐ Original result is valid. ☒ No, initiate Form 3.100.019.F02.	
Approved by QA Representative (Print):	Signature/Date:

Table 1: Information for ETX-260902-0505 and ETX-260914-0470 under investigation

Processing Analyst	Reading Analyst	Sample ID	Related Microbial ID	Media with microbial growth	Microbial ID
Alex Saravia	Elysse Nioupin	ETX-260902-0505	ETX-260910-0290	1 x 100mL TSB bottle	<i>Microbacterium sp. PM5</i> (Gram (+) rods)
Abayomi Odugbesi	Andrew Carrillo	ETX-260914-0470	ETX-260921-0498	1 x 100mL TSB bottle	<i>Microbacterium sp. PM5</i> (Gram (+) short rods)

Table 2: Environmental Monitoring from Processing Performed on 04Sep26

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMYY)	Analyst (Initials)	Day /Week(s)	Observation*	Environmental Monitoring Plate ETX ID	Microbial ID	Notes
Personnel EM Bracketing								
Personnel (Left Touch and Right Touch)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Biological Safety Cabinet EM Bracketing Biological Safety Cabinet (BSC)								
Surface Sampling of ISO 5 (4 locations)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Weekly Active Air Sampling Bracketing								
Active Air Sampling of Cleanrooms	Weekly	04Sep26	ISS	Week on Testing Date	2 CFU (ISO 8 114)	ETX-260914-0487	<i>Corynebacterium ureicelerivorans</i> <i>Mycobacterium grossiae</i>	None
Surface Sampling of Anteroom and Cleanroom Bracketing								
Surface Sampling of Cleanrooms	Weekly	04Sep26	ISS	Week on Testing Date	No growth	N/A	N/A	None