OOS Number: OOS- 261553

Phase I

Section A – Test Details					
Initiator:	Simin Mohammad (Written by: Maryam Naeem)	**Test Date:**	26-Jun-2026	**Date Initiated:**	06-Jul-2026
Date of Incident:	06-Jul-2026	**Test Name:**	Environmental Monitoring	**Sample ID:**	ETX-260706-0305
Name of Analyst who Performed the Test:	Simin Mohammad (Active Air Sampling Plate Setup) Sophia Santamaria (Active Air Sampling Plate Reader)	**Sample / Active Name**	EM SMO 142 Air 26JUN2026	**Lot #:**	EM SMO 142 Air 26JUN2026
		Dosage Form	Plate		
Description of Incident:	The CFU count for the environmental monitoring plate exceeded the action level.	☐ Client Care notified of OOS ☐ Sterility and Endotoxin test related OOS; Client must be notified within 24 hours of OOS			
	SOP / Test Method #: MICRO-SOP-2	Effective Date: 23 Jul 2026	SOP / Test Method Rev: Rev. 16	Limits/Specification: Alert Level: ≥ 8 CFU/Plate Action Level: > 10 CFU/Plate	
Manager notified	Manager/designee name: Kathan Parikh	Date: 06-Jul-2026	Quality Assurance Department notified:	Yes ☐ No ☐	

Section B – Investigation and Root Cause Analysis			
Personnel Discrepancy		**Comments**	
Analyst interviewed?	☑ Yes ☐ No ☐ N/A	Yes, analysts Simin Mohammad and Sophia Santamaria were comprehensively interviewed.	
Correct samples analyzed?	☐ Yes ☐ No ☑ N/A	N/A	
Correct SOP / Test Method used/followed?	☑ Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-2	
Correct sample collection/technique?	☑ Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-2	
Are the Test Result Records Attached & Calculations Verified and Correct?	☑ Yes ☐ No ☐ N/A	Yes, Information is available in EagleTrax under ETX-260706-0305.	
Is the analyst qualified to perform the test?	☑ Yes ☐ No ☐ N/A	Yes, the analysts are trained and qualified by quality to perform the test.	
Is formula worksheet provided and verified?	☐ Yes ☐ No ☑ N/A	Not applicable	
Does the processing method/method set conform to the required specification?	☐ Yes ☐ No ☑ N/A	Not applicable	
Was the sample stored appropriately?	☑ Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-2	
Material Discrepancy		**Lot Number**	**Expiry Date**
Is the integrity of the sample(s) questionable?	☐ Yes ☑ No ☐ N/A		
Was the sample transported appropriately?	☑ Yes ☐ No ☐ N/A		
Are the other test results from this run under investigation?	☐ Yes ☐ No ☑ N/A		

OOS Number: OOS- 261553

Appropriate/correct glassware used?	☐Yes ☐No ☑N/A		
Are reagents stored in proper condition and not expired?	☑Yes ☐No ☐N/A	TSA Plate: 1011622280	TSA Plate: 11 Nov 2026
Standard Used	Not Applicable	Not Applicable	Not Applicable
Solvent Used	Not Applicable	Not Applicable	Not Applicable
Is the standard the source of the root cause?	☐Yes ☐No ☑N/A		
Has the analyst been instructed to keep the original test solution for possible retesting?	☐Yes ☐No ☑N/A		
Equipment Discrepancy		**Equipment ID**	**Calibration Due Date**
Was the instrument set up correctly?	☑Yes ☐No ☐N/A	Please see below	Please see below
Is the clean room facility certified?	☑Yes ☐No ☐N/A	CR142	Nov 2026
System Performance Check (if applicable)?	☐Yes ☐No ☑N/A	Not Applicable	Not Applicable
System Suitability RSD < 2% (PDA)?	☐Yes ☐No ☑N/A	Not Applicable	Not Applicable
System Suitability RSD < 10% (QDA, CAD)?	☐Yes ☐No ☑N/A	Not Applicable	Not Applicable
Do the environmental monitoring results conform to required standards?	☐Yes ☑No ☐N/A	No	No
Do the controls (i.e., positive, negative, etc.) conform to the required standards?	☐Yes ☐No ☑N/A	Not Applicable	Not Applicable
Is equipment/instrument functional and calibrated/qualified/certified/PM?	☑Yes ☐No ☐N/A	Incubator: E001031 (Sensor E001505) Incubator: E001034 (Sensor E001501)	Aug 2027 Feb 2027 Aug 2027 Feb 2027

OOS Number: OOS- 261553

Are chromatogram/spectra/raw data correct?	☐ Yes ☐ No ☑ N/A	Not Applicable	Not Applicable

Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)

- ☑ N/A
- ☐ Re-injection of sample vial
- ☐ Re-injection of original standard vial
- ☐ Re-vialing of original working standard solution
- ☐ Re-vialing of original working sample solution
- ☐ Re-dilution of a working sample solution from the original stock
- ☐ Re-dilution of a working standard solution from the original stock standard
- ☐ Other: N/A MN 10 Sep 2026

Section D – Phase I Summary

Phase I Summary:

The analyst involved in the weekly active air sampling plate setup, Simin Mohammad, and the analyst involved in reading the plate, Sophia Santamaria, were interviewed comprehensively. Their answers are recorded throughout this document.

The EM plates were stored in compliance with the supplier's recommendations, and their integrity was visually inspected prior to use. Furthermore, the plates were confirmed to be within their valid expiration dates. All the supplies were thoroughly disinfected according to MICRO SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). The functionality of both incubators were verified through a review of data obtained from our comprehensive in-house continuous monitoring system.

Weekly active air sampling was performed by analyst Simin Mohammad, in ISO 8 Cleanroom Suite 142, on 26 Jun 2026 as per MICRO-SOP-2 - Environmental Monitoring of the Cleanroom Facility.

The plates were initially incubated at a temperature of 30–35°C in incubator E001031 for a minimum duration of 48 hours, commencing on 26 Jun 2026. Following completion of minimum of 48 hours of incubation on 29 Jun 2026, the plates were further incubated for minimum of 5 days, with the incubation concluding on 06 Jul 2026. Please see Table 1 for detailed information on the observations during respective incubations.

Based on the observations in Table 1, since the CFU count exceeded the action level for the ISO 8 CR142 active air sampling plate, the plate was submitted for Microbial Identification under ETX-260706-0305. The colonies were identified as identified as Micrococcus luteus (Gram (+) cocci), Staphylococcus haemolyticus (Gram (+) cocci) and Auricoccus indicus (Gram (+) cocci).

To observe if the organisms identified, were transient in nature or recurring, weekly environmental monitoring plates for cleanroom suite 142, were bracketed to include date before testing and date after testing as detailed in Table 2 (please see attached).

OOS Number: OOS- 261553

Phase I Summary (continued):

Environmental Monitoring Summary: Weekly active air and surface monitoring for the preceding week was not performed, as the L-Suite had not yet been certified.

During the week under investigation, weekly active air monitoring in CR142 yielded a total of 11 CFUs. The recovered environmental isolates were identified as Micrococcus luteus (Gram-positive cocci), Staphylococcus haemolyticus (Gram-positive cocci), and Auricoccus indicus (Gram-positive cocci). Additionally, 3 CFUs were recovered from the active air monitoring plate in CR143 Section II, which were identified as Micrococcus luteus, Staphylococcus capitis, and Trematеia guiyangensis. During the subsequent week of monitoring, performed on 03 Jul 2026, 10 CFUs were recovered from the CR143 Section I active air plate and 8 CFUs were recovered from the CR143 Section II active air plate. Colonies recovered from both locations were morphologically characterized as Gram-positive cocci and Gram-positive short rods.

Weekly surface monitoring conducted during the week under investigation recovered 2 CFUs from the sink table in ISO 8 CR142, which were identified as Gram-positive rods. In the following week, 5 CFUs were recovered from the same sampling location and were identified as Streptococcus thermophilus (Gram-positive cocci).

A summary of all relevant environmental monitoring results is provided in Table 2.

During the interview with the analyst, they indicated that no obvious abnormalities or deviations in the testing procedure were observed. All the samples were thoroughly disinfected prior to testing. The ISO 8 CR 142 was prepared, cleaned, and disinfected before initiation of testing in accordance with MICRO-SOP-2 and MICRO-SOP-9.

Monthly cleaning and disinfection of the ISO 8 Anteroom (CR142), ISO 8 Anteroom (CR143), ISO 7 Buffer Room (CR144), ISO 7 Buffer Room (CR145), and associated ISO 5 Biosafety Cabinets were performed on 14 Jun 2026 in accordance with MICRO-SOP-9, by laboratory technician Andrew Carrillo. Documentation confirmed that all hydrogen peroxide (H_2O_2) indicators passed acceptance criteria, demonstrating successful completion of the monthly decontamination process. Additionally, routine cleaning and disinfection activities were performed both before and after testing in accordance with established procedures.

Notably no samples processed within that week in CR 142 failed ScanRDI test.

OOS Number: OOS- 261553

Phase I Summary (continued):

Based on the available evidence, the recovery of 11 CFUs from the weekly active air sampling plate collected on 26 Jun 2026 appears to represent an isolated event. This assessment is supported by the absence of microbial recovery from the CR142 weekly active air sampling plate collected in the following week of testing (03 Jul 2026).

The environmental monitoring results and organism identification did not indicate an ongoing or systemic contamination issue. The investigation identified no impact to client samples, testing activities, or laboratory operations attributable to the event. A review of sample results, environmental monitoring data, and associated laboratory activities did not identify any evidence that samples were adversely affected by the positive environmental monitoring result.

Taken together, the available data indicate that the environmental monitoring event was transient and non-recurring, with no evidence of sample impact or a systemic environmental control deficiency. The findings are most consistent with an isolated environmental monitoring excursion, with potential laboratory-related factors considered as a possible contributor. Therefore, no additional corrective or preventive actions are warranted at this time beyond continued routine environmental monitoring, adherence to established cleaning and disinfection controls, and compliance with existing procedures.

OOS Number: OOS- 261553

Has root cause been identified as a possible laboratory error?
Note: Root cause must be conclusive, verifiable, and well-documented.

☑ Yes

☐ If retesting is ***required***, complete Phase II of the OOS (initiate Form 3.100.019.F02).

☐ No, the OOS result is valid.

Reviewer comment(s):

Prepared by (*Print*)**:** Maryam Naeem	Signature/Date:
Lab Manager/Designee (*Print*)**:** Neha Hulyalkar	Signature/Date:

Section E – Quality Disposition

Can investigation be closed?

☐ Yes

☐ Original result is valid.

☐ No, initiate Form 3.100.019.F02.

Approved by QA Representative (*Print*)**:**	Signature/Date:

Table 1: Read Dates & Incubation Observation

ETX Submission ID	Set-up Analyst & Date	Sampling Site & Location	Plate Reading Analyst (≥ 48H)	CFUs Observed after 48 Hour Incubation at 30–35°C (E001031)	Plate Reading Analyst (NLT 5 days)	CFUs Observed after NLT 5-day Incubation at 20–25°C (E001034)	Microbial Identification
ETX-260706-0305, ETX-260706-0300	SMO 26 Jun 2026	Weekly active air Sampling Plate	SAS 29 Jun 2026	3 CFUs on 143 Section II plate and 11 CFUs on CR142 plate	SAS 06 Jul 2026	3 CFUs on 143 Section II plate and 11 CFUs on CR142 plate	*Micrococcus luteus (Gram (+) cocci, Staphylococcus haemolyticus Gram (+) cocci, Auricoccus indicus Gram (+) cocci.), Staphylococcus capitis Gram (+) cocci, Tremateia guiyangensis Hyphae*

Table 2: Environmental Monitoring for Analyst & Cleanroom

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMM YYYY)	Analyst (Initials)	Day /Week(s)	Observation	Environmental Monitoring Plate ETX ID	Microbial ID	Notes
Weekly Active Air Sampling Bracketing								
Active Air Sampling of Cleanrooms	Weekly	26 Jun 2026	SMO	Week (Of Testing Date)	3 CFUs on 143 Section II plate and 11 CFUs on CR142 plate	ETX-260706-0305, ETX-260706-0300	*Micrococcus luteus (Gram (+) cocci, Staphylococcus haemolyticus Gram (+) cocci, Auricoccus indicus Gram (+) cocci.), Staphylococcus capitis Gram (+) cocci, Tremateia guiyangensis Hyphae*	None
Active Air Sampling of Cleanrooms	Weekly	03 Jul 2026	SMO	Week (After Testing Date)	8 CFUs on CR143 Section II plate and 10 CFUs on 143 Section I plate	ETX-260713-0353, ETX-260713-0358	Gram (+) short rods, Gram (+) cocci	None
Surface Sampling of Anteroom and Cleanroom Bracketing								
Surface Sampling of Cleanrooms	Weekly	26 JUN 2026	SMO	Week (Of Testing Date)	2 CFUs on the Sink Table in Room 142	ETX-260706-0295	Gram (+) rods	None
Surface Sampling of Cleanrooms	Weekly	03 JUL 2026	SMO	Week (After Testing Date)	5 CFUs on the Sink Table in Room 142	ETX-260713-0361	Streptococcus thermophilus Gram (+) cocci	None