OOS Number: OOS- 262098

Phase I

Section A – Test Details					
Initiator:	Alex Saravia (Written by Qiyue Chen)	**Test Date:**	04-Sep-2026	**Date Initiated:**	10-Sep-2026
Date of Incident:	10-Sep-2026	**Test Name:**	USP <71> / EP 2.6.1 Sterility Test	**Sample ID:**	ETX-260902-0505
Name of Analyst who Performed the Test:	Prepping Analyst: Ishita Sharma (ISS) Processing Analyst: Alex Saravia (ES) Reading Analyst: Elysse Nioupin (EN)	**Sample / Active Name**	GLP3R/Cagrilinitide	**Lot #:**	2608-216
		Dosage Form	Liquid		
Description of Incident:	On 10-Sep-2026, sample ETX-260902-0505 was found positive for viable microorganisms after USP <71> sterility testing.	☑ Client Care notified of OOS ☑ Sterility and Endotoxin test related OOS; Client must be notified within 24 hours of OOS			
	SOP / Test Method #: MICRO-SOP-5	Effective Date: 24Jul2026	SOP / Test Method Rev: 19	Limits/Specification: Pass/Fail	
Manager notified	Manager/designee name: Kathan Parikh	Date: 10-Sep-2026	Quality Assurance Department notified:	Yes ☑ No ☐	

Section B – Investigation and Root Cause Analysis			
Personnel Discrepancy		**Comments**	
Analyst interviewed?	☑Yes ☐ No ☐ N/A	Yes, analysts Ishita Sharma, Alex Saravia, and Elysse Nioupin were comprehensively interviewed.	
Correct samples analyzed?	☑Yes ☐ No ☐ N/A	Yes, sample ID: ETX-260902-0505	
Correct SOP / Test Method used/followed?	☑Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-5	
Correct sample collection/technique?	☑Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-5	
Are the Test Result Records Attached & Calculations Verified and Correct?	☑Yes ☐ No ☐ N/A	Yes, information is available on EagleTrax under ETX-260902-0505	
Is the analyst qualified to perform the test?	☑Yes ☐ No ☐ N/A	Yes, the analysts are trained and qualified by quality to perform the test	
Is formula worksheet provided and verified?	☐Yes ☐ No ☑ N/A	Not Applicable	
Does the processing method/method set conform to the required specification?	☐Yes ☐ No ☑ N/A	Not Applicable	
Was the sample stored appropriately?	☑Yes ☐ No ☐ N/A	Yes, the sample was stored refrigerated as per client's instructions	
Material Discrepancy		**Lot Number**	**Expiry Date**
Is the integrity of the sample(s) questionable?	☐Yes ☑ No ☐N/A		
Was the sample transported appropriately?	☑Yes ☐ No ☐N/A		
Are the other test results from this run under investigation?	☐Yes ☑ No ☐N/A		

Printed by rseymour@eagleanalytical.com from https://app.zenqms.com on 10-Sep-2026 at 7:25:44 PM UTC

OOS Number: OOS- 262098

Appropriate/correct glassware used?	☐Yes ☐ No ☑N/A		
Are reagents stored in proper condition and not expired?	☑Yes ☐ No ☐N/A	Process Consumables: Information is available in EagleTrax Sample Consumables section Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly cleaning logs	Process Consumables: Information is available in EagleTrax Sample Consumables section Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly cleaning logs
Standard Used	Not applicable	Not applicable	Not applicable
Solvent Used	Not applicable	Not applicable	Not applicable
Is the standard the source of the root cause?	☐Yes ☐ No ☑N/A		
Has the analyst been instructed to keep the original test solution for possible retesting?	☐Yes ☐ No ☑N/A		
Equipment Discrepancy		**Equipment ID**	**Calibration Due Date**
Was the instrument set up correctly?	☑Yes ☐ No ☐ N/A	ISO 5 BSC E001316	Jun 2027
Is the clean room facility certified?	☑Yes ☐ No ☐ N/A	E001736 (CR114)	Dec 2026
System Performance Check (if applicable)?	☐Yes ☐ No ☑ N/A	Not applicable	Not applicable
System Suitability RSD < 2% (PDA)?	☐Yes ☐ No ☑ N/A	Not applicable	Not applicable
System Suitability RSD < 10% (QDA, CAD)?	☐Yes ☐ No ☑ N/A	Not applicable	Not applicable
Do the environmental monitoring results conform to required standards?	☑Yes ☐ No ☐ N/A	Phase I Summary	Phase I Summary
Do the controls (i.e., positive, negative, etc.) conform to the required standards?	☑Yes ☐ No ☐ N/A	Phase I Summary	Phase I Summary
Is equipment/instrument functional and calibrated/qualified/certified/PM?	☑Yes ☐ No ☐ N/A	Incubator E001356 (Sensor E001450) Incubator E001357 (Sensor E001449) Incubator E001034 (Sensor E001501) Incubator E001031 (Sensor E001505) ISO 5 BSC E001316	Jan 2027 Feb 2027 Jan 2027 Feb 2027 Aug 2027 Feb 2027 Aug 2027 Feb 2027 Dec 2026

OOS Number: OOS- 262098

Are chromatogram/spectra/raw data correct?	☐ Yes ☐ No ☑ N/A	Not applicable	Not applicable

Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)

- ☑ N/A
- ☐ Re-injection of sample vial
- ☐ Re-injection of original standard vial
- ☐ Re-vialing of original working standard solution
- ☐ Re-vialing of original working sample solution
- ☐ Re-dilution of a working sample solution from the original stock
- ☐ Re-dilution of a working standard solution from the original stock standard
- ☐ Other: N/A QYC 15Oct26

Section D – Phase I Summary

Phase I Summary:

All analysts involved in the prepping, processing, and reading of the sample - Ishita Sharma, Alex Saravia, and Elysse Nioupin - were interviewed comprehensively. Their answers are recorded throughout this document. This investigation was performed in accordance with MICRO-SOP-53, Sterility Test Out-of-Specification Investigation Procedure.

Upon arrival, the sample was stored refrigerated in accordance with the Client's instructions. Prepping analyst - Ishita Sharma - and processing analyst - Alex Saravia - verified the physical integrity and packaging of the sample throughout both the preparation and processing stages. No leaks, cracks, or visible turbidity were observed at any point, verifying container integrity.

All reagents and supplies mentioned in the material section above were stored according to the suppliers' recommendations, and their integrity was visually verified before utilization. Moreover, all reagents and supplies had valid expiration dates. The functionality of all equipment was confirmed by reviewing data generated by our comprehensive in-house continuous monitoring system.

The cleanroom suite (CR 114) used for processing procedures comprises three interconnected sections: the innermost ISO 7 cleanroom (114B), which connects to the middle ISO 7 buffer room (114A), and then to the outermost ISO 8 anteroom (114). A positive air pressure system is maintained throughout the suite to ensure controlled, unidirectional airflow from 114B through 114A and into 114.

The ISO 5 Biological Safety Cabinet (BSC) E001316, located in the innermost ISO 7 room (114B), was used for sample processing steps. It was thoroughly cleaned and disinfected prior to each procedure in accordance with MICRO SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). Additionally, BSC E001316 was certified and approved by both the Engineering and Quality Assurance teams. Sample processing was conducted in the ISO 5 BSC E001316 in the innermost ISO 7 room (114B) by Alex Saravia on 04Sep26 as per MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test).

On 04Sep26, the sample vials for ETX-260902-0505 were received from the Sample Submissions team and brought into the Sterile Microbiology lab. Upon arrival, each sample vial was sprayed with an acidified bleach disinfectant, placed into pre-disinfected bins, and allowed a 10-minute contact time.

The secondary disinfection happened in the ISO 8 anteroom (114), where the vials were again treated with acidified bleach and provided a 10-minute contact time before processing. Subsequently, the vials were moved into innermost ISO 7 cleanroom (114B). Inside this cleanroom, the processing analyst, Alex Saravia, performed a final disinfection step, allowing an additional 10-minute contact time. Once fully disinfected, the vials were transferred into the ISO 5 BSC E001316.

Inside the BSC, each container was aseptically opened, ensuring minimal exposure to the environment. The contents were then reconstituted with 2mL Bacteriostatic water per vial (each vial containing GLP3R/Cagrilinitide in 25mg/5mg concentration). Half the contents of each reconstituted vial was then dispensed directly from the container into sterile canisters placed on a vacuum manifold for membrane filtration. The sample was processed and tested as per MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test). Media bottles were transferred into incubators E001356 and E001357 to begin incubation.

OOS Number: OOS- 262098

Phase I Summary (continued):

On 10Sep26 (Day 6 of incubation), microbial growth was observed in one TSB (Tryptic Soy Broth) media bottle by analyst, Elysse Nioupin, and confirmed by Microbiology Lab Supervisor, Robin Seymour. The positive TSB bottle for ETX-260902-0505 was submitted for Differential Staining and Microbial Identification under ETX-260910-0290. Differential staining indicated the presence of Gram-positive rods. Definitive identification identified the isolate as Microbacterium sp. PM5 (Gram-positive rods).

The culture media utilized were within their expiry period. Negative control media bottles for the membrane filtration method were handled, processed, and incubated in the same manner as the test samples. No microbial growth was observed in the corresponding negative controls.

Environmental Monitoring (EM) Recoveries Review:

ISO 5 BSC and Personnel Evaluation:
Upon reviewing the environmental monitoring data associated with the sterility test, no microbial growth was detected on personnel monitoring plates (left- and right-hand touch plates for analyst Alex Saravia), settling plates, or ISO 5 BSC surface sampling plates within BSC E001316 on the date of testing (04Sep26), the preceding testing date (03Sep26), or the subsequent testing date (08Sep26). Therefore, the contemporaneous personnel and ISO 5 environmental monitoring results do not support processing personnel or the ISO 5 BSC as a potential source of the Microbacterium sp. PM5 detected in test sample ETX-260902-0505.

Cleanroom EM Evaluation:
Routine weekly surface sampling of Cleanroom Suite 114 performed on 04Sep26 demonstrated no microbial growth. Weekly active-air monitoring of the outermost ISO 8 Room 114 (CR 114) recovered 2 CFUs (ETX-260914-0487), identified as Corynebacterium ureicelerivorans and Mycobacterium grossiae. All of these cleanroom environmental isolates differed distinctly in genus and morphology from the product contamination isolate (Microbacterium sp. PM5). Considering the facility's layered disinfection program, controlled unidirectional airflow, physical segregation of the ISO 8 anteroom, and complete absence of contamination in the ISO 5 critical zone, these recoveries represent an isolated background event and are not considered a credible source of contamination for the test sample.

The absence of contamination on analyst glove plates and work-surface environmental monitoring plates collected on the date of testing indicates that there was no viable transfer of contaminants to the ISO 5 BSC. Additionally, the lack of contamination in other samples processed during the same testing session further demonstrates that the testing environment was operating in optimal condition.

The analysts confirmed full compliance with cleaning procedures as outlined in MICRO SOP-9 (Cleaning and Disinfecting Procedure for Microbiology) and MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test).

Monthly cleaning and disinfection of the outermost ISO 8 Anteroom, the middle ISO 7 Buffer room, the innermost ISO 7 cleanroom, and its containing ISO 5 BSCs for Cleanroom suite CR114 was performed on 16Aug26, as per MICRO-SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). During both cleaning cycles, it was documented that all H2O2 indicators passed. This confirms the efficient monthly cleaning of all three parts of Cleanroom suite CR114.

Analyzing a 6-month sample history for Solyn LLC (E75000), this specific analyte "GLP3R/Cagrilinitide" has had no prior failures using USP <71> / EP 2.6.1 Sterility Test during this period.

To assess the potential for sample-to-sample contamination contributing to the positive results, a comprehensive review was conducted of all samples processed on the same day. All other samples processed by the analyst and other analysts that day tested negative. These findings suggest that cross-contamination between samples is highly unlikely.

OOS Number: OOS- 262098

Phase I Summary (continued):

Based on the observations outlined above, it is unlikely that the failing results were due to reagents, supplies, the cleanroom environment, the process, or analyst involvement. Consequently, the possibility of laboratory error contributing to this failure is minimal and the original result is deemed to be valid.

However, when investigating the lot history, it was discovered that the same lot (Lot 2608-216) had previously been submitted for ScanRDI sterility testing under ETX-260807-0602 and yielded a passing result. Based on this conflicting passing ScanRDI result for the same lot, the laboratory requested additional sample vials from the client for retesting under ETX-260914-0470 and initiated a Phase II investigation (CORP-FORM-22).

OOS Number: OOS- 262098

Has root cause been identified as a possible laboratory error?
Note: Root cause must be conclusive, verifiable, and well-documented.

☐ Yes

☑ If retesting is ***required***, complete Phase II of the OOS (initiate Form 3.100.019.F02).

☑ No, the OOS result is valid.

Reviewer comment(s):

Prepared by (*Print*)**:** Qiyue Chen	Signature/Date: Qiyue Chen Digitally signed by Qiyue Chen DN: OU=Eagle Analytical Services, O=Strerie Lab, CN=Qiyue Chen, E=qchen@eagleanalytical.com Location: Houston, TX Date: 2026.10.22 11:31:07-05'00' Foxit PDF Editor Version: 13.2.7
Lab Manager/Designee (*Print*)**:** Robin Seymour	Signature/Date: Robin Seymour Digitally signed by Robin Seymour DN: CN=Robin Seymour, O=Eagle Analytical Services, OU=Microbiology - Cleanroom Ops , E=rseymour@eagleanalytical.com Reason: I have reviewed this document Location: Date: 2026.10.22 13:08:33-05'00' Foxit PDF Editor Version: 14.0.8

Section E – Quality Disposition

Can investigation be closed?

☐ Yes

☐ Original result is valid.

☐ No, initiate Form 3.100.019.F02.

Approved by QA Representative (*Print*)**:**	Signature/Date:

Table 1: Information for ETX-260902-0505 under investigation

Processing Analyst	Reading Analyst	Sample ID	Related Microbial ID	Media with microbial growth	Microbial ID
Alex Saravia	Elysse Nioupin	ETX-260902-0505	ETX-260910-0290	1 x 100mL TSB bottle	*Microbacterium sp. PM5* (Gram (+) rods)

Table 2: Environmental Monitoring from Processing Performed on 04Sep26

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMMYY)	Analyst (Initials)	Day /Week(s)	Observation	Environmental Monitoring Plate ETX ID	Microbial ID	Notes
Personnel EM Bracketing								
Personnel (Left Touch and Right Touch)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Biological Safety Cabinet EM Bracketing - ISO 5 BSC E001316 (Suite 114)								
Surface Sampling of ISO 5 (4 locations)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Weekly Active Air Sampling Bracketing (Suite 114)								
Active Air Sampling of Cleanrooms	Weekly	04Sep26	ISS	Week on Testing Date	2 CFUs (ISO 8 114)	ETX-260914-0487	*Corynebacterium ureicelerivorans* *Mycobacterium grossiae*	None
Weekly Surface Sampling of Cleanrooms Bracketing (Suite 114)								
Surface Sampling of Cleanrooms	Weekly	04Sep26	ISS	Week on Testing Date	No growth	N/A	N/A	None