OOS Number: OOS- 262022

Phase I

Section A – Test Details					
Initiator:	Ayomide Odugbesi (Written by: Dhvanir Kansara)	**Test Date:**	24-Aug-2026	**Date Initiated:**	01-Sep-2026
Date of Incident:	01-Sep-2026	**Test Name:**	USP <71> / EP 2.6.1 Sterility Test	**Sample ID:**	ETX-260820-0099
Name of Analyst who Performed the Test:	Prepping Analyst: Elysse Nioupin (EN) Processing Analyst: Ayomide Odugbesi (AOD) Reading Analyst: Andrew Carillo (ANC)	**Sample / Active Name**	Viscum Album 1mg	**Lot #:**	260817b
		Dosage Form	Liquid		
Description of Incident:	On 01 Sep 2026, sample ETX-260820-0099 was found positive for viable microorganisms after USP <71> sterility testing.	☑ Client Care notified of OOS ☑ Sterility and Endotoxin test related OOS; Client must be notified within 24 hours of OOS			
	SOP / Test Method #: MICRO-SOP-5	Effective Date: 24Jul2026	SOP / Test Method Rev: 19	Limits/Specification: Pass/Fail	
Manager notified	Manager/designee name: Kathan Parikh	Date: 01-Sep-2026	Quality Assurance Department notified:	Yes ☑ No ☐	

Section B – Investigation and Root Cause Analysis			
Personnel Discrepancy		**Comments**	
Analyst interviewed?	☑ Yes ☐ No ☐ N/A	Yes, analysts Elysse Nioupin, Andrew Carillo, and Ayomide Odugbesi were comprehensively interviewed.	
Correct samples analyzed?	☑ Yes ☐ No ☐ N/A	Yes, sample ID: ETX-260820-0099	
Correct SOP / Test Method used/followed?	☑ Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-5	
Correct sample collection/technique?	☑ Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-5	
Are the Test Result Records Attached & Calculations Verified and Correct?	☑ Yes ☐ No ☐ N/A	Yes, Information is available on Eagletrax under ETX-260820-0099.	
Is the analyst qualified to perform the test?	☑ Yes ☐ No ☐ N/A	Yes, the analysts are trained and qualified by quality to perform the test	
Is formula worksheet provided and verified?	☐ Yes ☐ No ☑ N/A	Not applicable	
Does the processing method/method set conform to the required specification?	☐ Yes ☐ No ☑ N/A	Not applicable	
Was the sample stored appropriately?	☑ Yes ☐ No ☐ N/A	Yes, the sample was stored as per client's instructions. Information is available in EagleTrax Sample Location History under ETX-260820-0099.	
Material Discrepancy		**Lot Number**	**Expiry Date**
Is the integrity of the sample(s) questionable?	☐ Yes ☑ No ☐ N/A		
Was the sample transported appropriately?	☑ Yes ☐ No ☐ N/A		
Are the other test results from this run under investigation?	☐ Yes ☑ No ☐ N/A		

OOS Number: OOS- 262022

Appropriate/correct glassware used?	☐ Yes ☐ No ☑ N/A		
Are reagents stored in proper condition and not expired?	☑ Yes ☐ No ☐ N/A	Process Consumables: Information is available in EagleTrax Sample Consumables section Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly cleaning logs	Process Consumables: Information is available in EagleTrax Sample Consumables section Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly cleaning logs
Standard Used	Not applicable	Not applicable	Not applicable
Solvent Used	Not applicable	Not applicable	Not applicable
Is the standard the source of the root cause?	☐ Yes ☐ No ☑ N/A		
Has the analyst been instructed to keep the original test solution for possible retesting?	☐ Yes ☐ No ☑ N/A		
Equipment Discrepancy		**Equipment ID**	**Calibration Due Date**
Was the instrument set up correctly?	☑ Yes ☐ No ☐ N/A	ISO 5 BSC E001314	Jun 2027
Is the clean room facility certified?	☑ Yes ☐ No ☐ N/A	E001737 (CR115)	Dec 2026
System Performance Check (if applicable)?	☐ Yes ☐ No ☑ N/A	Not applicable	Not applicable
System Suitability RSD < 2% (PDA)?	☐ Yes ☐ No ☑ N/A	Not applicable	Not applicable
System Suitability RSD < 10% (QDA, CAD)?	☐ Yes ☐ No ☑ N/A	Not applicable	Not applicable
Do the environmental monitoring results conform to required standards?	☑ Yes ☐ No ☐ N/A	See Phase I Summary	See Phase I Summary
Do the controls (i.e., positive, negative, etc.) conform to the required standards?	☑ Yes ☐ No ☐ N/A	See Phase I Summary	See Phase I Summary
Is equipment/instrument functional and calibrated/qualified/certified/PM?	☑ Yes ☐ No ☐ N/A	Incubator E001356 (Monitored by Sensor E001450) Incubator E001357 (Monitored by Sensor E001449) Incubator E001034 (Monitored by Sensor E001501) Incubator E001031 (Monitored by Sensor E001505) ISO 5 BSC E001314	Jan 2027 Feb 2027 Jan 2027 Feb 2027 Aug 2027 Feb 2027 Aug 2027 Feb 2027 Jun 2027

OOS Number: OOS- 262022

Are chromatogram/spectra/raw data correct?	☐ Yes ☐ No ☑ N/A	Not applicable	Not applicable

Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)

- ☑ N/A
- ☐ Re-injection of sample vial
- ☐ Re-injection of original standard vial
- ☐ Re-vialing of original working standard solution
- ☐ Re-vialing of original working sample solution
- ☐ Re-dilution of a working sample solution from the original stock
- ☐ Re-dilution of a working standard solution from the original stock standard
- ☐ Other: N/A DK 02Oct2026

Section D – Phase I Summary

Phase I Summary:

This investigation was performed as per MICRO-SOP-53 Sterility Test Out-of-Specification (OOS) Investigation Procedure.

All analysts involved in the prepping, processing, and reading of the sample – Elysse Nioupin, Ayomide Odugbesi, and Andrew Carillo were interviewed comprehensively. Their answers are recorded throughout this document.

Upon arrival, the sample was stored in accordance with the Client's instructions. Analyst Ayomide Odugbesi verified the integrity of the sample throughout both the preparation and processing stages. No leaks or turbidity were observed at any point, verifying the integrity of the sample.

All reagents and supplies mentioned in the material section above were stored according to the suppliers' recommendations, and their integrity was visually verified before utilization. Moreover, all reagents and supplies had valid expiration dates. The functionality of all equipment was confirmed by reviewing data generated by our comprehensive in-house continuous monitoring system.

The cleanroom suite (CR115) used for processing procedures comprises three interconnected sections: the innermost ISO 7 cleanroom (115B), which connects to the middle ISO 7 buffer room (115A), and then to the outermost ISO 8 anteroom (115). A positive air pressure system is maintained throughout the suite to ensure controlled, unidirectional airflow from 115B through 115A and into 115.

The ISO 5 BSC E001314, located in the innermost ISO 7 room, (115B), was used for sample processing steps. It was thoroughly cleaned and disinfected prior to each procedure in accordance with MICRO SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). Additionally, BSC E001314 was certified and approved by both the Engineering and Quality Assurance teams. Sample processing was conducted in the ISO 5 BSC E001314 in the innermost ISO 7 room, (115B) by Ayomide Odugbesi on 24 Aug 2026 as per MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test).

On 24 Aug 2026, the sample vials for ETX-260820-0099 were received from the Sample Submissions team and brought into the Sterile Microbiology lab. Upon arrival, each sample vial was sprayed with an acidified bleach disinfectant, placed into pre-disinfected bins, and allowed a 10-minute contact time.

The secondary disinfection happened in the ISO 8 anteroom (115), where the vials were again treated with acidified bleach and provided a 10- minutes contact time before processing. Subsequently, the vials were moved into innermost ISO 7 cleanroom (115B). Inside this cleanroom, the processing analyst, Ayomide Odugbesi, performed a final disinfection step, allowing an additional 10-minute contact time. Once fully disinfected, the vials were transferred into the ISO 5 BSC E001314.

OOS Number: OOS- 262022

Phase I Summary (continued):

Inside the BSC, each container was aseptically opened, ensuring minimal exposure to the environment. The contents were then dispensed directly from the container into sterile canisters placed on a vacuum manifold for membrane filtration. The sample was processed and tested as per MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test). Media bottles were transferred into incubators E001356 and E001357 to begin incubation.

On 01 Sep 2026 (Day 8 of incubation), microbial growth was observed in one TSB (Tryptic Soy Broth) media bottle by analyst, Andrew Carillo, and confirmed by Microbiology Lab Supervisor, Robin Seymour. The positive TSB bottle for ETX-260820-0099 was submitted for Differential Staining and Microbial Identification under ETX-260901-0443. Differential staining indicated the presence of Gram-positive rods. Definitive identification identified the isolate as Bacillus safensis (Gram (+) rods).

Upon analyzing the environmental monitoring results, no microbial growth was detected on personnel monitoring plates on the preceding testing date (21 Aug 2026) or the subsequent testing date (25 Aug 2026). On the date of testing (24 Aug 2026), 2 CFUs were recovered from the right-hand touch personnel monitoring plate (ETX-260831-0417) and were identified as Bacillus licheniformis (Gram (+) endospore-forming rods) and Micrococcus luteus (Gram (+) cocci). No microbial growth was detected on settling plates or ISO 5 BSC surface sampling plates on the date of testing, the preceding testing date, or the subsequent testing date. Additionally, no microbial growth was recovered from the weekly surface sampling of anteroom, buffer room and cleanroom plates collected on 20 Aug 2026. The weekly active air sampling collected on 20 Aug 2026 recovered 9 CFUs of Gram (+) cocci from the ISO 8 area (ETX-260831-0366).

Although microbial growth was recovered on the analyst right-hand glove plate collected on the date of testing, the organisms identified (Bacillus licheniformis and Micrococcus luteus) are different from the organism recovered in the test sample (Bacillus safensis). Similarly, the Gram (+) cocci recovered from the weekly active air sampling of the ISO 8 cleanroom (115) are morphologically different from the Gram (+) rods recovered in the test sample. The absence of contamination on work-surface environmental monitoring plates collected on the date of testing indicates that there were no viable transfer of contaminants from ISO 8 environment to the ISO 5 biological safety cabinet (BSC). Additionally, the lack of contamination in the other samples (30 +) processed during the same testing session further demonstrates that the testing environment was operating in optimal condition.

Therefore, based on the absence of microbial recovery from ISO 5 critical-area monitoring, the lack of microbiological correlation between organisms recovered from personnel and environmental monitoring and the isolate recovered from the test sample, and the absence of growth on weekly surface monitoring plates from Cleanroom Suite CR115, the cleanroom environment is not considered a credible source of the Bacillus safensis recovered from the test sample.

The analysts confirmed full compliance with cleaning procedures as outlined in MICRO SOP-9 (Cleaning and Disinfecting Procedure for Microbiology) and MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test).

Monthly cleaning and disinfection of the outermost ISO 8 Anteroom, the middle ISO 7 Buffer room, the innermost ISO 7 cleanroom, and its containing ISO 5 BSCs for Cleanroom suite CR115 was performed on 16 Aug 2026, as per MICRO-SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). During both cleaning cycles, it was documented that all H_2O_2 indicators passed. This confirms the efficient monthly cleaning of all three parts of Cleanroom suite CR115.

Analyzing a 6-month sample history for Uriel Pharmacy (E02836), one prior failure under ETX-260811-0261 (OOS-261987) using USP <71> / EP 2.6.1 Sterility Test during this period was found. The same sample analyte "Viscum Album" at higher concentration (20 mg) was tested. The microbial growth recovered for ETX-260811-0261 (OOS-261987) was identified to be Bacillus velezensis (Gram (+) rods). No laboratory errors were determined to be contributing to the failing result of ETX-260811-0261.

During review of lot history, additional sample material of the same lot "260817b" was received for Scan RDI testing on 18 Sep 2026 under submission ETX-260914-0452 and passed the sterility test. However, it is important to note that a review of the submission determined that no approved method suitability test was available to support the validity for microbial growth recovery using the ScanRDI method for this specific sample.

Furthermore, the discrepancy between the previous passing ScanRDI result and the current USP <71> sterility failure may be attributable to the non-homogeneous distribution of microbial contamination within the compounded batch. When microbial contamination is present at very low levels, microorganisms may not be uniformly distributed throughout the product, resulting in variability between samples collected from the same lot. Consequently, one aliquot may not contain contaminating microorganisms and yield an acceptable result, while another aliquot from the same batch may contain viable microorganisms and generate a positive sterility test result. Given the absence of a qualified method suitability study for the ScanRDI submission, the prior passing result cannot be considered directly comparable to the current USP <71> sterility test outcome.

To assess the potential for sample-to-sample contamination contributing to the positive results, a comprehensive review was conducted of all samples processed on the same day. All other samples processed by the analyst and other analysts that day tested negative. These findings suggest that cross-contamination between samples is highly unlikely.

Based on the observations outlined above, it is unlikely that the failing results were due to reagents, supplies, the cleanroom environment, the process, or analyst involvement. Consequently, the possibility of laboratory error contributing to this failure is minimal and the original result is deemed to be valid.

OOS Number: OOS- 262022

Phase I Summary (continued):

N/A DK 02Oct2026

OOS Number: OOS- 262022

Has root cause been identified as a possible laboratory error?
Note: Root cause must be conclusive, verifiable, and well-documented.

☐ Yes

☐ If retesting is ***required***, complete Phase II of the OOS (initiate Form 3.100.019.F02).

☑ No, the OOS result is valid.

Reviewer comment(s):

Prepared by (*Print*)**:**	Signature/Date:
Dhvanir Kansara	Dhvanir Kansara Digitally signed by Dhvanir Kansara DN: CN=Dhvanir Kansara, O=Eagle Analytical Services, OU=Project Microbiologist - Microbiology, E=dkansara@eagleanalytical.com Reason: I am the author of this document Location: Date: 2026.10.26 17:45:09-05'00' Foxit PDF Editor Version: 14.0.8
Lab Manager/Designee (*Print*)**:**	Signature/Date:
Robin Seymour	Robin Seymour Digitally signed by Robin Seymour DN: CN=Robin Seymour, O=Eagle Analytical Services, OU=Microbiology - Cleanroom Ops , E=rseymour@eagleanalytical.com Reason: I have reviewed this document Location: Date: 2026.10.26 17:50:48-05'00' Foxit PDF Editor Version: 14.0.8

Section E – Quality Disposition

Can investigation be closed?

☐ Yes

☐ Original result is valid.

☐ No, initiate Form 3.100.019.F02.

Approved by QA Representative (*Print*)**:**	Signature/Date:

Table 1: Information for samples under investigation OOS-262022

Reading Analyst	Day of Incubation	Sample ID	Related Microbial ID	Media with microbial growth	Microbial Identification
Andrew Carillo	08	ETX-260820-0099	ETX-260901-0443	1 x 100mL TSB	*Bacillus safensis* Gram (+) rods

Table 2: Environmental Monitoring for Analyst & Cleanroom

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMMYYYY)	Analyst (Initials)	Day /Week(s)	Observation	Environmental Monitoring Plate ETX ID	Microbial ID	Notes
Personnel EM Bracketing 24Aug2026								
Personnel (Left Touch and Right-Hand Touch)	Daily	21 Aug 2026	AOD	Date Before Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right- Hand Touch)	Daily	24 Aug 2026	AOD	Date of Testing	2 CFUs (Right-Hand Touch)	ETX-260831-0417	*Bacillus licheniformis* Gram (+) endospore-forming rods *Micrococcus luteus* Gram (+) cocci	None
Personnel (Left Touch and Right- Hand Touch)	Daily	25 Aug 2026	AOD	Date After Testing	No growth	N/A	N/A	None
Biological Safety Cabinet EM Bracketing Biological Safety Cabinet (BSC) E001314								
Surface Sampling of ISO 5 (4 locations)	Daily	21 Aug 2026	AOD	Date Before Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	24 Aug 2026	AOD	Date of Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	25 Aug 2026	AOD	Date After Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	21 Aug 2026	AOD	Date Before Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	24 Aug 2026	AOD	Date of Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	25 Aug 2026	AOD	Date After Testing	No growth	N/A	N/A	None
Weekly Active Air Sampling for CR 115 (E001737)								
Active Air Sampling of Cleanrooms	Weekly	20 Aug 2026	SMO	Week of Testing	9 CFUs (ISO8)	ETX-260831-0366	Gram (+) cocci	None
Surface Sampling of Anteroom, Buffer room and Cleanroom for CR 115 (E001737)								
Surface Sampling of Cleanrooms	Weekly	20 Aug 2026	SMO	Week of Testing	No growth	N/A	N/A	None