OOS Number: OOS- 262277

Phase I

Section A – Test Details					
Initiator:	Ayomide Odugbesi (Written by: Dhvanir Kansara)	**Test Date:**	25-Sep-2026	**Date Initiated:**	30-Sep-2026
Date of Incident:	30-Sep-2026	**Test Name:**	USP <71> / EP 2.6.1 Sterility Test	**Sample ID:**	Refer to table 1
Name of Analyst who Performed the Test:	Prepping Analyst: Elysse Nioupin (EN) Processing Analyst: Ayomide Odugbesi (AOD) Reading Analyst: Andrew Carrillo (ANC)	**Sample / Active Name**	Refer to table 1	**Lot #:**	Refer to table 1
		Dosage Form	Liquid		
Description of Incident:	On 30 Sep 2026 and 05 Oct 2026 samples ETX-260917-0497 and ETX-260917-0470 were found positive for viable microorganisms after USP <71> sterility testing respectively.	☑ Client Care notified of OOS ☑ Sterility and Endotoxin test related OOS; Client must be notified within 24 hours of OOS			
	SOP / Test Method #: MICRO-SOP-5	Effective Date: 24Jul2026	SOP / Test Method Rev: 19	Limits/Specification: Pass/Fail	
Manager notified	Manager/designee name: Kathan Parikh	Date: 30-Sep-2026	Quality Assurance Department notified:	Yes ☑ No ☐	

Section B – Investigation and Root Cause Analysis			
Personnel Discrepancy		**Comments**	
Analyst interviewed?	☑Yes ☐ No ☐ N/A	Yes, analysts Elysse Nioupin, Ayomide Odugbesi and Andrew Carrillo were comprehensively interviewed.	
Correct samples analyzed?	☑Yes ☐ No ☐ N/A	Yes, sample ID: ETX-260917-0497 and ETX-260917-0470	
Correct SOP / Test Method used/followed?	☑Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-5	
Correct sample collection/technique?	☑Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-5	
Are the Test Result Records Attached & Calculations Verified and Correct?	☑Yes ☐ No ☐ N/A	Yes, Information is available on Eagletrax under ETX-260917-0497 and ETX-260917-0470.	
Is the analyst qualified to perform the test?	☑Yes ☐ No ☐ N/A	Yes, the analysts are trained and qualified by quality to perform the test	
Is formula worksheet provided and verified?	☐Yes ☐ No ☑ N/A	Not Applicable	
Does the processing method/method set conform to the required specification?	☐Yes ☐ No ☑ N/A	Not Applicable	
Was the sample stored appropriately?	☑Yes ☐ No ☐ N/A	Yes, the sample was stored as per client's instructions. Information is available in EagleTrax Sample Location History under ETX-260917-0497 and ETX-260917-0470	
Material Discrepancy		**Lot Number**	**Expiry Date**
Is the integrity of the sample(s) questionable?	☐Yes ☑ No ☐N/A		
Was the sample transported appropriately?	☑Yes ☐ No ☐N/A		
Are the other test results from this run under investigation?	☑Yes ☐ No ☐N/A		

OOS Number: OOS- 262277

Appropriate/correct glassware used?	☐Yes ☐ No ☑N/A		
Are reagents stored in proper condition and not expired?	☑Yes ☐ No ☐N/A	Process Consumables: Information is available in EagleTrax Sample Consumables section Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly cleaning logs	Process Consumables: Information is available in EagleTrax Sample Consumables section Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly cleaning logs
Standard Used	Not applicable	Not applicable	Not applicable
Solvent Used	Not applicable	Not applicable	Not applicable
Is the standard the source of the root cause?	☐Yes ☐ No ☑N/A		
Has the analyst been instructed to keep the original test solution for possible retesting?	☐Yes ☐ No ☑N/A		
Equipment Discrepancy		**Equipment ID**	**Calibration Due Date**
Was the instrument set up correctly?	☑Yes ☐ No ☐ N/A	ISO 5 BSC E001314	Jun 2027
Is the clean room facility certified?	☑Yes ☐ No ☐ N/A	E001737 (CR115)	Dec 2026
System Performance Check (if applicable)?	☐Yes ☐ No ☑ N/A	Not applicable	Not applicable
System Suitability RSD < 2% (PDA)?	☐Yes ☐ No ☑ N/A	Not applicable	Not applicable
System Suitability RSD < 10% (QDA, CAD)?	☐Yes ☐ No ☑ N/A	Not applicable	Not applicable
Do the environmental monitoring results conform to required standards?	☑Yes ☐ No ☐ N/A	See Phase I Summary	See Phase I Summary
Do the controls (i.e., positive, negative, etc.) conform to the required standards?	☑Yes ☐ No ☐ N/A	See Phase I Summary	See Phase I Summary
Is equipment/instrument functional and calibrated/qualified/certified/PM?	☑Yes ☐ No ☐ N/A	Incubator E001356 (Monitored by Sensor E001450) Incubator E001357 (Monitored by Sensor E001449) Incubator E001034 (Monitored by Sensor E001501) Incubator E001031 (Monitored by Sensor E001505) ISO 5 BSC E001314	Jan 2027 Feb 2027 Jan 2027 Feb 2027 Aug 2027 Feb 2027 Aug 2027 Feb 2027 Jun 2027

OOS Number: OOS- 262277

Are chromatogram/spectra/raw data correct?	☐ Yes ☐ No ☑ N/A	Not applicable	Not applicable

Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)

- ☑ N/A
- ☐ Re-injection of sample vial
- ☐ Re-injection of original standard vial
- ☐ Re-vialing of original working standard solution
- ☐ Re-vialing of original working sample solution
- ☐ Re-dilution of a working sample solution from the original stock
- ☐ Re-dilution of a working standard solution from the original stock standard
- ☐ Other: N/A DK 08Oct2026

Section D – Phase I Summary

Phase I Summary:

All analysts involved in the prepping, processing, and reading of the sample – Elysse Nioupin, Ayomide Odugbesi, and Andrew Carrillo were interviewed comprehensively. Their answers are recorded throughout this document. This investigation was performed as per MICRO-SOP-53 Sterility Test Out-of-Specification (OOS) Investigation Procedure.

Upon arrival, samples were stored in accordance with the Client's instructions. Analysts - Elysse Nioupin and Ayomide Odugbesi - verified the integrity of the samples throughout both the preparation and processing stages. No leaks or turbidity were observed at any point, verifying the integrity of samples.

All reagents and supplies mentioned in the material section above were stored according to the suppliers' recommendations, and their integrity was visually verified before utilization. Moreover, all reagents and supplies had valid expiration dates. The functionality of all equipment was confirmed by reviewing data generated by our comprehensive in-house continuous monitoring system.

The cleanroom suite (CR115) used for processing procedures comprises three interconnected sections: the innermost ISO 7 cleanroom (115B), which connects to the middle ISO 7 buffer room (115A), and then to the outermost ISO 8 anteroom (115). A positive air pressure system is maintained throughout the suite to ensure controlled, unidirectional airflow from 115B through 115A and into 115.

The ISO 5 BSC E001314, located in the innermost ISO 7 room, (115B), was used for sample processing steps. It was thoroughly cleaned and disinfected prior to each procedure in accordance with MICRO SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). Additionally, BSC E001314 was certified and approved by both the Engineering and Quality Assurance teams. Sample processing was conducted in the ISO 5 BSC E001314 in the innermost ISO 7 room, (115B) by Ayomide Odugbesi on 25 Sep 2026 as per MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test).

On 25 Sep 2026, the sample vials for ETX-260917-0497 and ETX- 260917-0470 were received from the Sample Submissions team and brought into the Sterile Microbiology lab. Upon arrival, each sample vial was sprayed with an acidified bleach disinfectant, placed into pre-disinfected bins, and allowed a 10-minute contact time. Once fully disinfected, the vials were transferred into the ISO 5 BSC E001314.

OOS Number: OOS- 262277

Phase I Summary (continued):

Inside the BSC, each container was aseptically opened, ensuring minimal exposure to the environment. The contents were then dispensed directly from the container into sterile canisters placed on a vacuum manifold for membrane filtration. The samples were processed and tested as per MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test). Media bottles were transferred into incubators E001356 and E001357 to begin incubation.

Sterility testing for ETX-260917-0497 and ETX-260917-0470 was initiated on 25 Sep 2026. On 30 Sep 2026 (Day 5 of incubation), microbial growth was observed in one TSB (Tryptic Soy Broth) media bottle for ETX-260917-0497, and on 05 Oct 2026 (Day 10 of incubation), microbial growth was observed in one FTM (Fluid Thioglycollate Medium) media bottle for ETX-260917-0470 by analyst, Andrew Carrillo, and confirmed by Microbiology Lab Supervisor, Robin Seymour. The positive TSB bottle for ETX-260917-0497 and the positive FTM bottle for ETX-260917-0470 were submitted for Differential Staining and Microbial Identification under ETX-260930-0382 and ETX-261005-0636, respectively. Differential staining indicated the presence of Gram-positive rods and Gram-positive short rods, respectively. Definitive identification identified the isolates as Cutibacterium acnes (Gram (+) short rods) for ETX-260917-0470 and Bacillus altitudinis and Bacillus pumilus (Gram (+) rods) for ETX-260917-0497.

Upon analyzing the environmental monitoring results, no microbial growth was detected on personnel monitoring plates on the date of testing (25 Sep 2026), the preceding testing date (24 Sep 2026), or the subsequent testing date (28 Sep 2026). No microbial growth was detected on settling plates or ISO 5 BSC surface sampling plates on the date of testing (25 Sep 2026), the preceding testing date (24 Sep 2026), or the subsequent testing date (28 Sep 2026). Additionally, no microbial growth was recovered from the weekly surface sampling of anteroom, buffer room and cleanroom plates collected on 23 Sep 2026. The weekly active air sampling collected on 23 Sep 2026 recovered 6 CFUs of Gram (+) cocci from the ISO 8 area (ETX-261001-0625), identified as Micrococcus luteus, Kocuria indica and Kocuria rhizophila/sp. BT304.

The Gram (+) cocci recovered from the weekly active air sampling of the ISO 8 anteroom (115) are morphologically different from the Gram (+) rods and Gram (+) short rods recovered in the test samples. The absence of contamination on work-surface environmental monitoring plates collected on the date of testing indicates that there was no viable transfer of contaminants from ISO 8 environment to the ISO 5 biological safety cabinet (BSC). Additionally, the lack of contamination in other than the two samples under investigation processed during the same testing session further demonstrates that the testing environment was operating in optimal condition.

Therefore, based on the absence of microbial recovery from ISO 5 critical-area monitoring and personnel monitoring, the lack of microbiological correlation between organisms recovered from environmental monitoring and the isolates recovered from the test samples, and the absence of growth on weekly surface monitoring plates from Cleanroom Suite CR115, the cleanroom environment is not considered a credible source of the Bacillus altitudinis, Bacillus pumilus and Cutibacterium acnes recovered from the test samples.

The analysts confirmed full compliance with cleaning procedures as outlined in MICRO SOP-9 (Cleaning and Disinfecting Procedure for Microbiology) and MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test).

Monthly cleaning and disinfection of the outermost ISO 8 Anteroom, the middle ISO 7 Buffer room, the innermost ISO 7 cleanroom, and its containing ISO 5 BSCs for Cleanroom suite CR115 was performed on 13 Sep 2026, as per MICRO-SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). During both cleaning cycles, it was documented that all H_2O_2 indicators passed. This confirms the efficient monthly cleaning of all three parts of Cleanroom suite CR115.

To assess the potential for sample-to-sample contamination contributing to the positive results, a comprehensive review was conducted of all samples processed on the same day (25 Sep 2026). Two samples, ETX-260917-0497 and ETX-260917-0470, tested positive; both were submitted by the same client and contain the same analyte (Semaglutide) at different concentrations (0.88 mg/0.5 mL and 5.34 mg/0.5 mL). All other samples processed by the analyst and other analysts that day tested negative. Additionally, the organisms recovered from the two positive samples were different (Bacillus altitudinis and Bacillus pumilus in TSB for ETX-260917-0497; Cutibacterium acnes in FTM for ETX-260917-0470), so there is no microbiological correlation between them. These findings suggest that cross-contamination between samples is highly unlikely.

A review of the 6-month sample history for Blue Door Pharmacies 71015 (E71015) found one prior sterility failures for USP <71> / EP 2.6.1 sterlity testing. The microbial growth from the previous failing sample (ETX-260909-0269, OOS-262191) was identified to be Bacillus circulans. No laboratory errors were determined to be contributing to the failing result of ETX-260909-0269.

Based on the observations outlined above, it is unlikely that the failing results were due to reagents, supplies, the cleanroom environment, the process, or analyst involvement. Consequently, the possibility of laboratory error contributing to this failure is minimal and the original result is deemed to be valid.

OOS Number: OOS- 262277

Phase I Summary (continued):

N/A DK08Oct2026

OOS Number: OOS- 262277

Has root cause been identified as a possible laboratory error?
Note: Root cause must be conclusive, verifiable, and well-documented.

☐ Yes
- ☐ If retesting is ***required***, complete Phase II of the OOS (initiate Form 3.100.019.F02).

☑ No, the OOS result is valid.

Reviewer comment(s):

Prepared by (*Print*)**:**	Signature/Date:
Dhvanir Kansara	Dhvanir Kansara Digitally signed by Dhvanir Kansara DN: CN=Dhvanir Kansara, O=Eagle Analytical Services, OU=Project Microbiologist - Microbiology, E=dkansara@eagleanalytical.com Reason: I am the author of this document Location: Date: 2026.10.28 18:31:12-05'00' Foxit PDF Editor Version: 14.0.8
Lab Manager/Designee (*Print*)**:**	Signature/Date:
Robin Seymour	

Section E – Quality Disposition

Can investigation be closed?

☐ Yes
- ☐ Original result is valid.

☐ No, initiate Form 3.100.019.F02.

Approved by QA Representative (*Print*)**:**	Signature/Date:

Table 1: Samples under investigation OOS-262277

Sample ID	Sample Name	Lot #	Dosage Form
ETX-260917-0497	Semaglutide 0.88mg/0.5ml	LG402000387	Liquid
ETX-260917-0470	Semaglutide 5.34mg/0.5ml	LG402000388	Liquid

Table 2: Information for samples under investigation OOS-262277

Reading Analyst	Day of Incubation	Sample ID	Related Microbial ID	Media with microbial growth	Microbial Identification
Andrew Carrillo	05	ETX-260917-0497	ETX-260930-0382	1 x 100mL TSB	*Bacillus altitudinis* *Bacillus pumilus* Gram (+) rods
Andrew Carrillo	10	ETX-260917-0470	ETX-261005-0636	1 x 100mL FTM	*Cutibacterium acnes* Gram (+) short rods

Table 3: Environmental Monitoring for Analyst & Cleanroom

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMM YYYY)	Analyst (Initials)	Day /Week(s)	Observation	Environmental Monitoring Plate ETX ID	Microbial ID	Notes
Personnel EM Bracketing 25Sep2026								
Personnel (Left and Right- Hand Touch)	Daily	24 Sep 2026	AOD	Date Before Testing	No growth	N/A	N/A	None
Personnel (Left and Right- Hand Touch)	Daily	25 Sep 2026	AOD	Date of Testing	No growth	N/A	N/A	None
Personnel (Left and Right- Hand Touch)	Daily	28 Sep 2026	AOD	Date After Testing	No growth	N/A	N/A	None
Biological Safety Cabinet EM Bracketing Biological Safety Cabinet (BSC) E001314								
Surface Sampling of ISO 5 (4 locations)	Daily	24 Sep 2026	AOD	Date Before Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	25 Sep 2026	AOD	Date of Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	28 Sep 2026	AOD	Date After Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	24 Sep 2026	AOD	Date Before Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	25 Sep 2026	AOD	Date of Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	28 Sep 2026	AOD	Date After Testing	No growth	N/A	N/A	None
Weekly Active Air Sampling for CR 115 (E001737)								
Active Air Sampling of Cleanrooms	Weekly	23 Sep 2026	SMO	Week of Testing	6 CFU (ISO8)	ETX-261001-0625	*Micrococcus luteus* *Kocuria indica* *Kocuria rhizophila/ sp. BT304* Gram (+) cocci	None
Surface Sampling of Anteroom, Buffer room and Cleanroom for CR 115 (E001737)								
Surface Sampling of Cleanrooms	Weekly	23 Sep 2026	SMO	Week of Testing	No growth	N/A	N/A	None