OOS Number: OOS- 262237

Phase I

Section A – Test Details					
Initiator:	Muralidhar Bythatagari (Written by: Qiyue C	**Test Date:**	24-Sep-2026	**Date Initiated:**	24-Sep-2026
Date of Incident:	24-Sep-2026	**Test Name:**	Scan RDI Sterility Test	**Sample ID:**	ETX-260921-0148
Name of Analyst who Performed the Test:	Prepping Analyst: Elysse Nioupin (EN) Processing Analyst: Guanchen Li (GL) Changeover Analyst: Muralidhar Bythatagari (MRB) Reading Analyst: Muralidhar Bythatagari (MRB)	**Sample / Active Name** **Dosage Form**	Semaglutide R 2.5mg/ml Benzyl Alcohol 0.9% Injectable	**Lot #:**	20066
Description of Incident:	On 24Sep26, sample ETX-260921-0148 was found positive for viable microorganisms after Scan RDI sterility testing.	☑ Client Care notified of OOS ☑ Sterility and Endotoxin test related OOS; Client must be notified within 24 hours of OOS			
	SOP / Test Method # MICRO-SOP-12 (16) ENG-SOP-4 (05)	Effective Date: 24Jul26 24Jul26	SOP / Test Method Rev: Rev: 16 Rev: 05	Limits/Specification: <1 event	
Manager notified	Manager/designee name: Kathan Parikh	Date: 24-Sep-2026	Quality Assurance Department notified:	Yes ☑ No ☐	

Section B – Investigation and Root Cause Analysis			
Personnel Discrepancy		**Comments**	
Analyst interviewed?	☑Yes ☐ No ☐ N/A	Yes, analysts Elysse Nioupin, Guanchen Li, and Muralidhar Bythatagari were interviewed comprehensively.	
Correct samples analyzed?	☑Yes ☐ No ☐ N/A	Yes, ETX-260921-0148	
Correct SOP / Test Method used/followed?	☑Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-12, ENG-SOP-4	
Correct sample collection/technique?	☑Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-12, ENG-SOP-4	
Are the Test Result Records Attached & Calculations Verified and Correct?	☑Yes ☐ No ☐ N/A	Yes, See 092426-2132-3 for more information.	
Is the analyst qualified to perform the test?	☑Yes ☐ No ☐ N/A	Yes, all analysts are trained and qualified by quality to perform the test.	
Is formula worksheet provided and verified?	☐Yes ☐ No ☑ N/A	Not Applicable	
Does the processing method/method set conform to the required specification?	☐Yes ☐ No ☑ N/A	Not Applicable	
Was the sample stored appropriately?	☑Yes ☐ No ☐ N/A	Yes, Information is available in Eagle Trax Sample Location History under ETX-260921-0148	
Material Discrepancy		**Lot Number**	**Expiry Date**
Is the integrity of the sample(s) questionable?	☐Yes ☑ No ☐N/A		
Was the sample transported appropriately?	☑Yes ☐ No ☐N/A		
Are the other test results from this run under investigation?	☐Yes ☑ No ☐N/A		

OOS Number: OOS- 262237

Appropriate/correct glassware used?	☐Yes ☐No ☑N/A		
Are reagents stored in proper condition and not expired?	☑Yes ☐No ☐N/A	Scan Consumables: See the attached data packet Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly	Scan Consumables: See the attached data packet Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly
Standard Used	C. albicans	06122026-10231-CA	11Jun28
Solvent Used	Not Applicable	Not Applicable	Not Applicable
Is the standard the source of the root cause?	☐Yes ☐No ☑N/A		
Has the analyst been instructed to keep the original test solution for possible retesting?	☐Yes ☐No ☑N/A		
Equipment Discrepancy		**Equipment ID**	**Calibration Due Date**
Was the instrument set up correctly?	☑Yes ☐No ☐N/A	E002132	Oct 2026
Is the clean room facility certified?	☑Yes ☐No ☐N/A	E001738 (CR116) E001978 (CR144)	Dec 2026 Dec 2026
System Performance Check (if applicable)?	☑Yes ☐No ☐N/A	E002132	Oct 2026
System Suitability RSD < 2% (PDA)?	☐Yes ☐No ☑N/A	Not Applicable	Not Applicable
System Suitability RSD < 10% (QDA, CAD)?	☐Yes ☐No ☑N/A	Not Applicable	Not Applicable
Do the environmental monitoring results conform to required standards?	☑Yes ☐No ☐N/A	See Phase I Summary	See Phase I Summary
Do the controls (i.e., positive, negative, etc.) conform to the required standards?	☑Yes ☐No ☐N/A	See Phase I Summary	See Phase I Summary
Is equipment/instrument functional and calibrated/qualified/certified/PM?	☑Yes ☐No ☐N/A	Incubator E001034 (Sensor E001501) Incubator E001031 (Sensor E001505) BSC E001312 BSC E001937	Aug 2027 Feb 2027 Aug 2027 Feb 2027 Jun 2027 Jul 2027

OOS Number: OOS- 262237

Are chromatogram/spectra/raw data correct?	☐ Yes ☐ No ☑ N/A	Not Applicable	Not Applicable

Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)

- ☑ N/A
- ☐ Re-injection of sample vial
- ☐ Re-injection of original standard vial
- ☐ Re-vialing of original working standard solution
- ☐ Re-vialing of original working sample solution
- ☐ Re-dilution of a working sample solution from the original stock
- ☐ Re-dilution of a working standard solution from the original stock standard
- ☐ Other: N/A QYC 13Oct2026

Section D – Phase I Summary

Phase I Summary:

All analysts involved in the preparation, processing, changeover, and reading of the sample – Elysse Nioupin, Guanchen Li, and Muralidhar Bythatagari – were interviewed comprehensively. Their responses are documented throughout this report. This investigation was performed in accordance with MICRO-SOP-53, Sterility Test Out-of-Specification Investigation Procedure.

Upon arrival, the sample was stored refrigerated in accordance with the Client's instructions. Prepping analyst - Elysse Nioupin - and processing analyst - Guanchen Li - verified the physical integrity and packaging of the sample throughout both the preparation and processing stages. No leaks, cracks, or visible turbidity were observed prior to testing, verifying container integrity.

All reagents and supplies mentioned in the material section above were stored according to suppliers' recommendations, and their integrity was visually verified before utilization. Moreover, each reagent, media, and consumable possessed valid expiration dates. The functionality of all equipment was confirmed by reviewing continuous environmental and operational monitoring data.

During the preparation phase, Elysse Nioupin disinfected the sample containers using acidified bleach and placed them into a pre-disinfected storage bin. On 24Sep26, prior to sample processing, Guanchen Li performed a second disinfection with acidified bleach, allowing a minimum contact time of 10 minutes before transferring the samples into the cleanroom suites. A final disinfection step was completed immediately before introducing the sample into the ISO 5 Biological Safety Cabinet (BSC E001312) located in the innermost ISO 7 cleanroom (116B). All activities were performed in accordance with MICRO-SOP-12, Rapid Scan RDI® Test using FIFU Method.

Cleanroom suite 116, used for sample processing, comprises the innermost ISO 7 cleanroom 116B, middle ISO 7 buffer room 116A, and outermost ISO 8 anteroom 116. Cleanroom L-Suite, used for changeover, consists of ISO 7 cleanroom 145, ISO 7 buffer room 144, ISO 8 anteroom 143, and outermost ISO 8 room 142. Outward-cascading positive air pressure differentials are continuously maintained across both suites to ensure controlled unidirectional airflow.

The ISO 5 BSC E001312 located in Cleanroom 116B and ISO 5 BSC E001937 located in Cleanroom 144 were thoroughly cleaned and disinfected prior to their respective procedures in accordance with MICRO-SOP-9, Cleaning and Disinfecting Procedure for Microbiology. Both BSCs were certified and approved by the Engineering and Quality Assurance teams prior to testing.

Pre-labeling and filtration activities were performed by Guanchen Li on 24Sep26 within the ISO 5 biosafety cabinet (BSC E001312) located in the innermost ISO 7 cleanroom (116B). The changeover procedure was subsequently performed by analyst Muralidhar Bythatagari on the same date within the ISO 5 biosafety cabinet (BSC E001937) located in Cleanroom L-Suite. The reading analyst, Muralidhar Bythatagari, confirmed that the ScanRDI instrument E002132 was set up as per ENG-SOP-4 (Scan RDI® System – Operations (Standard C3 Quality Check and Microscope Setup and Maintenance)), and the negative control and positive control for analyst Guanchen Li yielded expected results.

OOS Number: OOS- 262237

Phase I Summary (continued):

Environmental Monitoring (EM) Recoveries Review:

ISO 5 BSC and Personnel Evaluation:
Upon review of the environmental monitoring data, absence of microbial recovery (No Growth) was demonstrated across all critical ISO 5 zones and personnel monitoring on the date of testing. Daily personnel monitoring for processing analyst Guanchen Li and changeover analyst Muralidhar Bythatagari yielded no microbial growth on left and right fingertip touch plates. Daily surface sampling (4 locations) and settling plates within processing BSC E001312 and changeover BSC E001937 yielded no microbial growth.

Cleanroom EM Evaluation:
Weekly surface monitoring of Cleanroom Suite 116 conducted on 24Sep26 and Cleanroom L-Suite conducted on 22Sep26 demonstrated no microbial recovery across all sampled cleanroom surfaces, confirming effective sanitization and surface control.

Weekly active air monitoring of Cleanroom Suite 116 conducted on 24Sep26 demonstrated no microbial recovery in the ISO 7 cleanrooms; however, 3 CFUs under test sample ETX-261005-0773 were recovered from the ISO 8 anteroom (116), identified as Gram-positive cocci. Weekly active air monitoring of Cleanroom L-Suite conducted on 22Sep26 demonstrated no microbial recovery in the ISO 7 cleanrooms (145 and 144); however, 6 CFUs under test sample ETX-260929-0335 (identified as five Gram-positive cocci and one Gram-negative coccobacilli) and 8 CFUs under test sample ETX-260929-0341 (identified as six Gram-positive cocci and two Gram-positive short rods) were recovered from the ISO 8 anteroom (143 Section I and Section II, respectively), and 2 CFUs under test sample ETX-260929-0344 were recovered from the outermost ISO 8 room (142), identified as two Gram-positive cocci. The recovered organisms are common environmental isolates with morphology distinctly different from the curved rod-shaped morphology observed in the failing test sample.

It is important to emphasize that all sample processing activities were performed strictly within the validated ISO 5 BSC E001312 located in the innermost ISO 7 cleanroom (116B), and changeover activities were performed within ISO 5 BSC E001937 located in the ISO 7 cleanroom of L-Suite. There is minimal exposure of the test sample to ambient ISO 8 air, as samples and supplies are transferred in disinfected, closed containers on carts through the layered cleanroom suites. Furthermore, the recoveries occurred in the lower-classified ISO 8 anteroom and outer room environments, which are physically segregated from the ISO 5 processing zone by closed doors and an outward-cascading positive air pressure gradient. In conjunction with the complete absence of microbial growth on all analyst glove touch plates, settling plates, and ISO 5 BSC work surfaces throughout testing, there is no plausible contamination transfer pathway from the ambient ISO 8 environment to the test sample.

Monthly cleaning and disinfection of the cleanrooms (ISO 7) and their containing biosafety cabinets (ISO 5) were performed on the 16 Aug 26 for CR116 and 30Aug26 for L-suite, as per MICRO-SOP-9, Cleaning and Disinfecting Procedure for Microbiology. It was documented that all chemical indicators passed, verifying that environmental sanitization remained validated and in control prior to testing.

Analyzing a 6-month sample history for GoGoMeds Select (E10747), this specific analyte "Semaglutide R 2.5mg/ml Benzyl Alcohol 0.9%" has had one prior failure, documented under OOS-262106 for submission ETX-260908-0694, tested on 10Sep26. The microorganism detected in the previous investigation exhibited clustered circular-shaped morphology, which differs from the curved rod-shaped morphology observed in the current investigation. The previous failure investigation was reviewed and no laboratory error or assignable laboratory cause was identified.

All samples processed on the same day were also evaluated for evidence of sample-to-sample cross-contamination. The test sample ETX-260921-0148 was the 27th sample processed by Guanchen Li on 24Sep26. All other samples processed by the same analyst, as well as samples processed by other laboratory personnel on the date of testing, yielded negative results. Analyst Guanchen Li verified that gloves were disinfected between samples and standard aseptic techniques were strictly maintained. The absence of additional positive samples or clustering patterns provides further evidence against cross-contamination.

Based on the laboratory investigation, no assignable laboratory cause was identified involving the analyst, instrument, reagents, supplies, or monitored laboratory environment. Therefore, the likelihood of laboratory error contributing to this failure is considered minimal, and the original result is deemed valid.

OOS Number: OOS- 262237

Phase I Summary (continued):

N/A QYC 13Oct26

OOS Number: OOS- 262237

Has root cause been identified as a possible laboratory error?
Note: Root cause must be conclusive, verifiable, and well-documented.

☐ Yes

☐ If retesting is ***required***, complete Phase II of the OOS (initiate Form 3.100.019.F02).

☑ No, the OOS result is valid.

Reviewer comment(s):

Prepared by (*Print*)**:**	Signature/Date:
Qiyue Chen	SIGN
Lab Manager/Designee (*Print*)**:**	Signature/Date: SIGN

Section E – Quality Disposition

Can investigation be closed?

☐ Yes

☐ Original result is valid.

☐ No, initiate Form 3.100.019.F02.

Approved by QA Representative (*Print*)**:**	Signature/Date: SIGN

Table 1: Information for ETX-260921-0148 under investigation

Processing Analyst	Reading Analyst	Sample ID	Events	Confirmed Microbial Events	Morphology Description
Guanchen Li	Muralidhar Bythatagari	ETX-260921-0148	362	90	***Curved rod-shaped morphology***

Table 2: Environmental Monitoring from Testing Performed on 24Sep26

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMMYY)	Analyst	Day /Week(s)	Observation	EM Plate ETX Number	Microbial ID	Notes
Personnel EM								
Personal (Left Touch and Right Touch)	Daily	24Sep26	GL	Date of Testing (Scan)	No Growth	Not Applicable	Not Applicable	None
Personal (Left Touch and Right Touch)	Daily	24Sep26	MRB	Date of Testing (Scan C/O)	No Growth	Not Applicable	Not Applicable	None
Biological Safety Cabinet EM for E001312 and E001937								
Surface Sampling of ISO 5 BSC E001312 (4 Locations)	Daily	24Sep26	GL	Date of Testing (Scan)	No Growth	Not Applicable	Not Applicable	None
Surface Sampling of ISO 5 BSC E001937 (4 Locations)	Daily	24Sep26	MRB	Date of Testing (Scan C/O)	No Growth	Not Applicable	Not Applicable	None
Settling Sampling of ISO 5 BSC E001312	Daily	24Sep26	GL	Date of Testing (Scan)	No Growth	Not Applicable	Not Applicable	None
Settling Sampling of ISO 5 BSC E001937	Daily	24Sep26	MRB	Date of Testing (Scan C/O)	No Growth	Not Applicable	Not Applicable	None
Weekly Active Air Sampling of Cleanroom Suite 116 (E001738) with Processing BSC								
Active Air Sampling of Cleanrooms	Weekly	24Sep26	SMO	Week of Testing	3 CFUs (116 ISO8)	ETX-261005-0773	Gram (+) cocci	None
Weekly Active Air Sampling of Cleanroom 145, 144, 143, 142 (L-Suite) with Changeover BSC								
Active Air Sampling of Cleanrooms	Weekly	22Sep26	SMO	Week of Testing	6 CFUs (ISO 8 143 Sec I) 8 CFUs (ISO 8 143 Sec II) 2 CFUs (ISO 8 142)	ETX-260929-0335 ETX-260929-0341 ETX-260929-0344	Gram (+) cocci Gram (-) coccobacilli Gram (+) cocci Gram (+) short rods Gram (+) cocci	None
Weekly Surface Sampling of Cleanroom Suite 116 (E001738) with Processing BSC								
Surface Sampling of Cleanrooms	Weekly	24Sep26	SMO	Week of Testing	No Growth	Not Applicable	Not Applicable	None
Weekly Surface Sampling of Cleanroom 145, 144, 143, 142 (L-Suite) with Changeover BSC								
Surface Sampling of Cleanrooms	Weekly	22Sep26	SMO	Week of Testing	No Growth	Not Applicable	Not Applicable	None