OOS Number: OOS- 262329

Phase II

Section A – Sample Detail					
Sample Name:	Sermorelin 0.9mg/ml	**Re-Test Date:**	21-Oct-2026	**Original Result:**	Fail
Name of Analyst who Performed Re-Test:	Prepping: Elysse Nioupin (EN) Processing: Ayomide Odugbesi (AOD) Reading: Andrew Carrillo (ANC)	**Sample ID:**	Original: ETX-260624-0251 (BUD-T90) Retest: ETX-261021-0445	**Re-Test Result:**	Pass

Section B – Investigation and Root Cause				
Investigation	Is the test conducted in accordance with the same method /process?	☑ Yes ☐ No	SOP#: MICRO-SOP-5	If the answer is NO to any of the investigation item(s), mark the item(s) with sequential number starting with one (1) and comment here: Not Applicable
	Is reagents (reference standards, solvent, etc.) stored in proper condition and not expired?	☑ Yes ☐ No	Lot #: TSB: Please see Consumables section under the submission on EagleTrax FTM: Please see Consumables section under the submission on EagleTrax	
			Exp. Date: TSB: Please see Consumables section under the submission on EagleTrax FTM: Please see Consumables section under the submission on EagleTrax	
	Equipment/Instruments Used:	Are they functional and calibrated/PM?	Calibration / PM due date	
	ISO 5 BSC E001314	☑ Yes ☐ No	Jun 2027	
	CR 115 (E001737)	☑ Yes ☐ No	Dec 2026	
	Incubator E001356 (Sensor E001450)	☑ Yes ☐ No	Jan 2027, Feb 2027	
	Incubator E001357 (Sensor E001449)	☑ Yes ☐ No	Jan 2027, Feb 2027	
	Not Applicable	☑ Yes ☐ No	Not Applicable	
	Is the clean room facility certified?	☑ Yes ☐ No ☐ N/A	Certified due date: 31-Dec-2026	
	Do the controls (i.e. positive, negative, C3, etc.,) conform to the required standards?	☑ Yes ☐ No ☐ N/A	See Phase II Summary	
	Do the environmental monitoring results conform to required standards?	☑ Yes ☐ No ☐ N/A	SOP#: See Phase II Summary	
	System Performance Check (if applicable)	☐ Yes ☐ No ☑ N/A		
	System Suitability RSD < 2% (PDA)	☐ Yes ☐ No ☑ N/A		
	System Suitability RSD <10 % (QDA,CAD)	☐ Yes ☐ No ☑ N/A		

OOS Number: OOS- 262329

	Is the analyst trained to perform the test?	☑ Yes ☐ No	
	Are the Test Result Records Attached & Calculations Verified and Correct?	☑ Yes ☐ No	
	Does the processing method/ method set conform to the required specification?	☑ Yes ☐ No	
	Re-Testing from the same vial?	☐ Yes ☑ No ☐ N/A	
	Is formula worksheet provided and verified?	☑ Yes ☐ No	

Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)

- ☐ N/A
- ☐ Re-injection of sample vial
- ☐ Re-injection of original standard vial
- ☐ Re-vialing of original working standard solution
- ☐ Re-vialing of original working sample solution
- ☐ Re-dilution of a working sample solution from the original stock
- ☐ Re-dilution of a working standard solution from the original stock standard
- ☑ Other: Retest of additional sample vials from same

Section D – Phase II Summary

All analysts involved in the initial testing and Phase II retesting - initial prepping analyst Elysse Nioupin, initial processing analyst Guanchen Li, subculture analyst Ayomide Odugbesi, initial reading analyst Andrew Carrillo, retest processing analyst Ayomide Odugbesi, and retest reading analyst Andrew Carrillo - were interviewed comprehensively. Their responses are documented throughout this report. This investigation was performed in accordance with MICRO-SOP-53, Sterility Test Out-of-Specification Investigation Procedure.

INITIAL TEST UNDER SUBMISSION ETX-260624-0251 (BUD-T90):
Upon arrival on 24Jun26, the sample was stored refrigerated in accordance with the client's instructions as part of a beyond-use date study (BUD-T90). Prepping analyst Elysse Nioupin and processing analyst Guanchen Li verified the physical integrity and packaging of the sample throughout the preparation and processing stages. No leaks, cracks, or visible turbidity were observed, verifying container closure integrity prior to testing.

All reagents and supplies mentioned in the material section above were stored according to supplier recommendations, and their integrity was visually verified before utilization. Moreover, all reagents, culture media, and consumables had valid expiration dates. The functionality of all equipment was confirmed by reviewing data generated by our comprehensive in-house continuous monitoring system.

The cleanroom suite (CR 115) used for processing procedures comprises three interconnected sections: the innermost ISO 7 cleanroom (115B), which connects to the middle ISO 7 buffer room (115A), and then to the outermost ISO 8 anteroom (115). Outward-cascading positive air pressure differentials are continuously maintained across the suite to ensure controlled, unidirectional airflow from 115B through 115A and into 115.

The ISO 5 Biological Safety Cabinet (BSC) E001314, located in innermost ISO 7 room 115B, was used for sample processing steps. It was thoroughly cleaned and disinfected prior to each procedure in accordance with MICRO-SOP-2 (Environmental Monitoring of the Clean-room Facility) and MICRO-SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). Additionally, BSC E001314 was certified and approved by Engineering and Quality Assurance.

On 22Sep26, sample prep was performed by Elysse Nioupin. On 23Sep26, sample vials for ETX-260624-0251 (BUD-T90) were retrieved from controlled refrigerated storage and brought into the sterile microbiology suite. Sample container surfaces were sprayed with acidified bleach disinfectant, placed into pre-disinfected transfer bins, and allowed a verified 10-minute contact time. Secondary disinfection with acidified bleach was performed in the ISO 8 anteroom (115) with an additional 10-minute contact time. Inside innermost ISO 7 cleanroom 115B, processing analyst Guanchen Li performed a final disinfection step before transferring the containers into the ISO 5 BSC E001314.

Inside BSC E001314, containers were aseptically accessed with minimal exposure to the ISO 5 environment. Testing was executed by direct inoculation in strict accordance with approved method suitability ETX-260401-0599 and MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test). Specifically, 15 mL of sterile Tween 80 and 5 mL of sample were directly inoculated into 200 mL media bottles of Tryptic Soy Broth and Fluid Thioglycollate Medium. Matching direct inoculation negative control bottles were prepared concurrently and manipulated identically. The inoculated media bottles were transferred into calibrated incubators E001356 (20-25 °C) and E001357 (30-35 °C) to commence incubation.

OOS Number: OOS- 262329

Phase II Summary (continued):

On 08Oct26 (Day 14 read), initial test results were recorded as Inconclusive due to formulation-induced turbidity inherent to the concentrated Sermorelin sample matrix. In accordance with USP <71> and laboratory procedure for turbid samples, aliquots were aseptically subcultured into fresh media bottles on 07Oct26 by analyst Ayomide Odugbesi and returned to incubation.

On 12Oct26 (Day 18 of original bottles and Day 5 of subculture aliquots), microbial growth was observed and confirmed in both original TSB bottle and subcultured TSB bottle (2 x 200mL TSB, Original and Subculture Bottles) by reading analyst Andrew Carrillo and verified by laboratory supervisor. The FTM media bottles (original and subculture) remained clear and negative (No Growth) throughout incubation. Positive TSB bottles were submitted for Differential Staining and Microbial Identification under submission ETX-261012-0367. Differential staining indicated Gram-positive rods. Definitive identification confirmed the isolate as Bacillus megaterium, as detailed in Table 1.

All culture media and consumables utilized were within their valid manufacturer expiration dates. Negative control media bottles for direct inoculation were manipulated and incubated alongside the test samples under identical conditions; both TSB and FTM negative controls demonstrated complete absence of microbial growth (No Growth), verifying media sterility and aseptic technique.

Attached Table 2 details the environmental monitoring data associated with sample processing on 23Sep26. Environmental monitoring plates were incubated in accordance with MICRO-SOP-2, Environmental Monitoring of the Clean-room Facility. Review of contemporaneous personnel monitoring (left- and right-hand touch plates for analyst Guanchen Li) and ISO 5 BSC E001314 monitoring (surface contact plates and settling plates) demonstrated No Growth across all sampling locations on the date of testing (23Sep26), the date before testing (22Sep26), and the date after testing (24Sep26). These data confirm that processing personnel and the ISO 5 BSC were maintained in an optimal state of microbiological control and were not a source of contamination.

Routine weekly surface sampling of Cleanroom Suite 115 performed on 23Sep26 demonstrated No Growth. Weekly active-air sampling of the outermost ISO 8 Room 115 recovered 6 CFUs (ETX-261001-0625). Microbial identification confirmed these isolates as Micrococcus luteus, Kocuria indica, Kocuria rhizophila, and one pending fungal isolate (Pending FunITS, exhibiting hyphae morphology). Crucially, all recovered environmental isolates were Gram-positive cocci or fungal hyphae, different from the Gram-positive spore-forming rod (Bacillus megaterium) detected in the positive test sample, with zero Bacillus species recovered in the cleanroom environment. Furthermore, outermost Room 115 functions as an ISO 8 anteroom physically separated from innermost cleanroom 115B and the ISO 5 processing zone by cascaded airlocks and positive pressure differentials. The complete absence of microbial recovery across all critical ISO 7 rooms (115A and 115B), personnel gloves, and ISO 5 BSC surfaces confirms that room air contaminants did not enter the ISO 5 critical work area.

Monthly cleaning and disinfection of the cleanrooms (ISO 7) and their containing biosafety cabinets (ISO 5) were performed on 13Sep26 for Suite 115, as per MICRO-SOP-9, Cleaning and Disinfecting Procedure for Microbiology. It was documented that all chemical indicators passed, which confirmed the efficient monthly cleaning of all cleanrooms in Suite 115.

Analyzing a 6-month sample history for GoGoMeds Select (E10747), this specific analyte "Sermorelin 0.9mg/ml" has had no prior Out-of-Specification (OOS) occurrences under USP <71> sterility testing.

To assess the potential for sample-to-sample contamination contributing to the positive results, a comprehensive review was conducted of all samples processed on the same day. All other samples processed by the analyst that day tested negative. These findings suggest that cross-contamination between samples is highly unlikely. Consequently, the Phase I laboratory investigation did not identify any assignable laboratory cause contributing to the initial failure, and the original result is considered valid.

OOS Number: OOS- 262329

Phase II Summary (continued):

PHASE II RETEST UNDER SUBMISSION ETX-261021-0445:
In accordance with Phase II investigation procedures under CORP-FORM-22 and follow-up communications regarding the BUD-T90 stability study, the client requested a retest of additional vials from Lot 17009. An associated Phase II retest was initiated under submission ETX-261021-0445 to assess the sterility status of the remaining stability sample vials.

The retest sample was prepared on 20Oct26 by prepping analyst Elysse Nioupin and processed on 21Oct26 by processing analyst Ayomide Odugbesi in accordance with MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test). Testing was performed by direct inoculation inside certified ISO 5 BSC E001314 within Cleanroom Suite 115 following standard multi-barrier sanitization and strict aseptic technique. Inoculation volumes strictly matched method suitability ETX-260401-0599 (15 mL sterile Tween 80 and 5 mL sample directly inoculated into 200 mL TSB and FTM media bottles). Negative control bottles were prepared concurrently under identical conditions.

The inoculated media bottles and concurrent negative controls were incubated in qualified incubators E001356 (20-25 °C) and E001357 (30-35 °C). Throughout the required 14-day incubation period ending on 04Nov26, regular turbidity readings and microscopic inspections were performed by reading analyst Andrew Carrillo and verified by laboratory supervisor Robin Seymour. Both TSB and FTM media bottles remained completely clear with No Growth observed. Matching negative control media bottles demonstrated complete absence of microbial growth, confirming media sterility and aseptic integrity throughout the testing process. The retest result for submission ETX-261021-0445 was confirmed as Pass (No Growth).

In accordance with USP <71> and cGMP investigation principles, because the comprehensive Phase I laboratory investigation demonstrated that equipment, cleanroom environment, media, supplies, and analyst handling were fully in control with no assignable laboratory error, the initial positive sterility finding under ETX-260624-0251 (BUD-T90) cannot be invalidated. The passing retest result under ETX-261021-0445 demonstrates that the microbial contamination detected in the initial test was not uniformly present across all vials in Lot 17009. Rather, the data indicate a low-level, non-uniform distribution of microbial contamination (Bacillus megaterium) within the stability lot. Consequently, while the retest vials passed sterility requirements, the initial OOS result under ETX-260624-0251 (BUD-T90) remains confirmed and valid for the BUD-T90 study.

OOS Number: OOS- 262329

Has root cause been identified? ☑ Yes ☐ No	The most probable cause is: Non-uniformly distributed microbial contamination within Lot 17009. The initial failing result under ETX-260624-0251 (BUD-T90) remains confirmed and valid. Client Care notified: Yes☑ No☐

Section E – Corrective and Preventive Action

Corrective Action(s): Not Applicable	**OOS cause (select all)** ☐ Equipment Error ☐ Procedure ☐ Analyst ☐ Training ☐ System ☐ External Phenomena ☐ Other: _____
Preventive Action(s) Not Applicable	CAPA required: ☐ Yes, CAPA # _____ ☑ No
FOLLOW-UP REQUIRED: ☐ Yes ☑ No	FOLLLOW-UP DATE:

Section F – Acknowledgement and Closure

Prepared by:	Print Name:	Date: 04-Nov-2026
Reviewed by:	Print Name:	Date:
Approved by (QA):	Print Name:	Date:

Table 1: Information for ETX-260624-0251 (BUD-T90) and ETX-261021-0445 under investigation

Processing Analyst	Reading Analyst	Sample ID	Related Microbial ID	Media with microbial growth	Sterility Result	Microbial ID
Guanchen Li	Andrew Carrillo	ETX-260624-0251 (BUD-T90)	ETX-261012-0367	2 x 200mL TSB (Original and Subculture Bottles)	Fail	*Bacillus megaterium* (Gram (+) rods)
Ayomide Odugbesi	Andrew Carrillo	ETX-261021-0445	Not Applicable	No Growth	Pass	None

Table 2: Environmental Monitoring from Testing Performed on 23Sep26

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMMYY)	Analyst	Day /Week(s)	Observation	EM Plate ETX Number	Microbial ID	Notes
Personnel EM								
Personnel (Left Touch and Right Touch)	Daily	22Sep26	GL	Date Before Testing	No Growth	Not Applicable	Not Applicable	None
Personnel (Left Touch and Right Touch)	Daily	23Sep26	GL	Date of Testing	No Growth	Not Applicable	Not Applicable	None
Personnel (Left Touch and Right Touch)	Daily	24Sep26	GL	Date After Testing	No Growth	Not Applicable	Not Applicable	None
Biological Safety Cabinet EM for E001314								
Surface Sampling of ISO 5 (4 locations)	Daily	22Sep26	AOD	Date Before Testing	No Growth	Not Applicable	Not Applicable	None
Surface Sampling of ISO 5 (4 locations)	Daily	23Sep26	GL	Date of Testing	No Growth	Not Applicable	Not Applicable	None
Surface Sampling of ISO 5 (4 locations)	Daily	24Sep26	AOD	Date After Testing	No Growth	Not Applicable	Not Applicable	None
Settling Sampling of ISO 5 (2 locations)	Daily	22Sep26	AOD	Date Before Testing	No Growth	Not Applicable	Not Applicable	None
Settling Sampling of ISO 5 (2 locations)	Daily	23Sep26	GL	Date of Testing	No Growth	Not Applicable	Not Applicable	None
Settling Sampling of ISO 5 (2 locations)	Daily	24Sep26	AOD	Date After Testing	No Growth	Not Applicable	Not Applicable	None
Weekly Active Air Sampling of Cleanroom Suite 115 (E001737) with Processing BSC								
Active Air Sampling of Cleanrooms	Weekly	23Sep26	SMO	Week of Testing	6 CFUs (ISO 8 115)	ETX-261001-0625	*Micrococcus luteus* *Kocuria indica* *Kocuria rhizophila* Pending FunITS (Hyphae)	None
Weekly Surface Sampling of Cleanroom Suite 115 (E001737) with Processing BSC								
Surface Sampling of Cleanrooms	Weekly	23Sep26	SMO	Week of Testing	No Growth	Not Applicable	Not Applicable	None