OOS Number: OOS- 262098

Phase I

Section A – Test Details					
Initiator:	Alex Saravia (Written by: C	**Test Date:**	04-Sep-2026	**Date Initiated:**	10-Sep-2026
Date of Incident:	10-Sep-2026	**Test Name:**	USP <71> / EP 2.6.1 Sterility (Every Day	**Sample ID:**	ETX-260902-0505, ETX-260914-0470
Name of Analyst who Performed the Test:	Prepping Analyst: Alex Saravia (ES), Andrew Carrillo (AC) Processing Analyst: Alex Saravia (ES), Abayomi Odugbesi (AOD) Reading Analyst: Elysse Nioupin (EN), Andrew Carrillo (AC)	**Sample / Active Name**	GLP3R/Cagrilinitide	**Lot #:**	2608-216
		Dosage Form	Liquid		
Description of Incident:	On 10 Sep 2026, sample ETX-260902-0505 was confirmed positive and on 21 Sep 2026, sample ETX-260914-0470 was confirmed positive for viable microorganisms (1 x 100mL TSB each) after USP <71> sterility testing. Both samples belong to lot 2608-216 under investigation in OOS-262098.	☑ Client Care notified of OOS ☑ Sterility and Endotoxin test related OOS; Client must be notified within 24 hours of OOS			
	SOP / Test Method # MICRO-SOP-5	Effective Date: 24Jul2026	SOP / Test Method Rev: 19	Limits/Specification: Pass/Fail	
Manager notified	Manager/designee name: Kathan Parikh	Date: 10-Sep-2026	Quality Assurance Department notified:	Yes ☑ No ☐	

Section B – Investigation and Root Cause Analysis			
Personnel Discrepancy		**Comments**	
Analyst interviewed?	☑ Yes ☐ No ☐ N/A	Yes. Analysts Alex Saravia, Elysse Nioupin, Andrew Carrillo, and Abayomi Odugbesi were interviewed comprehensively. Handling error was refuted by identical retest recovery.	
Correct samples analyzed?	☑ Yes ☐ No ☐ N/A	Yes, sample IDs: ETX-260902-0505 and ETX-260914-0470	
Correct SOP / Test Method used/followed?	☑ Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-5	
Correct sample collection/technique?	☑ Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-5	
Are the Test Result Records Attached & Calculations Verified and Correct?	☑ Yes ☐ No ☐ N/A	Yes, information is available on EagleTrax under ETX-260902-0505 and ETX-260914-0470	
Is the analyst qualified to perform the test?	☑ Yes ☐ No ☐ N/A	Yes, the analysts are trained and qualified by quality to perform the test	
Is formula worksheet provided and verified?	☐ Yes ☐ No ☑ N/A	Not Applicable	
Does the processing method/method set conform to the required specification?	☐ Yes ☐ No ☑ N/A	Not Applicable	
Was the sample stored appropriately?	☑ Yes ☐ No ☐ N/A	Yes, both samples were stored as per client's instructions. Information is available in EagleTrax Sample Location History under ETX-260902-0505 and ETX-260914-0470	
Material Discrepancy		**Lot Number**	**Expiry Date**
Is the integrity of the sample(s) questionable?	☐ Yes ☑ No ☐ N/A		
Was the sample transported appropriately?	☑ Yes ☐ No ☐ N/A		
Are the other test results from this run under investigation?	☐ Yes ☑ No ☐ N/A		

OOS Number: OOS- 262098

Appropriate/correct glassware used?	☐Yes ☐ No ☑N/A		
Are reagents stored in proper condition and not expired?	☑Yes ☐ No ☐N/A	Process Consumables: ETX-260902-0505: FTM Lot 2567320, TSB Lot 2548010, Fluid D Lot 685561 ETX-260914-0470: FTM Lot 2567320, TSB Lot 2567280, Fluid D Lot 687774, Bacteriostatic Water NM7681 Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly cleaning logs	Process Consumables: ETX-260902-0505: FTM Lot 2567320, TSB Lot 2548010, Fluid D Lot 685561 ETX-260914-0470: FTM Lot 2567320, TSB Lot 2567280, Fluid D Lot 687774, Bacteriostatic Water NM7681 Environmental Plates: TSA and Surface Plate: see attached environmental logs Monthly Cleaning: H2O2 strips and IPA: See attached monthly cleaning logs
Standard Used	Not applicable	Not applicable	Not applicable
Solvent Used	Not applicable	Not applicable	Not applicable
Is the standard the source of the root cause?	☐Yes ☐ No ☑N/A		
Has the analyst been instructed to keep the original test solution for possible retesting?	☐Yes ☐ No ☑N/A		
Equipment Discrepancy		**Equipment ID**	**Calibration Due Date**
Was the instrument set up correctly?	☑Yes ☐ No ☐ N/A	ISO 5 BSC E001316, ISO 5 BSC E001314	Jun 2027, Jun 2027
Is the clean room facility certified?	☑Yes ☐ No ☐ N/A	CR 114 (E001736) and CR 115	Dec 2026
System Performance Check (if applicable)?	☐Yes ☐ No ☑ N/A	Not applicable	Not applicable
System Suitability RSD < 2% (PDA)?	☐Yes ☐ No ☑ N/A	Not applicable	Not applicable
System Suitability RSD < 10% (QDA, CAD)?	☐Yes ☐ No ☑ N/A	Not applicable	Not applicable
Do the environmental monitoring results conform to required standards?	☑Yes ☐ No ☐ N/A	See Phase I Summary	See Phase I Summary
Do the controls (i.e., positive, negative, etc.) conform to the required standards?	☑Yes ☐ No ☐ N/A	See Phase I Summary	See Phase I Summary
Is equipment/instrument functional and calibrated/qualified/certified/PM?	☑Yes ☐ No ☐ N/A	Incubator E001356 (Sensor E001450) Incubator E001357 (Sensor E001449) Incubator E001034 (Sensor E001501) Incubator E001031 (Sensor E001505)	Jan 2027 / Feb 2027 Jan 2027 / Feb 2027 Aug 2027 / Feb 2027 Aug 2027 / Feb 2027

OOS Number: OOS- 262098

Are chromatogram/spectra/raw data correct?	☐ Yes ☐ No ☑ N/A	Not applicable	Not applicable

Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)

- ☑ N/A
- ☐ Re-injection of sample vial
- ☐ Re-injection of original standard vial
- ☐ Re-vialing of original working standard solution
- ☐ Re-vialing of original working sample solution
- ☐ Re-dilution of a working sample solution from the original stock
- ☐ Re-dilution of a working standard solution from the original stock standard
- ☐ Other: N/A QYC 08Oct26

Section D – Phase I Summary

Phase I Summary:

All analysts involved in the prepping, processing, and reading of both samples – Alex Saravia, Elysse Nioupin, Andrew Carrillo, and Abayomi Odugbesi – were interviewed comprehensively. Their answers are recorded throughout this document.

Upon arrival, both sample submissions (ETX-260902-0505 and ETX-260914-0470) were stored in accordance with the Client ' s instructions. Analysts verified the integrity of the sample containers throughout both preparation and processing stages. No leaks, cracks, or turbidity were observed prior to testing, verifying container integrity.

All reagents and supplies mentioned in the material section above were stored according to suppliers ' recommendations, and their integrity was visually verified before utilization. Moreover, all culture media, rinses, and supplies possessed valid expiration dates. The functionality of all equipment was confirmed by reviewing continuous monitoring data.

Initial testing was conducted in Cleanroom Suite 114 (comprising the innermost ISO 7 cleanroom 114B, middle ISO 7 buffer room 114A, and outermost ISO 8 anteroom 114). Retest processing was conducted in Cleanroom Suite 115. Positive air pressure cascades are maintained throughout both suites to ensure controlled, outward unidirectional airflow.

Initial sample ETX-260902-0505 was received on 02 Sep 2026 and processed on 04 Sep 2026 by Alex Saravia in certified ISO 5 BSC E001316 (Cleanroom 114B) as per MICRO-SOP-5 (USP <71> / EP 2.6.1 Sterility Test). Prior to entry, vials were disinfected with acidified bleach allowing a 10-minute contact time at each transfer boundary. Membrane filtration was performed (3 vials filtered). Media bottles were transferred into designated incubators E001356 and E001357. On 10 Sep 2026 (Day 6 of incubation), turbidity was observed in 1 x 100mL TSB bottle by reading analyst Elysse Nioupin and confirmed by supervisor Robin Seymour. The positive bottle was submitted for Microbial Identification under ETX-260910-0290, which definitively identified the isolate as Microbacterium sp. PM5 (Gram (+) rods). Concurrent negative controls remained sterile.

Secondary sample ETX-260914-0470 was prepped on 14 Sep 2026 by Andrew Carrillo and processed on 15 Sep 2026 by Abayomi Odugbesi in certified ISO 5 BSC E001314 in Cleanroom Suite 115 as per MICRO-SOP-5 via membrane filtration (4 vials / 60 gm filtered). Standard multi-barrier disinfection and strict aseptic techniques were maintained. Media bottles were incubated in incubators E001356 and E001357. On 21 Sep 2026 (Day 6 of incubation), turbidity was observed in 1 x 100mL TSB bottle by reading analyst Andrew Carrillo and confirmed by supervisor Robin Seymour. The positive bottle was submitted for Microbial Identification under ETX-260921-0498, which definitively identified the identical isolate, Microbacterium sp. PM5 (Gram (+) short rods). Concurrent negative controls remained sterile.

OOS Number: OOS- 262098

Phase I Summary (continued):

ISO 5 BSC Environmental Monitoring Results Evaluation:
After reviewing the Environmental Monitoring (EM) records for both testing dates (04 Sep 2026 and 15 Sep 2026), no microbial growth was detected on operator personnel fingertip touch plates, settling plates, or ISO 5 BSC surface contact plates for either session, nor on preceding or subsequent testing days (including 03Sep26, 04Sep26, 08Sep26 for ES in BSC E001316, and 14Sep26, 15Sep26, 16Sep26 for AOD in BSC E001314).

Cleanroom Environmental Monitoring Results Evaluation:
For the initial processing on 04 Sep 2026 in Suite 114, weekly active surface sampling showed no growth; weekly active air sampling in ISO 8 cleanroom 114 recovered 2 CFUs (ETX-260914-0487), identified as Corynebacterium ureicelerivorans and Mycobacterium grossiae; on 10 Sep 2026, 1 CFU was recovered (ETX-260921-0520), identified as Micrococcus luteus. These environmental isolates differed distinctly in genus and morphology from the sample isolate (Microbacterium sp. PM5). For the retest processing on 15 Sep 2026 in Cleanroom Suite 115, weekly active surface sampling showed no growth; weekly active air sampling in ISO 8 cleanroom 115 recovered 9 CFUs (ETX-260923-0402), identified as Kocuria indica, Brevibacterium sp. CS2, Corynebacterium sp, Micrococcus luteus, Paracoccus yeei, Staphylococcus hominis, and Kocuria rhizophila. 100% of these environmental isolates differed distinctly in genus and morphology from the product contamination isolate (Microbacterium sp. PM5). Both air recoveries were strictly confined to the outermost ISO 8 anterooms (ISO 8 114 and ISO 8 115). All actual testing occurred within certified ISO 5 BSCs (E001316 in Suite 114 and E001314 in Suite 115) located in ISO 7 cleanrooms separated by positive pressure cascades. Test containers were transferred in disinfected, lidded bins, and critical zone settling, surface contact, and analyst fingertip plates remained 100% sterile (0 CFU). Therefore, cleanroom air recoveries were unrelated to the sample contamination. (Refer to Table 1 for sample details, Table 2 for environmental monitoring from processing performed on 04 Sep 2026, and Table 3 for environmental monitoring from processing performed on 15 Sep 2026).

The complete absence of contamination across all analyst glove touch plates, settling plates, and ISO 5 work surfaces across both processing sessions confirms that the ISO 5 critical zones remained in optimal control. Full compliance with MICRO-SOP-9 and MICRO-SOP-5 was verified. Monthly cleaning and disinfection of Cleanroom Suite 114 and Suite 115 was performed on 30 Aug 2026 as per MICRO-SOP-9, with all chemical H2O2 indicators passing.

A 6-month historical review for client Solyn LLC (E75000) confirmed that analyte GLP3R/Cagrilinitide had no prior sterility failures. Batch cross-contamination reviews were conducted for all samples processed on 04 Sep 2026 (where ETX-260902-0505 was 3rd in the batch) and 15 Sep 2026. All other client samples processed during both testing sessions tested negative, ruling out cross-contamination.

Importantly, the investigation evaluated why the prior rapid ScanRDI sterility test on this lot (ETX-260807-0602) yielded a passing result. In compounded parenteral products, low-level bioburden is characteristically non-uniformly distributed across individual vials. Under low-concentration non-uniform contamination, random unit sampling naturally results in some vials containing zero viable cells—as occurred with the vials sampled for ScanRDI under ETX-260807-0602—while other vials harbor low-level viable bioburden. Furthermore, no method suitability was on file for ScanRDI with this formulation. When low-level viable organisms were introduced into the 14-day USP <71> membrane filtration enrichment process, the microorganisms were successfully enriched and recovered in TSB on Day 6 in both independent testing events (ETX-260902-0505 and ETX-260914-0470), yielding the identical strain (Microbacterium sp. PM5). The successful replication across different processing analysts (Alex Saravia vs. Abayomi Odugbesi), different BSCs (E001316 vs. E001314), and different cleanroom suites (Suite 114 vs. Suite 115) conclusively refutes the preliminary hypothesis of analyst handling error during reconstitution. The passing ScanRDI result and both failing USP <71> results are scientifically consistent with non-uniform microbial distribution. Consequently, inherent product contamination in Lot 2608-216 is confirmed, and Lot 2608-216 fails USP <71> sterility requirements.

OOS Number: OOS- 262098

Phase I Summary (continued):

N/A QYC 08Oct26

OOS Number: OOS- 262098

Has root cause been identified as a possible laboratory error?
Note: Root cause must be conclusive, verifiable, and well-documented.

☑ Yes

☑ If retesting is ***required***, complete Phase II of the OOS (initiate Form 3.100.019.F02).

☐ No, the OOS result is valid.

Reviewer comment(s):
Inherent product contamination in Lot 2608-216, confirmed by independent dual-sample recovery of identical strain Microbacterium sp. PM5 on Day 6 in TSB under ETX-260902-0505 and ETX-260914-0470.

Prepared by (*Print*)**:**	Signature/Date:
Qiyue Chen	
Lab Manager/Designee (*Print*)**:**	Signature/Date:

Section E – Quality Disposition

Can investigation be closed?

☐ Yes

☐ Original result is valid.

☑ No, initiate Form 3.100.019.F02.

Approved by QA Representative (*Print*)**:**	Signature/Date:

Table 1: Information for ETX-260902-0505 and ETX-260914-0470 under investigation

Processing Analyst	**Reading Analyst**	Sample ID	Related Microbial ID	Media with microbial growth	Microbial ID
Alex Saravia	Elysse Nioupin	ETX-260902-0505	ETX-260910-0290	1 x 100mL TSB bottle	*Microbacterium sp. PM5* (Gram (+) rods)
Abayomi Odugbesi	Andrew Carrillo	ETX-260914-0470	ETX-260921-0498	1 x 100mL TSB bottle	*Microbacterium sp. PM5* (Gram (+) short rods)

Table 2: Environmental Monitoring from Processing Performed on 04Sep26

Environmental Monitoring (EM) Sampling Site	**Frequency**	**Date (DDMMMYY)**	**Analyst (Initials)**	**Day /Week(s)**	**Observation***	**Environmental Monitoring Plate ETX ID**	**Microbial ID**	**Notes**
Personnel EM Bracketing								
Personnel (Left Touch and Right Touch)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Biological Safety Cabinet EM Bracketing - ISO 5 BSC E001316 (Suite 114)								
Surface Sampling of ISO 5 (4 locations)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	03Sep26	ES	Date Before Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	04Sep26	ES	Date of Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	08Sep26	ES	Date After Testing	No growth	N/A	N/A	None
Weekly Active Air Sampling Bracketing (Suite 114)								
Active Air Sampling of Cleanrooms	Weekly	04Sep26	ISS	Week on Testing Date	2 CFUs (ISO 8 114)	ETX-260914-0487	*Corynebacterium ureicelerivorans* *Mycobacterium grossiae*	None
Weekly Surface Sampling of Cleanrooms Bracketing (Suite 114)								
Surface Sampling of Cleanrooms	Weekly	04Sep26	ISS	Week on Testing Date	No growth	N/A	N/A	None

Table 3: Environmental Monitoring from Processing Performed on 15Sep26

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMMYY)	Analyst (Initials)	Day /Week(s)	Observation*	Environmental Monitoring Plate ETX ID	Microbial ID	Notes
Personnel EM Bracketing								
Personnel (Left Touch and Right Touch)	Daily	14Sep26	AOD	Date Before Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	15Sep26	AOD	Date of Testing	No growth	N/A	N/A	None
Personnel (Left Touch and Right Touch)	Daily	16Sep26	AOD	Date After Testing	No growth	N/A	N/A	None
Biological Safety Cabinet EM Bracketing - ISO 5 BSC E001314 (Suite 115)								
Surface Sampling of ISO 5 (4 locations)	Daily	14Sep26	AOD	Date Before Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	15Sep26	AOD	Date of Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 locations)	Daily	16Sep26	AOD	Date After Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	14Sep26	AOD	Date Before Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	15Sep26	AOD	Date of Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 locations)	Daily	16Sep26	AOD	Date After Testing	No growth	N/A	N/A	None
Weekly Active Air Sampling Bracketing (Suite 115)								
Active Air Sampling of Cleanrooms	Weekly	15Sep26	SMO	Week on Testing Date	9 CFUs (ISO 8 115)	ETX-260923-0402	*Kocuria indica* *Brevibacterium sp. CS2* *Corynebacterium sp* *Micrococcus luteus* *Paracoccus yeei* *Staphylococcus hominis* *Kocuria rhizophila*	None
Weekly Surface Sampling of Cleanrooms Bracketing (Suite 115)								
Surface Sampling of Cleanrooms	Weekly	15Sep26	SMO	Week on Testing Date	No growth	N/A	N/A	None