



QUALITY SYSTEM

FORM

DOCUMENT #: 3.100.019.F01

LEVEL: 3

Effective Date:

APPROVED

JEsqueda , 9/30/2025, 4:15:53 PM

Revision #: 11

TITLE:

LABORATORY OOS INVESTIGATION FORM

Page 1 of 6

OOS Number: OOS- 261401

Phase I

Section A – Test Details

Initiator:	Guanchen (David) Li (Written by: Dhvanir Kansara)	Test Date:	04-Jun-2026	Date Initiated:	15-Jun-2026
Date of Incident:	15-Jun-2026	Test Name:	Environmental Monitoring	Sample ID:	ETX-260615-0424
Name of Analyst who Performed the Test:	Guanchen (David) Li (Surface Sampling Analyst) Maraya Chukwumerije and Simin Mohammad (Surface Sampling Plate Reader)	Sample / Active Name	Sterility GL E001314 S1 04JUN2026	Lot #:	Sterility GL E001314 S1 04JUN2026
		Dosage Form	Plate		
Description of Incident:	The CFU count for the environmental monitoring plate exceeded the action level.		☐ Client Care notified of OOS ☐ Sterility and Endotoxin test related OOS; Client must be notified within 24 hours of OOS		
	SOP / Test Method # MICRO-SOP-2	Effective Date: 05 Aug 2025	SOP / Test Method Rev: 15	Limits/Specification: Action level: >= 1CFU/Plate	
Manager notified	Manager/designee name: Robin Seymour	Date: 15-Jun-2026	Quality Assurance Department notified:	Yes ☐ No ☐	

Section B – Investigation and Root Cause Analysis

Personnel Discrepancy		Comments
Analyst interviewed?	☒ Yes ☐ No ☐ N/A	Yes, analysts Guanchen (David) Li and Maraya Chukwumerije and Simin Mohammad were comprehensively interviewed.
Correct samples analyzed?	☐ Yes ☐ No ☒ N/A	Not applicable
Correct SOP / Test Method used/followed?	☒ Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-2
Correct sample collection/technique?	☒ Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-2
Are the Test Result Records Attached & Calculations Verified and Correct?	☒ Yes ☐ No ☐ N/A	Yes, Information is available on Eagletrax under ETX-260615-0424
Is the analyst qualified to perform the test?	☒ Yes ☐ No ☐ N/A	Yes, the analysts are trained and qualified by quality to perform the test
Is formula worksheet provided and verified?	☐ Yes ☐ No ☒ N/A	Not Applicable
Does the processing method/method set conform to the required specification?	☐ Yes ☐ No ☒ N/A	Not Applicable
Was the sample stored appropriately?	☒ Yes ☐ No ☐ N/A	Yes, as per MICRO-SOP-2
Material Discrepancy		Lot Number
Is the integrity of the sample(s) questionable?	☐ Yes ☐ No ☒ N/A	
Was the sample transported appropriately?	☐ Yes ☐ No ☒ N/A	
Are the other test results from this run under investigation?	☐ Yes ☐ No ☒ N/A	



QUALITY SYSTEM

FORM

DOCUMENT #: 3.100.019.F01

LEVEL: 3

Effective Date:

APPROVED
JEsqueda, 9/30/2025, 4:15:53 PM

Revision #: 11

TITLE:

LABORATORY OOS INVESTIGATION FORM

Page 2 of 6

OOS Number: OOS- 261401

Appropriate/correct glassware used?	☐ Yes ☐ No ☒ N/A		
Are reagents stored in proper condition and not expired?	☒ Yes ☐ No ☐ N/A	Contact Plate: 1011834770	Contact Plate: 25 Sep 2026
Standard Used	Not Applicable	Not Applicable	Not Applicable
Solvent Used	Not Applicable	Not Applicable	Not Applicable
Is the standard the source of the root cause?	☐ Yes ☐ No ☒ N/A		
Has the analyst been instructed to keep the original test solution for possible retesting?	☐ Yes ☐ No ☒ N/A		
Equipment Discrepancy		Equipment ID	Calibration Due Date
Was the instrument set up correctly?	☒ Yes ☐ No ☐ N/A	Please see below	Please see below
Is the clean room facility certified?	☒ Yes ☐ No ☐ N/A	CR115 (E001737)	December 2026
System Performance Check (if applicable)?	☐ Yes ☐ No ☒ N/A	N/A	N/A
System Suitability RSD < 2% (PDA)?	☐ Yes ☐ No ☒ N/A	Not Applicable	Not Applicable
System Suitability RSD < 10% (QDA, CAD)?	☐ Yes ☐ No ☒ N/A	Not Applicable	Not Applicable
Do the environmental monitoring results conform to required standards?	☐ Yes ☐ No ☒ N/A	Not Applicable	Not Applicable
Do the controls (i.e., positive, negative, etc.) conform to the required standards?	☐ Yes ☐ No ☒ N/A	Not Applicable	Not Applicable
Is equipment/instrument functional and calibrated/qualified/certified/PM?	☒ Yes ☐ No ☐ N/A	Incubator E001034 (Sensor E001501) Incubator E001031 (Sensor E001505)	Aug 2026 Feb 2027 Aug 2026 Feb 2027

	QUALITY SYSTEM		FORM
	DOCUMENT #: 3.100.019.F01		LEVEL: 3
	Effective Date:	APPROVED JEsqueda, 9/30/2025, 4:15:53 PM	Revision #: 11
TITLE:	LABORATORY OOS INVESTIGATION FORM		Page 3 of 6

OOS Number: OOS- 261401

Are chromatogram/spectra/raw data correct?				☐ Yes	☐ No	☒ N/A	Not Applicable	Not Applicable
Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)								
☒ N/A		☐ Re-vialing of original working sample solution						
☐ Re-injection of sample vial		☐ Re-dilution of a working sample solution from the original stock						
☐ Re-injection of original standard vial		☐ Re-dilution of a working standard solution from the original stock standard						
☐ Re-vialing of original working standard solution		☐ Other: N/A						
Section D – Phase I Summary								
Phase I Summary: The analyst involved in the surface sampling plate setup, Guanchen (David) Li (GL), and the analysts involved in reading the plate, Maraya Chukwumerije and Simin Mohammad, were interviewed comprehensively. Their responses are documented throughout this investigation. The EM plates were stored in accordance with the supplier's recommendations, visually inspected before use, and verified to be within their assigned expiration dates. All materials and supplies were disinfected in accordance with MICRO-SOP-9, Cleaning and Disinfecting Procedure for Microbiology. The functionality of the incubators was verified through review of data generated by the in-house continuous monitoring system. Surface Sampling was performed by Guanchen (David) Li in ISO 5 BSC E001314 located in room 115B in suite CR115 on the date of testing (04 June 2026), in accordance with MICRO-SOP-2, Environmental Monitoring of the Cleanroom Facility. The plates were initially incubated at a temperature of 30-35°C in incubator E001031 for a minimum duration of 48 hours, commencing on 04 June 2026. Following completion of the minimum 48 hours of incubation on 08 June 2026, no microbial growth was observed. The plates were subsequently incubated for a minimum of 5 days at 20-25°C in incubator E001034, with incubation ending on 15 June 2026. At completion of the second incubation period, one colony-like artifact was observed on S1. The plate was read by Maraya Chukwumerije after the initial incubation period and by Simin Mohammad after the second incubation period. Please see Table 1 for detailed information on the observations during the respective incubations. The observed artifact was submitted for microbial identification under ETX-260615-0424. However, following transfer or inoculation onto fresh media, no growth was observed. Therefore, the observed artifact could not be confirmed as a viable microbial colony or reported as a confirmed colony forming unit (CFU). The lack of growth upon subculture indicates that the observation may have been nonviable material, an artifact associated with agar preparation or pouring, or another non-microbial artifact. To determine whether the recovery was transient or recurring, personnel-monitoring plates for Guanchen (David) Li and ISO 5 BSC E001314 environmental-monitoring plates were bracketed to include the date before testing (03 June 2026), the date of testing (04 June 2026), and the date after testing (05 June 2026), as detailed in Table 2.								

**QUALITY SYSTEM**FORM**DOCUMENT #: 3.100.019.F01****LEVEL: 3**

Effective Date:

APPROVED

JEsqueda , 9/30/2025, 4:15:53 PM

Revision #: 11

TITLE:**LABORATORY OOS INVESTIGATION FORM****Page 4 of 6****OOS Number: OOS- 261401****Phase I Summary (continued):**

Environmental Monitoring Summary:

Personnel monitoring plates for Guanchen (David) Li, including left- and right-touch plates, showed no microbial growth on the date before testing (03 June 2026), the date of testing (04 June 2026), and the date after testing (05 June 2026).

For ISO 5 BSC E001314, daily surface sampling of four locations showed no microbial growth on the date before testing (03 June 2026). On the date of testing (04 June 2026), 1 CFU was recovered from S1 associated with Guanchen (David) Li. The recovery was documented under ETX-260615-0424; microbial identification indicated colony-like artifact. Surface sampling performed on the date after testing (05 June 2026) showed no microbial growth.

Settling sampling of ISO 5 BSC E001314, including two locations, showed no microbial growth on the date before testing (03 June 2026), the date of testing (04 June 2026), and the date after testing (05 June 2026).

Weekly active-air monitoring of Suite 115 conducted during the week before testing and the week of testing showed no microbial growth.

Weekly surface monitoring of the anteroom and cleanroom areas associated with Suite 115 showed no microbial growth during the week before testing or the week of testing.

During the interview, the analyst indicated that no obvious abnormalities or deviations occurred during the testing process. All materials were disinfected before testing, and the relevant cleanroom and ISO 5 BSC were cleaned and prepared before testing in accordance with MICRO-SOP-2 and MICRO-SOP-9.

Monthly cleaning and disinfection of the cleanroom suite, including the ISO 8 anteroom (115), ISO 7 buffer room (115A), ISO 7 cleanroom (115B), and the ISO 5 biosafety cabinets located within Room 115B, were performed on 26 April 2026 by Analyst - Rey Estrada - in accordance with MICRO-SOP-9, Cleaning and Disinfecting Procedure for Microbiology. All H2O2 indicators passed, confirming the successful completion and effectiveness of the monthly cleaning and disinfection activities within Rooms 115, 115A, and 115B. Additionally, routine cleaning and disinfection were performed before and after the testing activity in accordance with MICRO-SOP-9.

It is also important to note that no samples processed by Guanchen (David) Li in ISO 5 BSC E001314 on the date of testing (04 Jun 2026) failed Sterility testing.

Based on the available evidence, one colony-like artifact was observed on Sterility GL E001314 S1 04JUN2026 in ISO 5 BSC E001314 on the date of testing (04 June 2026). However, the observation could not be confirmed as a viable microbial CFU because no growth was obtained following inoculation onto fresh media. Therefore, the observation may represent a nonviable or non-microbial artifact, including a potential artifact associated with agar preparation or the agar-pouring process.

If the observed artifact had represented a viable CFU, it would appear to be an isolated event. This assessment is supported by the absence of microbial recovery from Guanchen (David) Li's personnel-monitoring plates on the date before testing (03 June 2026), the date of testing (04 June 2026), and the date after testing (05 June 2026); the absence of growth from BSC E001314 surface samples collected on the date before testing and the date after testing; and the absence of growth from ISO 5 settling plates throughout the bracketing period.

The negative ISO 5 settling, personnel, and bracketing surface monitoring results demonstrate that the BSC E001314 critical environment remained in a state of control. The available data do not support migration, persistence, or recurrence of contamination within ISO 5 BSC E001314. Collectively, the evidence supports that the recovery was an isolated, transient, and non-recurring event, while established cleaning, disinfection, and aseptic controls remained effective.



QUALITY SYSTEM

FORM

DOCUMENT #: 3.100.019.F01

LEVEL: 3

Effective Date:

APPROVED

JEsqueda , 9/30/2025, 4:15:53 PM

Revision #: 11

TITLE:

LABORATORY OOS INVESTIGATION FORM

Page 5 of 6

OOS Number: OOS- 261401

Phase I Summary (continued):

Accordingly, no systemic environmental control deficiencies were identified, and no additional corrective or preventive actions are warranted at this time beyond continued routine environmental monitoring and adherence to approved cleaning, disinfection, and aseptic procedures.



QUALITY SYSTEM

FORM

DOCUMENT #: 3.100.019.F01

LEVEL: 3

Effective Date:

APPROVED

JEsqueda , 9/30/2025, 4:15:53 PM

Revision #: 11

TITLE:

LABORATORY OOS INVESTIGATION FORM

Page 6 of 6

OOS Number: OOS- 261401

Has root cause been identified as a possible laboratory error?*Note: Root cause must be conclusive, verifiable, and well-documented.*☒ Yes☐ If retesting is **required**, complete Phase II of the OOS (initiate Form 3.100.019.F02).☐ No, the OOS result is valid.**Reviewer comment(s):****Prepared by (Print):**

Dhvanir Kansara

Signature/Date:

Lab Manager/Designee (Print):

Robin Seymour

Signature/Date:

Section E – Quality Disposition**Can investigation be closed?**☐ Yes☐ Original result is valid.☐ No, initiate Form 3.100.019.F02.**Approved by QA Representative (Print):**

Signature/Date:

Table 1: Read Dates and Incubation Observation

Sampling Location	Read Date (30-35°C, NLT 48h)	Read By	CFU Count / Observation	Read Date (20-25°C, NLT 5d)	Read By	CFU Count / Observation	Microbial Identification
Surface Sampling Plate (BSC E001314)	06 Jun 2026	MC	No microbial growth was observed	11 Jun 2026	SMO	1 CFU on Sterility GL E001314 S1 04JUN2026	colony-like artifact

Table 2: Environmental Monitoring Plates for Analyst and Cleanroom Bracketing

Sampling Type	Sampling Location	Date Before Testing (03 Jun 2026)		Date of Testing (04-Jun-2026)		Date After Testing (05 Jun 2026)	
		Analyst / Result	ETX / Identification	Analyst / Result	ETX / Identification	Analyst / Result	ETX / Identification
Personnel Monitoring	Glove Touch (Left / Right)	GL No growth	N/A N/A	GL No growth	N/A N/A	GL No growth	N/A N/A
Surface Sampling	ISO 5 BSC E001314	GL No growth	N/A N/A	GL 1 CFU	ETX-260615-0424 colony-like artifact	GL No growth	N/A N/A
Settling Sampling	ISO 5 BSC E001314	GL No growth	N/A N/A	GL No growth	N/A N/A	GL No growth	N/A N/A
Weekly Cleanroom Active Air	Cleanroom CR115 (E001737)	Rey Estrada No growth	N/A N/A	Rey Estrada No growth	N/A N/A	Rey Estrada No growth	N/A N/A
Weekly Cleanroom Surface	Anteroom & Buffer (CR115 (E001737))	Rey Estrada No growth	N/A N/A	Rey Estrada No growth	N/A N/A	Rey Estrada No growth	N/A N/A