

# Standard of the Camera & Imaging Products Association

# CIPA DC-004-Translation-2020

# Sensitivity of digital cameras

This translation has been made based on the original Standard (CIPA DC-004-2020). In the event of any doubts arising as the contents, the original Standard is to be the final authority.

Established in July 2004 Revised in September 2020

Presented by Standardization Committee

Published by Camera & Imaging Products Association

#### Disclaimer

- 1. Neither CIPA nor any of its members shall in any way warrant or take any responsibility for no-infringement of Intellectual Property Rights with respect to the use of CIPAStandards.
- 2. Neither CIPA nor any of its members shall give any warranty of any kind or take any responsibility for the scope, validity, and essentiality of the Essential Intellectual Property Rights with respect to CIPA Standards.
- 3. Neither CIPA nor any of its members which are not related to such licensing shall take any responsibility for the terms and conditions of licenses with owners of Intellectual Property Rights, or other licensing negotiations and the results of such negotiations with respect to CIPA Standards.
- 4. Neither CIPA nor any of its members shall give any warranty of any kind or take any responsibility, either expressed or implied, including warranties of merchantability and fitness for particular purpose, with respect to CIPA Standards.
- 5. Neither CIPA nor any of its members shall take any responsibility for any damages (meaning all damages including without limitation, loss of business profits, or other incidental or consequential damages) arising out of any use or inability to use the CIPA Standards. The same applies even if either CIPA or its members have been advised of the possibility of such damages.
- 6. Neither CIPA nor any of its members shall take any responsibility for any disputes that arise at an adopter of CIPA Standards that stem from or are in connection with CIPA standards or the use of CIPA standards.
- 7. In the event that a statement is not obtained from Sub-Working Group Participant Members to the effect that Essential Intellectual Property Rights are licensed under reasonable (or free) and nondiscriminatory terms, due to believing that Intellectual Property Rights will not be infringed by use of CIPA Standards even after the establishment, addition, or modification of Mandatory Provisions when enacting or revising CIPA Standards, neither CIPA nor any of its members shall give any warranty of any kind that Essential Intellectual Property Rights are not included in the CIPA Standards, and shall not take any responsibility for any disputes that arise as a result of such Intellectual Property Rights being included in the CIPA Standards.

Copyright © 2004-2020 CIPA All Rights Reserved

1

# **Table of Contents**

Introduction · · · · · · · · · · · · · · · · · · ·
Revision history · · · · · 2
1. Scope 3
2. Normative references
3. Terms and definitions
3.1 Sensitivity (photographic sensitivity) · · · · · · 3
3.2 Standard Output Sensitivity · · · · · · · 3
3.3 Recommended Exposure Index · · · · · 4
4. Spectral distribution of subjective illumination · · · · · · · · 4
5. Measurement method of standard output sensitivity · · · · · · · 5
5.1 Target signal for evaluation ••••• 5
5.2 Reference level
5.3 Measurement Conditions · · · · · 5
5.4 Test Chart6
5.5 Method of Measurement · · · · · · · · · · · · · · · · · · ·
6. Method of Notation · · · · · · · 7
6.1 Notational terms · · · · · · · · · · · · · · · · · · ·
6.2 Assigned values to be listed · · · · · · 8
6.3 Examples of Notations · · · · · 9
7. Conversion into assigned values from actual (calculated) values · · · · · · · 10
Annex 1 (Normative) Spectral distribution of subjective illumination · · · · · · · · · · · · · 11
Annex 2 (Normative) White Balance adjustment for cameras · · · · · · · · · · · · · · · · · · ·
Annex 3 (Informative) Recommended measurement method (An example) · · · · · · · · 15
Annex 4 (Informative) An example of Daylight Simulator equivalent to D55 · · · · · · 18
Explanation · · · · · 19

## Sensitivity of digital cameras

#### Introduction

This standard is the 2nd edition of CIPA DC-004 'Sensitivity of digital cameras' of which the 1st edition issued in 2004. It has been a long time since the 1st edition was issued and the revision of the international standard ISO 12232, which this standard has consistency, has derived the differences between the two standards have become noticeable, so this standard has been revised.

CIPA DC-004 and ISO 12232 both provide 'Standard Output Sensitivity (SOS)' and 'Recommended Exposure Index (REI)'. SOS is a physical measure and defined by light responsiveness of cameras (imaging systems). REI is an indicator recommended for exposure based on the image quality sensory evaluation by camera vendors. Therefore, these two factors have conceptual differences, however both serve as similar exposure control functions when using a camera, and they are able to be used as indicators to describe a 'practical sensitivity' indicating the necessary amount of light for a camera (imaging system).

These two should be used separately in accordance with the purpose just as both 'ISO speed' and 'Exposure Index' (the former was established based on the light sensitivity of film, and the latter is based on the image quality sensory evaluation of film vendors) have been used depending on the purpose of silver halide film cameras. .

Thus, this standard defines both of these as sensitivity of a digital camera. At the same time, comprehensive specification terms for catalogues are stipulated.

ISO12232 was titled "Determination of ISO speed" in the 1st edition issued in 1998, but has been renamed to "Determination of exposure index", "ISO speed ratings, standard output sensitivity, and recommended exposure index" since the 2nd edition. The point of the revision to the 2nd edition was the addition of the standard output sensitivity SOS and the recommended exposure index REI. This was the incorporation of these two indicators, first defined by DC-004-2004, the first version of this standard, into the ISO standard. Behind the scenes was the fact that the ISO speed of 12232: 1998 had problems applying to the sensitivity of consumer digital cameras (see explanation 1). Therefore, although this standard is consistent with ISO12232, only standard output sensitivity (SOS) described in Chapter 7 and recommended exposure index (REI) described in Chapter 8 of ISO12232: 2019 (3rd edition) are adopted and other indicators are not accepted.

In addition, since the specified range of the sensitivity notation value table (conversion table from actual values to representative values) was extended to the higher sensitivity side at the revision of ISO 12232 into the third edition (2019), this CIPA standard was revised for reflecting it. But actually, the content of the revision of the ISO standard adopted the Japanese

opinion proposed by CIPA almost as it was.

Thus, much of the inclusion in this standard reflecting the revision of the ISO 12232 can be considered as "reimport" metaphorically, and the consistency between the two standards is bidirectional.

### **Revision History**

July, 2004 1st edition	CIPA DC-004-2004	Specified sensitivity of digital cameras
Month,2020 Revised	CIPA DC-004-2020	► Reorganized the three-part chapter into a standard one
2nd edition		- Furthermore, the structure (order) of Explanation has been revised
		► Revised the description in [Introduction], where the chapter title translation has changed from former [Overview]
		► Updated Normative reference
		- Reflected the revision of ISO 7589 and updated the reprinted Table 1 and 2
		► Revised the description of and added a term to [Terms and definitions]
		► Added example.11 to [Examples of Notations]
		► Extended [conversion table from actual values to representative values] to the higher sensitivity side
		► Revised the title and some parts of symbols and descriptions in normative Annex 1
		➤ Deleted informative Annex 4 [Rules for conversion of assigned values from measured values (calculated values)]
		► Editorial correction for overall
		- Error corrections, and improvement and unification for expressions and appearances

#### 1. Scope

This standard is applicable to consumer digital still cameras. It defines the definition of sensitivity and its measurement method, and further specifies the method of notation of the sensitivity as product specifications to general consumers, in such as catalogues and instruction manuals.

#### 2. Normative reference

The following referenced documents are indispensable for the application of this document.

**ISO12232:2019** Photography — Digital still cameras — Determination of exposure index, ISO speed ratings, standard output sensitivity, and recommended exposure index **ISO7589: 2002** Photography - Illuminants for sensitometry - Specifications for daylight, incandescent tungsten and printer

#### 3. Terms and definitions

#### 3.1 Sensitivity (photographic sensitivity)

General term used for numerical values calculated based on the exposure at the focal plane of a DSC which produces a specified camera image signal level, including standard output sensitivity or recommended exposure index. Photographic sensitivity is clearer as a designation but simple sensitivity is also used, and this standard mainly uses simple one. It corresponds the photographic sensitivity of ISO 12232:2019, and is also called "ISO sensitivity", for historical reasons that date from ISO standards for photographic film cameras.

#### 3.2. Standard Output Sensitivity

A numerical notation that is converted by a prescribed method from the input exposure necessary to obtain specified digital output values for taking still images under specified conditions. Quantitatively, it is the exposure index corresponding to the necessary exposure for obtaining the predetermined reference level of digital signal output mentioned in the conditional specification below by using the predetermined spectral distribution light defined by the conditions described below.

That is the dimensionless value S obtained by the following equation where said exposure is Hm in the unit ' $1x \cdot s$ ':

$$S = \frac{10}{Hm}$$

#### 3.3 Recommended Exposure Index

An exposure index corresponding to the average exposure in a focal plane under the predetermined spectral distribution light defined by the conditions described below recommended by camera (imaging system) vendors (manufacturers etc.) for the purpose of reference to the setting an exposure index (film ISO speed value) when using a separate exposure meter or accessory strobe etc..

That is a dimensionless value REI calculated by the equation

$$REI = \frac{10}{Em}$$

where Em is said recommended average exposure in the focal plane in the unit 'lx ·s'.

**Note:** Recommended exposure index is not measureable (not a subject of measurement) according to principle because it declares the value which the vendor recommends. The measurement method of chapter 5 is certainly the one applicable only to standard output sensitivity. Attention that though there is automatic exposure control characteristics of a camera, which is a subject of measurements deeply relating recommended exposure index, it is not a measurement of recommended exposure index (See Explanation 8 and 9).

#### 4. Spectral distribution of subjective illumination

The value of sensitivity can be different with spectral distribution of the illuminations. This standard specifies two types of subjective illumination: **Daylight**, when daylight is assumed, and **Tungsten**, when a studio tungsten lamp is assumed. The measurement of **Daylight** is mandatory and **Tungsten** is optional.

When resulted values of **Daylight** are listed, the description of the subjective illumination may be omitted, and also the term 'daylight' may be included. In the case of **Tungsten**, the term 'tungsten' shall appear in the list of the resulted values.

When applying with a taking lens:

- Daylight: Use photographic daylight relative power D55 (note)
- Tungsten: Use studio tungsten relative power (note)

When applying to a camera body without a taking lens, for cameras with interchangeable lenses, use:

- Daylight: ISO sensitometric daylight illuminant (note)
- Tungsten: ISO sensitometric studio tungsten illuminant (note)

Note: These are all in line with ISO7589 (Table 1 or 2). See Annex 1 (Normative) for details.

#### 5. Measurement method of standard output sensitivity

Note: The method of this chapter is not applicable to recommended exposure index (See Note of 3.3).

#### 5.1 Target signal for evaluation

Target signal for evaluation is one of the following signals obtainable from the typical playback system (usually the bundled software), which is designated by the camera manufacturer concerning playback on personal computers.

- Digital grayscale (monochrome) signal (for monochrome cameras)
- Luminance signal (Y) calculated by the equation below using digital RGB signals (for colour cameras)

#### Y = MAX x $\gamma$ { 0.2126 $\gamma^{-1}$ {R/MAX}+0.7152 $\gamma^{-1}$ {G/MAX}+0.0722 $\gamma^{-1}$ {B/MAX} }

**MAX** is the normalization coefficient (=maximum digital output level: 255 for 8-bit system)  $\gamma$ { },  $\gamma$  -1{ } denote **sRGB** gamma characteristics and the inverse transformation (linearization) characteristics defined by **IEC61966-2-1**.

#### **5.2 Reference level**

The reference level of digital output to obtain **Hm** is

#### MAX x 0.461

where MAX is the maximum digital output level.

Fractions are dropped. (118 for 8-bit type)

#### 5.3. Measurement Conditions

#### **5.3.1** General conditions

- (1) Measurement shall be conducted where there is no outside light that may affect the measured values, preferably, in a darkroom.
- (2) Measurement shall start after all the tested materials and testing equipment are left in the testing environment until they are fully stable.

#### **5.3.2** Environmental conditions

(3) Measurement shall be conducted while maintaining the surrounding temperature at  $23^{\circ}C\pm2^{\circ}C$  and relative humidity at  $50\%\pm20\%$ .

### **5.3.3 Lighting conditions:** Apply the subjective illuminations described in chapter 4

#### (4) Illuminance

Illuminance of 2000 (lx) on the chart face is set as a standard illuminance. (In the case of transparent chart, the luminance at a clear point is 637 (cd/m<sup>2</sup>)). However, illuminance values can be set discretionarily unless there is some doubt.

Note: The illuminance stated above is defined under the condition that there is no intervening object. If, for example, ND filter is used for measurement, illuminance shall be treated as decreased in response to it. In addition, measuring illuminance does not normally affect Standard Output Sensitivity under a fixed state of sensitivity (when automatic sensitivity adjustment function does not work).

#### (5) Unevennes of chart luminance

Dispersion of chart luminance shall be 10% or less.

#### 5.3.4 Camera settings

#### (6) White balance adjustment

White balance of a camera needs to be adjusted appropriately to the measuring light source. See **Annex 2 (normative)** for specific provisions.

#### (7) Sensitivity settings

The automatic sensitivity adjustment function of a camera, if there is one, shall be deactivated. The sensitivity adjustment of a camera shall be fixed on one sensitivity point, being a subject of measurement.

Therefore, as a rule, a camera cannot be used for measurement if its automatic sensitivity adjustment function cannot be deactivated. However, when it is observed that a sensitivity adjustment is maintained to be a fixed representative condition during the time of measurement, Standard Output Sensitivity measurement may be conducted as an exception. (note)

Meanwhile, measuring illuminance in such cases is the standard illuminance described above, unless otherwise specifically stated.

Note: See Annex 3 (Informative) for specific examples.

#### (8) Exposure adjustment

Method of exposure adjustment itself is discretionary, however, it is necessary to obtain exposure adjustment values (aperture value and exposure time) used in the measurement. (note) For this reason, as well as for ease in achieving repeatability of measurement, **a manual exposure adjustment** on cameras is recommended.

The standard exposure time is **more than 1/500 s** but **less than 1/30 s**. If it is out of this range, the condition (exposure time) shall be mentioned.

Note: For example, displayed exposure values on a camera or exposure data recorded in the image file as enclosed data can be used. However, it must be noted in this case that errors in the control or notation of a camera are to be directly included as errors of the sensitivity values. See **Annex 3** (**Informative**) on this point.

#### (9) Other automatic adjustment functions

Various other automatic adjustment functions on cameras such as automatic focusing or anti-shake function shall also be deactivated, if it is possible, to measure the sensitivity. However, the deactivation is discretionary when there are no doubts about the measured values.

#### 5.4. Test Chart

A chart used for measurement shall have a colourless defusing surface with at least one uniform usable part (chip) as a measuring area of illuminance or signal level (which is the area used for the acquisition of measured values; hereinafter called the 'remarkable part').

Said remarkable part shall be included in the area of which the shading amount (input luminance converted) of the camera being tested is within less than 10% from the centre of an imaging area. Moreover, it is necessary to remove any objects that may cause flare or ghost in all other photographic areas other than the measuring area. From that perspective, it is desirable to cover all the photographic area of the camera being tested as one whole chart.

Note: It is convenient to use a chart with several chips of different reflectance. Annex 3 (Informative) shows an example of measurement using a Grayscale Chart.

### **5.5. Method of Measurement** (note 1)

- (1) Take an image of a chart under the designated light with the camera being tested.
- (2) Obtain exposure values, i.e. the effective aperture value **F** (dimensionless quantity) and exposure time **T** (s), of when the digital output value of the remarkable part of the chart equals to the reference level (see 5.2). (note 2)
- (3) Measure **luminance value B** (cd/m<sup>2</sup>) at the remarkable part of the chart described above.
- (4) Calculate **the focal plane exposure Hm** (lx·s), which is a measurement criterion, using the following equation.

$$Hm = \frac{0.65 \times B \times T}{F^2}$$

(5) Obtain Standard Output Sensitivity (calculated value) by the following equation using the focal plane exposure Hm from the calculation above.

$$S (calc) = \frac{10}{Hm}$$

Note 1: This method of measurement designates the measurement using a taking lens as a standard measurement method. In the case of a camera with interchangeable lenses, the lens used for the measurement shall be specified (priority is given to the lens included in the product package, if there is any). See Explanation for the calculation equation of (4) stated above.

It is possible to measure Standard Output Sensitivity of a camera body which has standard spectral characteristics without a lens, by giving imaging surface(that is focal plane) illuminance E(lx) in an appropriate way and using the value  $Hm = E \cdot T$  in the equation (4).

Note 2: Various devices are used in many practical cases in order to the obtain exposure values described in (2). See **Annex 3 (Informative)** for specific measurement methods in such cases.

#### 6. Method of Notation

#### **6.1 Notational terms**

(1) Characteristics to be noted as a specification of 'Sensitivity' in catalogues as such are the indicators of Standard Output Sensitivity (symbol: SOS), and/or Recommended Exposure Index (symbol: REI). The use of both or either shall be acceptable. When both are listed, Standard Output Sensitivity shall come first, followed by Recommended Exposure Index. It is also acceptable to use the terms 'Standard Output Sensitivity' and/or 'Recommended Exposure Index' themselves as notational terms of respective sensitivity indicators instead of using the

general term 'Sensitivity'. When using symbols, it should be shown the full terms in adequate position such as the neighbours of assigned values or the margin.

(2) When assigned values are noted as sensitivity indicators in catalogues or instruction booklets, either **Standard Output Sensitivity** or **Recommended Exposure Index** shall be listed in principle.

However, the above is not necessarily adopted in the case that assigned values have already been listed as specifications in other sections of the instruction booklets or catalogues, and also the descriptions of assigned values are not listed as specifications, for example:

- (a) A description of assigned values in the explanations of sensitivity in other (not specific) sections.
- (b) The indication of assigned values on the camera body itself pertaining to the operation of the exposure device.

Furthermore, when the assigned values of the two sensitivity indicators are the same, the distinguishing descriptions may be omitted.

For the illuminations, **Daylight** is mandatory and **Tungsten** is optional. When resulted values of **Daylight** are listed, the description of the subjective illumination may be omitted, and also the term 'daylight' may be included. In the case of **Tungsten**, the term 'tungsten' shall appear in the list of the resulted values.

(3) The word 'CIPA' may be used to specify that assigned values are in line with this standard. And the description of "ISO" may also be used for the notation, in accordance with ISO 12233.

#### 6.2 Assigned values to be listed

(1) Assigned values of sensitivity indicators described as the specifications to be listed in catalogues as such shall be the results rounded from an actual value into a representative value by using Table 1 in chapter 7. In other words, they shall be the ones selected from the values shown in the column of assigned value.

Notwithstanding, the rule above in this clause has an exception of adoption such as a list of characteristic values aiming to provide an information on piece-to piece variations in individual products targeting advanced users (for example, individual data sheets).

(2) A case where assigned values are different in the same camera depending on a function mode:

When the value under a particular mode is represented, priority shall be given to the value of the function mode with the highest probability of use such as 'default-setting', and it is desirable to specify the particular function mode along with the value.

When every assigned value of different function modes is listed, each of the corresponding function modes shall be specified.

(3) If an assigned value changes depending on various conditions including environmental

conditions, the conditions shall be clearly mentioned. For example there are some cases where the standard output sensitivity varies depending on the value of F due to structural factors of an image pickup device, etc. If this change in sensitivity affects the assigned value mentioned above, the measurement conditions (F-value) shall be mentioned. If no conditions are mentioned, general condition of use is assumed.

#### 6.3. Examples of Notations

- (Example 1) Respectively descriptions of two types of indicators

  Sensitivity: Standard Output Sensitivity 125/Recommended Exposure Index 100
- (Example 2) Single description of one type

Sensitivity: 100 (Standard Output Sensitivity)

(Example 3) Single description of a symbol with a full term shown in adequate position Sensitivity: 100 (REI)

(\* REI: Recommended Exposure Index)

(Example 4) Single description with notation of CIPA

Sensitivity: 100 (CIPA Standard Output Sensitivity)

- (Example 5) Omission of description of type with notation of CIPA, when Standard Output Sensitivity and Recommended Exposure Index of the camera have the same values
- (Example 6) With notation of ISO in the case of Example 1

Sensitivity/Standard Output Sensitivity: ISO 125

Recommended Exposure Index: ISO 100

Sensitivity: 100 (by CIPA standards)

(Example 7) With notation of ISO in the case of Example 2

Sensitivity: ISO 100 (Standard Output Sensitivity)

(Example 8) With notation of ISO in the case of Example 3

Sensitivity: ISO 100 (REI)

(\* REI: Recommended Exposure Index)

- (Example 9) Direct description of the term of an indicator with notation of ISO Standard Output Sensitivity: ISO 100
- (Example 10) With notation of ISO in the case of Example 5

Sensitivity: ISO 100

(Example 11) Description of type not omitted in the case of Example 10

Sensitivity: ISO 100 (Standard Output Sensitivity/Recommended Exposure Index)

#### 7. Conversion into assigned values from actual (calculated) values

Table 1. Conversion table of assigned values from actual (calculated) values

Actual value		Assig. val.	Actual value		Assigned value		
≥	<	(Rep. val.)	≥	<	(Represe	entativ	e value)
8.909	11.22	10	_	_		_	
11.22	14.14	12	11220	14140	12500	or	12800
14.14	17.82	16	14140	17820	16000		
17.82	22.45	20	17820	22450	20000	•	
22.45	28.28	25	22450	28280	25000	or	25600
28.28	35.64	32	28280	35640	32000		
35.64	44.90	40	35640	44900	40000		
44.90	56.57	50	44900	56570	50000	or	51200
56.57	71.27	64	56570	71270	64000		
71.27	89.09	80	71270	89090	80000		
89.09	112.2	100	89090	112200	100000	or	102400
112.2	141.4	125	112200	141400	125000	or	128000
141.4	178.2	160	141400	178200	160000		
178.2	224.5	200	178200	224500	200000	or	204800
224.5	282.8	250	224500	282800	250000	or	256000
282.8	356.4	320	282800	356400	320000		
356.4	449.0	400	356400	449000	400000	or	409600
449.0	565.7	500	449000	565700	500000	or	512000
565.7	712.7	640	565700	712700	640000		
712.7	890.9	800	712700	890900	800000	or	819200
890.9	1122	1000	890900	1122000	1000000	or	1024000
1122	1414	1250	1122000	1414000	1250000	or	1280000
1414	1782	1600	1414000	1782000	1600000		
1782	2245	2000	1782000	2245000	2000000	or	2048000
2245	2828	2500	2245000	2828000	2500000	or	2560000
2828	3564	3200	2828000	3564000	3200000	•	
3564	4490	4000	3564000	4490000	4000000	or	4096000
4490	5657	5000	4490000	5657000	5000000	or	5120000
5657	7127	6400	5657000	7127000	6400000		
7127	8909	8000	7127000	8909000	8000000	or	8192000
8909	11220	10000	8909000	11220000	10000000	or	10240000

**The meaning of the symbols:**  $\geq$  is "Upper than or equal to",  $\prec$  is "Lower than"

# Annex 1 (Normative) Spectral distribution of subjective illumination

#### 1. Objective characteristics

Relative spectral power distribution of **ISO 7589-2002** in the second column (the fourth column when lenses are not used for the measurement) of the tables below **(table 1, table 2)** are designated as objective characteristics.

Note: Standard errors to evaluate whether the light being tested corresponds to the objective characteristics are defined in the next section (Section 2 of annex 1); and therefore, the 'objective characteristics' listed here may be considered as reference characteristics. Objective characteristics are the characteristics having zero error variance in the next section.

Table 1 — Relative spectral power distribution,  $S_{\lambda}$ , of ISO sensitometric daylight illuminant

$\textbf{Wavelength}, \lambda$	Photographic daylighta relative daylighta relative the ISO standard	tographic transmittance of illuminant the ISO standard		Weighted spectral sensitivities for calculating ISO/SDI of daylight illuminant		
	power	lens	(daylight transmitted by lens)	Blue	Green	Red
nm	D <sub>55</sub>	₹ (λ)	$S_{\lambda} = D_{55} \overline{\tau} (\lambda)$	$W_{B}(\lambda)$	$W_{G}(\lambda)$	$W_{R}(\lambda)$
350	28	0,00	0			
360	31	0,07	2,17	1		
370	34	0,23	7,82	2		
380	33	0,42	13,86	5		
390	38	0,60	22,80	9		
400	61	0,74	45,14	14		
410	69	0,83	57,27	17		
420	72	0,88	63,36	19		
430	68	0,91	61,88	19		
440	86	0,94	80,84	17		
450	98	0,95	93,10	15		
460	100	0,97	97,00	13		
470	100	0,98	98,00	9	1	
480	103	0,98	100,94	5	1	
490	98	0,99	97,02	2	1	
500	101	0,99	99,99	1	2	
510	101	1,00	101,00	1	3	
520	100	1,00	100,00		5	
530	104	1,00	104,00		8	
540	102	1,00	102,00		15	
550	103	1,00	103,00		24	1
560	100	1,00	100,00		12	1
570	97	1,00	97,00		13	1
580	98	1,00	98,00		10	2
590	91	0,99	90,09		3	3
600	94	0,99	93,06		1	5
610	95	0.99	94,05			7
620	94	0,98	92,12			9
630	90	0,98	88,20			14
640	92	0,97	89,24			21
650	89	0,97	86,33			26
660	90	0,96	86,40			18
670	94	0,95	89,30			4
680	90	0,94	84,60			1
690	80	0,94	75,20			
Data for $D_{55}$ daylight from CIE Publication 15.2 — 1986.						

Table 2 — Relative spectral power distribution,  $S_{\lambda}$ , of ISO sensitometric studio tungsten illuminant

Wavelength, $\lambda$	Studio tungsten relative power the ISO standa		ISO sensitometric studio tungsten illuminant	Weighted spectral sensitivities for calculating ISO/SDI of studio tungsten illuminant		
	, , , , , , , , , , , , , , , , , , , ,	lens	(studio tungsten transmitted by lens)	Blue	Green	Red
nm	$P_{\lambda}$	<u>τ</u> (λ)	$S_{\lambda} = P_{\lambda} \overline{\tau} (\lambda)$	$W_{B}(\lambda)$	$W_{G}(\lambda)$	$W_{R}(\lambda)$
350	1	0,00	0	1		
360	3	0,07	0,21	2		
370	5	0,23	1,15	5		
380	8	0,42	3,36	12		
390	12	0,60	7,20	22		
400	16	0,74	11,84	32		
410	20	0,83	16,60	40		
420	24	0,88	21,12	44		
430	29	0,91	26,39	45		
440	34	0,94	31,96	40		
450	38	0,95	36,10	36		
460	43	0,97	41,71	31		
470	48	0,98	47,04	21	1	
480	53	0,98	51,94	11	1	
490	59	0,99	58,41	5	1	
500	64	0,99	63,36	2	2	
510	70	1,00	70,00	1	3	
520	76	1,00	76,00		5	
530	81	1,00	81,00		8	
540	88	1,00	88,00		15	
550	94	1,00	94,00		24	1
560	100	1,00	100,00		12	1
570	105	1,00	105,00		13	1
580	111	1,00	111,00		10	1
590	116	0,99	114,84		3	2
600	122	0,99	120,78		1	3
610	127	0,99	125,73			4
620	132	0,98	129,36			5
630	138	0,98	135,24			8
640	143	0,97	138,71			13
650	148	0,97	143,56			15
660	153	0,96	146,88			11
670	157	0,95	149,15			3
680	162	0,94	152,28			0
690	167	0,94	156,98			

#### 2. Criterion of spectral power distribution error for practical light

The requirements for a practical light used as subjective illumination are follows: **SDI** (**Spectral Distribution Index**) is obtained in accordance with 5.3 in **Chapter 5 of ISO 7589**, and it satisfies the error criterion stipulated in 5.4 in the same chapter. Specifics are described below in sections 2.1 and 2.2.

#### 2.1 How to obtain SDI

Let the relative spectral distribution of the practical light to be evaluated be  $L(\lambda)$  (where  $\lambda$  is a wavelength).

Using relative spectral transmittance  $\tau(\lambda)$ , of the **ISO standard lens** in the third column of the above **tables 1 and 2**, and weighted spectral sensitivities  $Wc(\lambda)$ , of three colours, namely blue, green and red, which are listed in three columns at the right side of each table (**table 1 for daylight and table 2 for tungsten**), response **Rc** to each colour can be calculated by the equation below

$$\mathbf{R}_{\mathrm{C}} = \int_{0}^{\infty} \mathbf{W}_{\mathrm{C}}(\lambda) \mathbf{x} \mathbf{L}(\lambda) \mathbf{x} \boldsymbol{\tau}(\lambda) d\lambda$$

(Where C represents one of three colours: B, G or R).

In reality, however, the dispersion value at each **10 nm** of wavelength listed in each table is calculated as the following equation shows:

$$\mathbf{R}_{\mathrm{C}} = \sum_{\lambda=350}^{700} \mathbf{W}_{\mathrm{C}}(\lambda) \mathbf{x} \mathbf{L}(\lambda) \mathbf{x} \mathbf{\tau} (\lambda)$$

(When measuring without a taking lens, adopt  $\tau(\lambda) = 1$  in the equation above.)

Calculate  $\log_{10} Rc$  to two decimal places for each response, and multiply the each difference with the minimum value of these three values by one hundred respectively. The obtained values, which are arranged in the order of Blue, Green, and Red with slash symbols in between, are called the 'Spectral Distribution Index'.

**Note:** From the definition above, it is derived that whenever the minimum colour index is zero, the other two indexes must be positive whole numbers. The SDI itself is defined above. Thus, the relationship among the three indexes is relative and only the difference among them has any meaning. Therefore, if the same value is added or subtracted, the resulting figures have absolutely the same meaning.

#### 2.2 Error criterion

Index value for blue of the subjective illumination shall be **within**  $\pm 4$  of that for green, and the value for red **within**  $\pm 3$  of that for green.

**Note:** An example of a light source satisfying the above error criterion for **daylight illuminants D55** is described in **Annex 4 (Informative)**.

## Annex 2 (Normative) White Balance adjustment for cameras

White balance of a camera shall be adjusted adequately to the measured light source. Specific provisions are described below.

(a) No standard is applicable to a camera without a **WB** adjustment function (including monochrome cameras).

Apply one of (b) $\sim$ (e) provided below to a camera with a WB adjustment function.

- (b) When the light source is daylight and a camera is manually adjustable to a preset WB value of a camera with a setting position described with the term 'daylight' or a similar expression, a measurement can be performed by using this position.
- (c) When the light source is tungsten and a camera is manually adjustable to a preset WB value of a camera with a setting position described with the term 'tungsten' or a similar expression, a measurement can be performed by using this position.
- (d) When a camera is equipped with an automatic WB function, a measurement can be performed while keeping the function activated. If the adjusted value can be locked once automatically adjusted (WB lock), a measurement shall be performed while keeping it locked.
- (e) Even in the following cases:
- When a camera does not fall under any of the provisions listed above (one having a WB adjustment function but no preset value corresponding to the light source).
- When a camera that falls under a provision listed above and its WB error can be made smaller.

a measurement can still be performed while keeping the adjustment in such a way so that the WB error under the measuring light source is kept at a minimum.

Note 1: WB adjustment function shall work prior to the completion of the photographic recording. (In other words, WB adjustment function shall not be used for measurement during the playback.)

Note 2: The degree of **WB error** in (e) can be calculated by the digital RGB values of the playback signal on the remarkable part of the chart as shown in the following equation.

 $\{ (\mathbf{R} - \hat{\mathbf{G}})^2 + (\mathbf{B} - \mathbf{G})^2 \}^{1/2}$ , and the obtained value can be used as evaluation value.

Note 3: For the public disclosure of Standard Output Sensitivity, the following two information items shall be recorded so as to be readily disclosed:

- Information as to 'which method from  $(b)\sim(e)$  has been used'
- The 'degree of WB error when (e) is used'.

However, when the sensitivity is described in catalogues, etc., these items may be omitted.

# Annex 3 (Informative) Recommended measurement method (An example)

**Note:** Since this Annex 3 is a reference and an example, it has not been updated from the contents at the time of the 1st edition of this standard. For this reason, there are some measuring equipment that do not match the times, but a corresponding successor model or the like may be appropriately used.

#### 1. Equipment for Measurement

- · A camera being tested and designated playback software
- · A fixing apparatus for the camera: for example, a tripod
- A spot luminance meter
- A chart: Grayscale chart of  $\gamma$ =0.45; for example, IEC1146-1 Test chart No. 1 or ITE Grayscale Chart II (Dai Nippon Printing Co., Ltd.), etc.
- Lighting equipment: lamp(s) or a light box (incandescent lamp type); for example, relative colour temperature 3200 K Tungsten lamp (light intensity adjusted by single-phase auto transformer, measured by Colour temperature meter)
- · Colour temperature conversion filter: for example, LB-120 filter of HOYA Corporation
- Personal computer and analyzing software (example: Photoshop<sup>TM</sup> ver. 5 of Adobe Systems Incorporated may be used)
- · ND (neutral density) filters, etc., when necessary

#### 2. Procedures for Measurement

- (1) A camera being tested should be set up and fixed in such a position so as to be able to take an image of a chart placed under standard lighting conditions (in the case of daylight, obtain the light with spectral characteristics equivalent to D55 using colour temperature conversion filter). The following two points should be noted for this procedure:
- If a camera features a zoom function and the F-value of the lens is designated in a certain zoom position, select that position.
- Adjust the distance to the chart and the zoom in such as way so as to be able to take a full image up to the ▲ marks on four sides of the grayscale chart. (This is not always required.)
- (2) Adjust exposure values (aperture and time) in such a way so as to be able to take an image in generally good condition (so that the grey area in the background reaches around 40 to 60% of the digital output). When the camera is equipped with automatic exposure function and the exposure value is known, automatic exposure is accepted.

Also, when a camera has a gain variable function that can be fixed, use it under the fixed condition.

**Note 1:** Even if a camera has a gain (sensitivity) adjustment function that cannot be fixed, the measured value of sensitivity may be regarded as a representative value of sensitivity when the sensitivity near the reference luminance

defined in section 3.3(4) does not change. This is because an adjusted sensitivity condition is assumed to be maintaining a representative fixed state at the time of measurement. (If it is a general camera, the condition above can often be fulfilled under standard lighting conditions.) In addition, the standard lighting should be adopted under the same conditions with the same values not only for the measurement of sensitivity but also for other specifications (SN, etc.).

In addition to the above, if it is possible to maintain the adjusted sensitivity of a camera at a maximum level by reducing the luminance of the target, this is also assumed to be maintaining a representative fixed state that is different from the condition mentioned above. This enables the obtainment of another representative sensitivity, namely, the 'maximum sensitivity'.

**Note 2:** It must be noted that errors contained in the control or the reading values are directly involved in the errors of the measured sensitivity when using the exposure value determined by the exposure control function of a camera. It is possible to reduce such measurement errors. An exposure time (shutter speed), for example, can be experimentally measured by measuring the image blurring by taking an image of a given moving subject. On the other hand, there is no effective way to reduce errors in aperture correction (F-value). Nonetheless, the full-open F-value of the lens is known to be trustworthy, and it is possible to reduce the errors by using such open aperture. (Note 3 below shows an example of measurement using an open aperture.)

**Note 3:** When the exposure value of a camera with automatic exposure function is not displayed, its exposure value can be obtained by the following method of photography (however, it must be noted this may also induce some errors when ND filter is used). This is possible only when the camera in question possesses a Fixed Gain Mode (one with no auto gain-up function or one whose auto gain-up function can be deactivated).

- When an image is taken, the aperture should be held fully open. In other words, insert ND filter in front of the camera if necessary, and capture the timing when the level of output image is lowered, that is, when the aperture is open and shutter speed is the longest exposure time.
- (3) Playback the image that has been taken, and analyze the output level. Note The sampling area can be obtained by selecting a middle range of each gradation of grayscale (preferably several hundred pixels or more) and calculate the mean values.

Take a measurement at each step. Select one step higher and one lower than the reference level D (example: 118 / 8 bit) and record the output level DU and DL (DU>D>DL) values, then measure the corresponding subject luminance values, BU and BL (luminance at the grayscale area), using a spot luminance meter. (When an ND filter is used for photography, measure its luminance by placing the same ND filter at the front of the luminance meter.)

Note: when a colour image is measured, for example when using Photoshop, the level can be measured as follows:

- · Convert the target image into grayscale image while designating the colour space as sRGB.
- · Measure the level by using either the 'information' display function or 'histogram' function.

#### (4) Calculation of Standard Output Sensitivity

Measured exposure values at two steps are expressed as HU and HL (HU>HL). Each H (unit  $lx \cdot s$ ) is obtained from the following equation by photographic subject luminance B (cd/m<sup>2</sup>), exposure time T(s), and aperture value F.

$$\mathbf{H} = \frac{0.65 \times \mathbf{B} \times \mathbf{T}}{\mathbf{F}^2}$$

Calculate exposure value Hm corresponding to a reference level D by using the following equation.

$$Hm = \frac{(DU - D) \times HL + (D - DL) \times HU}{DU - DL}$$

**Note:** When either DU or DL is identical to the value of D, H, which directly corresponds to them, becomes the same value of Hm, instead of interpolating. In this case, it is obvious that the rule in this text (5. Measurement Method) does not change. Interpolating method demonstrated above is simply an example of a practical substitution method of measurement, extending the consideration to the case where it is difficult to synchronize the remarkable part of the chart exactly to the value of D.

The interpolating equation mentioned above may contain some errors since it uses a collinear approximation (in the case of typical gamma characteristic of  $\gamma$ =0.45, maximum of 2%). In order to reduce the error, use interpolating value assuming typical  $\gamma$  instead of using collinear approximation (or even more preferably, one based on the gradation characteristics of the camera being tested). A similar error reduction effect may be obtained in a relatively simple manner by the logarithmic collinear approximation (to bring the results obtained by linear interpolation on a double logarithmic plot back to antilogarithm).

# Annex 4 (Informative) An example of Daylight Simulator equivalent to D55

As far as D55 daylight luminance is concerned, it is found in the calculation that a light source within the error range stipulated in **Annex 1** can be obtained by combining a 3200 K tungsten lamp and a HOYA LB-120 Glass Filter (HOYA Optics Corporation).

Calculated value of SDI is 0/3/1.

However, the calculation was conducted under the following conditions:

- Spectral distribution characteristics of the tungsten lamp are substituted by blackbody radiation characteristics with the same temperature.
- Data on the filter spectral characteristics are substituted by the typical value listed in the catalogue.

Therefore, the calculation does not guarantee that the error obtained in practice will lie within the error range described above, nor is using the filter mentioned above recommended.

# **Explanation**

This explanation describes the items and the related matters stipulated and included in this standard and its Annexes, and thus it does not constitute a part of this standard.

#### 1. Standard Output Sensitivity

ISO 12232, established in 1998, stipulates ISO Speed of digital cameras. However, it stipulates that the main value of 'ISO noise speed' should not be applied to a camera with lossy compression because the values vary due to the compression process during image recording. Therefore, it had application restrictions on general consumer cameras.

In the meantime, the term "sensitivity" (or ISO speed) of film is an exposure index based on the gradation characteristics. If it is accepted that the sensitivity of digital cameras should be stipulated in a similar manner, the sensitivity can be defined by using exposure values that give the prescribed standard output level. Similarly, the sensitivity of video cameras (including minimum subject luminance and standard sensitivity of professional cameras) is defined to be the standard output level of 50 IRE. ISO 12232 also stipulates 'ISO saturation speed'; which is similar to these, but a problem is that 'values are largely affected by the Knee characteristics even if the actual sensitivities are the same' because it uses the saturation level as the reference level.

Taking the above into consideration, this standard adopts the medium level on the tone curve as the sensitivity reference level. Specifically, Y-value was designated as the reference value for sensitivity measurement in the color space sRGB, which is the target of digital cameras in compliance with the Exif standard. The value of Y corresponds to a typical 18% neutral gray subject obtained by relating the maximum digital output (255 for 8 bit) to a subject reflectance rate of 100% (118 for 8 bit sRGB).

In other words, Standard Output Sensitivity (S) is stipulated as

S = 10/Hm (Where, Hm is the input luminance value to give the reference level of output =118<at 8 bit>: unit lx $\cdot$ s)

(The conversion system itself is the same as that of existing reversal films or the **ISO 12232** standard.)

#### 2. Supplement to the definition of Standard Output Sensitivity (3.2 in the main text)

## **2.1** Evaluated signal (5.1 in the main text )

In order to be able to measure and examine cameras available in the market, it is necessary to use the standard playback signal of personal computers instead of using the 'Y' signal preset inside the camera. It is also necessary to establish a uniform definition of luminance signal 'Y'. For that matter, color cameras have options; and this standard adopts sRGB luminance-generation coefficient set by IEC 61966-2-1. (For the sake of brevity, each digital

RGB signal is expressed simply in R, G, or B, in the main text of this standard. But in fact, each digital RGB signal is the signal processed by  $\gamma$  conversion, and the sRGB luminance-generation coefficient should be applied to linear luminance values. With that in mind, the signal processed by  $\gamma$  conversion is indicated with an apostrophe below.)

Exif standard (ver. 2.1 or earlier), which is the standard image file of digital cameras, designates a traditional matrix, Y' = 0.299R' + 0.587G' + 0.114B' as the Luminance Signal Matrix of a camera in the colour-space guideline used for the signal generation. Thus, the adoption of this matrix was considered. However, Exif also designates sRGB for the target colour space in a playback system. The following luminance signal was adopted in the end:

```
Y' = MAX \times \gamma \{0.2126\gamma^{-1}\{R'/MAX\} + 0.7152\gamma^{-1}\{G'/MAX\} + 0.0722\gamma^{-1}\{B'/MAX\} \}
```

Max is normalization coefficient (= digital maximum output value: 255 for 8 bit)

 $\gamma\{\ \}, \gamma^{-1}\{\ \}$  are sRGB gamma characteristics and its inversion (linearization) characteristics stipulated in IEC 61966-2-1

Y' is the luminance signal obtained from the reapplication of gamma curve to the luminance Y defined by the equation above. The equation above applies sRGB luminance-generation coefficient to luminance-linear values (R, G, B), which are obtained by adopting inverted gamma curve of each digital RGB signal (R'G'B') using the sRGB (IEC 61966-2-1).

However, neither equation has much influence on the actual measured values because the full correction of white balance is assumed. (If the photographic subject is achromatic; in other words, if the perfect white balance on the subject under test is maintained, the value obtained from the two equations above would be identical.)

Meanwhile, when mentioning sRGB, the linearized function is defined as  $\gamma$  in many cases, assuming a display type. However, as being in line with usage in the realm of the camera system, the function transforming into tone compressed signal from the linear signal is defined as  $\gamma$  in this standard, and the characteristic associated with display systems or the linearization function to restore the linear parameters is expressed as  $\gamma^{-1}$ .

#### 2.2 Reference level (5.2 in the main text)

In the colour space of digital cameras being tested (sRGB for DCF cameras), the Y-value corresponding to 18% standard neutral grey is designated as sensitivity value when the digital maximum output (255 for 8 bit) corresponds to a reflectance rate of 100%.

The level of sensitivity in itself is voluntary, thus, though it is not tolerated at around saturation level due to the defect caused by Knee characteristics, there is no single and absolute point of definition as long as the tone is in the middle range; therefore, it becomes necessary to select some value. Needless to say, it is then necessary to consider the compliance with the Film ISO speed and exposure control system of the existing photography world. Thus, this standard

adopts 18% neutral grey as a ground for selecting the reference level of sensitivity.

18% grey has long been used as the standard reflector in the photographic area for the evaluation of exposure control. This means it is set around the medium tone range. In other words, the logarithmic centre (logarithmic average) is measured at 18% when maximum and minimum values of the diffuse reflectance distribution of the subject are about 98% and 3.3% respectively. In other words, the value has even latitude against excess or deficiency of exposure caused by exposure errors, and this has been used as a substitute standard for evaluation to represent general photographic subjects. Therefore, it is relatively easy to obtain compliance with the exposure control system.

# 3. Supplement to measurement conditions of Standard Output Sensitivity (5.3 in the main text)

#### 3.1 Environmental conditions (5.3.2 in the main text)

The conditions are in line with ISO 12232, which stipulates that the humidity standard should be recommended, but the similar standard of ISO 14524 stipulates that it is mandatory. It has been decided that the recommendation does not have specific meaning. (There is a possibility of misstatement.)

### 3.2 Exposure adjustment ( (8) of 5.3.4 Camera settings in the main text )

If the exposure time is too long, a dark current could be generated; and if it is too short, a smear could be superposed on the real subject signal. Thus, some restrictions are placed on the exposure time.

# 4. Supplement to calculation of the focal plane exposure ( (4) of 5.5 Method of Measurement in the main text )

Unlike film, it is not possible for a user to measure the 'sensitivity' of a camera having a built-in lens without the lens. Most consumer digital cameras have a built-in lens. Even if a camera has interchangeable lenses, it is still generally difficult to know where to separate the system. (For example, it is particularly problematic when the optical system is so designed that an infrared-cut filter is mounted on the subject side from the major lens in order to switch to high-sensitivity (infrared) photography). Taking these factors into consideration, a camera with a mounted lens has been designated as the basic state.

In this case, when the correction coefficient for the light-reducing effect of a lens represented by transmission factor is expressed as  $\tau$  (all other elements, except for aperture, such as 'subject-distance coefficient', 'flare coefficient', and 'cosine 4 power-rule correction coefficient' are included in this definition) the exposure in the focal plane Hm is calculated as follows:

$$\mathbf{Hm} = \frac{\tau \mathbf{x} \pi \mathbf{x} \mathbf{B} \mathbf{x} \mathbf{T}}{4 \mathbf{x} \mathbf{F}^2}$$

In that case, with due consideration for the compliance with other international standards such as ISO 12232 and ISO 14524 (OECF), the correction coefficient mentioned above representing a camera with mounted lens would be as follows:

$$\tau \times \pi/4 = 0.65$$
  $(\tau = 0.828)$ 

(refer to **ISO 12232 Annex B**)

#### 5. Supplement to listing of information of White Balance (Note 3 of Annex 2)

This standard designates to keep the information on white balance as mandatory; it also stipulates that this information may be omitted on the condition that sensitivity notation is expressed. In reality, there is not much advantage of presenting such additional information since numerical influence from WB adjustment on the measurement of sensitivity is small, on the contrary, it could even cause unnecessary confusion. Therefore, it is rather recommended to omit the information.

#### 6. Supplement to measurement using open aperture (Notes 2 and 3 of Annex 3(2))

When calculating sensitivity based on the nominal open F-value, using the open aperture metering method, measurement errors may occur when the specification of open F-value is not satisfied (darker than the nominal value). The result is the lower sensitivity in calculation, and this does not give an advantage.

# 7. Cameras unable to measure Standard Output Sensitivity (Relating to Note 3 of Annex 3-(2))

Sensitivity is measurable in the end, if either one of the following conditions is fulfilled:

- (a) An exposure value can be known. (having a manual exposure function, or otherwise, exposure value on display and/or data on image file)
- (b) A gain value can be fixed.

However, if neither condition (a) nor (b) is fulfilled, the sensitivity (of the product itself without dismantlement, etc.) is not measurable (by someone other than the manufacturer).

#### 8. Recommended Exposure Index

It is not uniformly defined what an 'appropriate exposure' is, because it depends heavily on the preference of the individual subjects or photographers. Nevertheless, in light of the importance of the exposure of cameras, attempts have been made to set up a 'standard exposure', which is to help attain maximum rate of success. In many cases, the auto exposure adopted by makers of

digital cameras is the embodiment of such 'standard exposure' or 'recommended exposure by manufactures to help attain maximum rate of success'. (However, this is not to say such recommended exposure itself by the manufacturer is the 'appropriate exposure' for a photographer in practice.) In recent years, various methods have become available to process luminance information, using partial photometry information taken from multiple parts of the subject, including Pattern Photometry or Peak Photometry.

On the other hand, when the aperture or shutter speed is to be obtained by using a reflective stand-alone exposure meter or accessory strobe, the average photometry values are used. Adequate preset value of film sensitivity (exposure index) must be adapted to such equipment during photography, in which case the recommended value preset by the maker (in other words, the value to obtain the 'standard exposure' mentioned above) is the 'Recommended Exposure Index'.

The preset value of the film sensitivity or exposure value corresponds to the exposure on the imaging surface (the inverted number based on an appropriate constant number in practice). Therefore, an indication of Recommended Exposure Index is the same as showing the value of 'average exposure in the focal plane recommended by makers for the average photometry' or 'average exposure in the focal plane obtained as a result of photography by using auto exposure with traditional average photometry'. Moreover, constant number  $10 \ [lx \cdot s]$  of REI = 10/Em, which is used to convert the exposure in the focal plane into the exposure index, has been set the same as the relationship between ISO speed and exposure value in the focal plane stipulated in section 5.4 Exposure in the focal plane of ISO 2721 Cameras–Automatic controls of exposure.

#### 9. Relation between Recommended Exposure Index and Automatic Exposure systems

When the camera in question is equipped with a **traditional** (i.e. simple) automatic-exposure function, the average exposure in the focal plane given by the automatic-exposure function to a uniform photographic subject must naturally be equal to the above-mentioned Em value (A value in REI=10/Em) recommended by the vendor of the camera.

In this case, the following equation is satisfied:

$$AV + TV = BV + log_2(0.32 \times REI)$$

$$(Where: AV = log_2F^2$$

$$TV = -log_2T[s]$$

$$BV = log_2\{B[cd/m^2]/(0.32 \times K)\}^{note 1})$$

Therefore, the value of REI can be presumed from this relationship by measuring the performance of the automatic-exposure function. However it is true only under the assumption of perfect automatic exposure function, thus this presumption depends on the performance of

the exposure control system. note 2

On the contrary, a specific relationship with automatic-exposure function does not exist in a camera with **advanced** automatic functions; for example, when the controller varies the level of exposure in the focal plane in accordance with the patterns or absolute luminance value of a photographic subject. Thus, in this case, there is no way to measure REI directly or indirectly.

Note 1: The application of  $\underline{BV = \log_2 - \{0.292 \text{ x B [cd/m}^2]/k \}}$  is accepted. K refers to the metric and k refers to the imperial system of calibration factor. The former is mostly used for specifications of a stand-alone exposure meter and the latter for a light box for adjustment of the automatic-exposure controller. Standard settings in recent years seem to adopt K=14 or k=1.3 although it is left to the discretion of each manufacturer. When BV values are obtained directly from an exposure meter to measure luminance of a photographic subject instead of using a luminance meter, the calibration factor of the exposure meter results in being assumed.

Note 2: This standard stipulates only the Recommended Exposure Index (recommended average exposure in focal plane), and does not stipulate the performance of the automatic-exposure function.

#### 10. Deliberation Committee

The deliberations for the drafting of this Standard were conducted mainly by a sub-working group under the Technical Working Group of the Standardization Committee, namely, the **Sensitivity Sub-Working Group.** In addition, the deliberations started in January 2000 by the Sensitivity Sub-Working Group (Chief: Hideaki Yoshida / OLYMPUS OPTICAL CO., LTD. Present OLYMPUS CORPORATION) in the Digital Camera Technology Sub-committee of the Japan Camera Industry Association (Voluntary association: resolved in June 2002), which is the former body of the Camera & Imaging Products Association, and later succeeded by the Sensitivity Sub-Working Group of this association.

And the deliberations to revise to the 2nd edition has been carried out by the Sensitivity Sub-Working Group newly launched in September in 2019.

The following are the committees involved in the standardization.

#### **Standardization Committee**

Chair	Suzuki Masao	Canon Inc.
Vice Chair	Satoh Hitoshi	FUJIFILM Corporation
Vice Chair	Imafuji Kazuharu	NIKON CORPORATION
Vice Chair	Yoshida Hideaki	Olympus Corporation
Vice Chair	Fukushima Tsumoru	Panasonic Corporation
Vice Chair	Katoh Naoya	Sony Imaging Products & Solutions Inc.

## **Technical Working Group**

Leader Udagawa Yoshiro Canon Inc.

Sub Leader Houshuyama Hideo NIKON CORPORATION Sub Leader Yoshida Hideaki Olympus Corporation

## **Sensitivity Sub-Working Group**

Chief Yoshida Hideaki Olympus Corporation

Paul Hubel Apple, Inc.
Mori Munehiro Apple, Inc.
Takagi Atsushi Canon Inc.
Udagawa Yoshiro Canon Inc.
Ogasawara Tsutomu Canon Inc.

Nakamura Satoshi Sony Imaging Products & Solutions Inc. Matsumura Yasutoshi Sony Imaging Products & Solutions Inc.

Houshuyama Hideo NIKON CORPORATION Hirama Nobutaka NIKON CORPORATION Fukushima Tsumoru Panasonic Corporation

Koyanagi Masahiko HUAWEI TECHNOLOGIES JAPAN K.K.

Kondo Shigeru FUJIFILM Corporation Terauchi Masakazu Ricoh Company, Ltd. Any and all standards published by CIPA have been set forth without examining any possibility of infringement or violation of Intellectual Property Rights (patent right, utility model right, design right, copyright and any other rights or legal interests of the same kind).

In no event shall CIPA be liable in terms of Intellectual Property Rights for the contents of such standards.

# CIPA DC-004-2020

Published in September 2020

Published by Camera & Imaging Products Association

MA Shibaura Building 3F, 3-8-10 Shibaura, Minato-ku, Tokyo

108-0023

TEL 03-5442-4800 FAX 03-5442-4801

## All rights reserved

No part of this standard may be reproduced in any form or by any means without prior permission from the publisher.