



T5-D2 Right-Hand 6-DoF Hold During In-Place Stepping

(a) Position Hold Error



(b) Orientation Hold Error



Transient peak appears at gait handoff; steady-state passes 20 mm / 5 deg thresholds.