RK3399 LOG EXPLANATION

发布版本:1.0

作者邮箱: xig@rock-chips.com

日期:2017.12

文件密级:公开资料

前言

概述

产品版本

芯片名称	内核版本
RK3399	4.4

读者对象

本文档(本指南)主要适用于以下工程师:

技术支持工程师

软件开发工程师

硬件开发工程师

修订记录

日期	版本	作者	修改说明
2017-12-26	V1.0	许剑群	

RK3399 LOG EXPLANATION RK3399开机LOG说明

RK3399开机LOG说明

- 1 DDR Version 1.00 return(-1)
- DDR Version 1.00 return(-1)
- 3 DDR Version 1.00 return(-1)

```
DDR Version 1.00 return(-1)
 5
     DDR Version 1.08 20170320
                                  //DDR Loader 版本日期
 6
                                   //DDR Loader 开始标志
     Channel 0: LPDDR3, 800MHz
 7
8
     CS = 0
                                   //DDR片选信息
9
     MR0=0x0
10
     MR1=0x0
11
     MR2=0x0
12
     MR3=0x0
13
     MR4=0x0
     MR5=0x0
14
15
     MR6=0x0
16
     MR7=0x0
17
     MR8=0x0
18
     MR9=0x0
19
     MR10=0x0
20
     MR11=0x0
21
     MR12=0x0
22
     MR13=0x0
23
     MR14=0x0
     MR15=0x0
24
25
     MR16=0x0
26
     CS = 1
                                   //DDR片选信息
27
     MR0=0x0
28
     MR1=0x0
29
     MR2=0x0
30
     MR3=0x0
31
     MR4=0x0
32
     MR5=0x0
33
     MR6=0x0
34
     MR7=0x0
35
     MR8=0x0
36
     MR9=0x0
37
     MR10=0x0
38
     MR11=0x0
39
     MR12=0x0
40
     MR13=0x0
41
     MR14=0x0
42
     MR15=0x0
43
     MR16=0x0
     Bus Width=32 Col=10 Bank=8 Row=15/15 CS=2 Die Bus-Width=32 Size=2048MB
44
     Channel 1: LPDDR3, 800MHz
                                  //DDR通道信息
45
46
     CS = 0
                                   //DDR片选信息
47
     MR0=0x58
     MR1=0x58
48
49
     MR2=0x58
50
     MR3=0x58
51
     MR4=0x2
52
     MR5=0x1
53
     MR6=0x5
54
     MR7=0x0
55
     MR8=0x1F
     MR9=0x1F
56
```

```
57
     MR10=0x1F
58
      MR11=0x1F
59
     MR12=0x1F
     MR13=0x1F
60
61
     MR14=0x1F
62
     MR15=0x1F
63
     MR16=0x1F
     CS = 1
                                   //DDR片选信息
     MR0=0x58
65
     MR1=0x58
66
67
     MR2=0x58
68
     MR3=0x58
69
     MR4=0x2
70
     MR5=0x1
71
     MR6=0x5
     MR7=0x0
72
73
     MR8=0x1F
 74
     MR9=0x1F
75
     MR10=0x1F
 76
     MR11=0x1F
77
     MR12=0x1F
78
     MR13=0x1F
79
     MR14=0x1F
80
     MR15=0x1F
81
     MR16=0x1F
82
     Bus Width=32 Col=10 Bank=8 Row=15/15 CS=2 Die Bus-Width=32 Size=2048MB //总线带宽信息
83
     256B stride
                                   //交织信息
     ch 0 ddrconfig = 0x101, ddrsize = 0x2020
84
     ch 1 ddrconfig = 0x101, ddrsize = 0x2020
85
86
      pmugrf_os_reg[2] = 0x3AA0DAA0, stride = 0xD //PMUGRF信息
87
                                     //DDR Loader 结束标志"OUT"
      Boot1: 2017-06-09, version: 1.09 //MINILOADER开始
88
89
     CPUId = 0x0
90
     ChipType = 0x10, 1828
91
      SdmmcInit=2 0
92
     BootCapSize=100000
93
     UserCapSize=14910MB
     FwPartOffset=2000 , 100000
94
95
     SdmmcInit=0 20
      StorageInit ok = 69117
96
97
     LoadTrustBL
     No find bl30.bin
98
99
     Load uboot, ReadLba = 2000
     Load OK, addr=0x200000, size=0x72b94 //MINILOADER结束
100
      RunBL31 0x10000
                                         //BL31的COMMIT号
101
102
      NOTICE: BL31: v1.3(debug):9f93abc
     NOTICE: BL31: Built : 10:18:20, Jul 27 2017
103
104
     NOTICE: BL31: Rockchip release version: v1.1
105
      INFO: GICv3 with legacy support detected. ARM GICV3 driver initialized in EL3
106
      INFO: plat_rockchip_pmu_init(1089): pd status 3e
107
      INFO: BL31: Initializing runtime services
108
      INFO:
              BL31: Initializing BL32
109
     INF [0x0] TEE-CORE:init_primary_helper:337: Initializing (1.1.0-106-g2d5da6a #1 Fri Oct
```

```
20 01:35:40 UTC 2017 aarch64)
110
111
      INF [0x0] TEE-CORE:init_primary_helper:338: Release version: 1.1
112
113
     INF [0x0] TEE-CORE:init teecore:83: teecore inits done
114
      INFO:
              BL31: Preparing for EL3 exit to normal world
      INFO: Entry point address = 0x200000 //UB00T地址
115
116
      INFO: SPSR = 0x3c9
                                             //BL31结束标志
117
118
119
      U-Boot 2014.10-RK3399-06-02526-g45a462c (Oct 25 2017 - 09:05:48) //UB00T开始标志
120
121
     CPU: rk3399
122
     cpu version = 0
123
     CPU's clock information:
     apll1 = 816000000HZ
124
125
     apllb = 24000000HZ
126
     gpl1 = 800000000HZ
127
     aclk periph h = 133333333HZ, hclk periph h = 66666666HZ, pclk periph h = 33333333HZ
      aclk periph 10 = 100000000HZ, hclk periph 10 = 100000000HZ, pclk periph 10 = 50000000HZ
128
129
     hclk periph 11 = 100000000HZ, pclk periph 11 = 50000000HZ
     cpll = 800000000HZ
130
131
     dp11 = 800000000HZ
     vpl1 = 24000000HZ
132
     npl1 = 24000000HZ
133
134
     pp11 = 676000000HZ
135
     Board: Rockchip platform Board
136
     Uboot as second level loader
137
     DRAM: Found dram banks: 1
138
     139
     Reserve memory for trust os.
1.40
      dram reserve bank: base = 0x08400000, size = 0x01200000
141
     128 MiB
142
     SdmmcInit = 0 20
143
      storage init OK!
144
     Using default environment
145
146
     GetParam
147
     Load FDT from resource image.
148
      power key: bank-0 pin-5
149
     can't find dts node for fixed
     usb bc: can find node by path: /dwc-control-usb/usb_bc
150
151
     dwc_otg_check_dpdm: usb bc disconnected
152
     pmic:rk808
153
     can't find dts node for pwm1
154
     set pwm voltage ok,pwm id =2 vol=900000,pwm value=16
155
     CPU's clock information:
     apll1 = 816000000HZ
156
157
     apllb = 24000000HZ
158
      gpll = 800000000HZ
159
      aclk periph h = 133333333HZ, hclk periph h = 66666666HZ, pclk periph h = 33333333HZ
160
      aclk periph 10 = 100000000HZ, hclk periph 10 = 100000000HZ, pclk periph 10 = 50000000HZ
     hclk periph 11 = 100000000HZ, pclk periph 11 = 50000000HZ
161
```

```
162
      cpll = 800000000HZ
163
      dpll = 800000000HZ
164
      vpl1 = 24000000HZ
165
     npll = 24000000HZ
      pp11 = 676000000HZ
166
      Can't find dts node for fuel guage cw201x
167
     can't find dts node for ec-battery
168
169
      Can't find dts node for charger bq25700
170
      SecureBootEn = 0, SecureBootLock = 0
171
172
      #Boot ver: 2017-10-25#1.09
173
      empty serial no.
174
      normal boot.
175
     checkKey
176
      vbus = 0
      no fuel gauge found
177
178
     no fuel gauge found
179
      read logo on state from dts [1]
180
      no fuel gauge found
181
      Using display timing dts
      Detailed mode clock 160000 kHz, flags[a]
182
     H: 1200 1320 1340 1361
183
184
      V: 1920 1941 1944 1962
185
     bus format: 100e
186
      rk lcdc - 0 dclk set: dclk = 160000000HZ, pll select = 1, div = 1
187
     final DSI-Link bandwidth: 1064 Mbps x 4
188
     failed to wait for phy lock state
189
     Hit any key to stop autoboot: 0
190
     load fdt from resouce.
191
      Secure Boot state: 0
192
      kernel @ 0x00280000 (0x01238008)
      ramdisk @ 0x05bf0000 (0x001e65b8)
193
194
      bootrk: do bootm linux...
195
      Loading Device Tree to 0000000005600000, end 0000000056160c3 ... OK
196
      Add bank:0000000000200000, 0000000008200000
197
      Add bank:000000009600000, 00000000eea000000
      WARNING: could not set reg FDT_ERR_BADOFFSET.
198
199
200
      Starting kernel ...
                                       //UBOOT结束标志
201
202
           0.000000] Booting Linux on physical CPU 0x0
                                                         //内核启动
        0.000000] Initializing cgroup subsys cpuset
203
204
      [ 0.000000] Initializing cgroup subsys cpu
        0.000000] Initializing cgroup subsys cpuacct
205
206
           0.000000] Initializing cgroup subsys schedtune
207
           0.000000] Linux version 4.4.103 (wmc@ubuntu) (gcc version 4.9 20140514 (prerelease)
     (GCC) ) #1185 SMP PREEMPT Tue Dec 12 14:38:48 CST 2017 //内核固件编译者和时间信息
          0.000000] Boot CPU: AArch64 Processor [410fd034]
208
          0.000000] earlycon: Early serial console at MMIO32 0xff1a0000 (options '')
209
      [
210
           0.000000] bootconsole [uart0] enabled
211
           0.000000] Reserved memory: failed to reserve memory for node 'stb-devinfo@00000000':
     base 0x0000000000000000, size 0 MiB
     Γ
           0.000000] cma: Reserved 16 MiB at 0x00000000f7000000
```

```
213
           0.0000001 psci: probing for conduit method from DT.
214
           0.000000] psci: PSCIv1.0 detected in firmware.
      Γ
215
           0.000000] psci: Using standard PSCI v0.2 function IDs
      0.000000] psci: Trusted OS migration not required
216
      0.000000] PERCPU: Embedded 21 pages/cpu @ffffffc0f6ef0000 s45504 r8192 d32320 u86016
217
           0.000000] Detected VIPT I-cache on CPU0
218
           0.000000] CPU features: enabling workaround for ARM erratum 845719
219
220
      0.000000] Built 1 zonelists in Zone order, mobility grouping on. Total pages:
     994824
           0.000000] Kernel command line: earlycon=uart8250,mmio32,0xff1a0000 swiotlb=1
221
      Γ
     androidboot.baseband=N/A androidboot.selinux=permissive androidboot.hardware=rk30board0
222
           0.000000] PID hash table entries: 4096 (order: 3, 32768 bytes)
223
           0.000000] Dentry cache hash table entries: 524288 (order: 10, 4194304 bytes)
224
           0.000000] Inode-cache hash table entries: 262144 (order: 9, 2097152 bytes)
225
           0.000000] software IO TLB [mem 0xf6ea7000-0xf6ee7000] (0MB) mapped at
     [ffffffc0f6ea7000-ffffffc0f6ee6fff]
226
           0.000000] Memory: 3930820K/4042752K available (10878K kernel code, 1632K rwdata,
      Γ
     5268K rodata, 832K init, 1069K bss, 95548K reserved, 16384K cma-reserved)
227
      Γ
           0.000000] Virtual kernel memory layout:
                         modules : 0xffffff800000000 - 0xffffff8008000000
228
      0.000000]
                                                                                 128 MB)
                         vmalloc : 0xffffff8008000000 - 0xffffffbdbfff0000 (
229
      0.0000001
                                                                                 246 GB)
                          .init : 0xffffff8009050000 - 0xffffff8009120000
           0.0000001
                                                                                 832 KB)
230
      [
231
      [
           0.0000001
                           .text : 0xffffff8008080000 - 0xffffff8008b20000
                                                                             ( 10880 KB)
                         .rodata : 0xffffff8008b20000 - 0xffffff8009050000 ( 5312 KB)
232
      Γ
           0.000000]
                           .data : 0xffffff8009120000 - 0xffffff80092b8008
233
           0.0000001
                                                                               1633 KB)
      234
      Γ
           0.000000]
                         vmemmap : 0xffffffbdc0000000 - 0xffffffbfc0000000 (
                                                                                   8 GB
     maximum)
235
      Γ
           0.0000001
                                   0xffffffbdc0008000 - 0xffffffbdc3e00000
                                                                                  61 MB actual)
                                                                            (
                         fixed : 0xffffffbffe7fd000 - 0xffffffbffec00000
236
      0.0000001
                                                                             ( 4108 KB)
           0.0000001
                         PCI I/O : 0xffffffbffee00000 - 0xffffffbfffe00000
                                                                                  16 MB)
237
      238
      Γ
           0.000000]
                         memory : 0xffffffc000200000 - 0xffffffc0f8000000
                                                                             ( 3966 MB)
           0.000000] SLUB: HWalign=64, Order=0-3, MinObjects=0, CPUs=6, Nodes=1
239
           0.000000] Preemptible hierarchical RCU implementation.
240
241
           0.000000] Build-time adjustment of leaf fanout to 64.
242
      Γ
           0.000000] RCU restricting CPUs from NR CPUS=8 to nr cpu ids=6.
243
           0.000000] RCU: Adjusting geometry for rcu fanout leaf=64, nr cpu ids=6
           0.000000] NR IRQS:64 nr irqs:64 0 //GIC初始化
244
           0.000000] GIC: Using split EOI/Deactivate mode
245
246
           0.000000] ITS: /interrupt-controller@fee00000/interrupt-controller@fee20000
           0.000000] ITS: allocated 65536 Devices @9600000 (psz 64K, shr 0)
247
      Γ
248
      0.000000] ITS: using cache flushing for cmd queue
           0.000000] GIC: using LPI property table @0x0000000009680000
249
      Γ
           0.000000] ITS: Allocated 1792 chunks for LPIs
250
      0.000000] CPU0: found redistributor 0 region 0:0x00000000fef00000
251
252
           0.000000] CPU0: using LPI pending table @0x0000000009690000
      Γ
253
      0.000000] GIC: using cache flushing for LPI property table
254
           0.000000] GIC: PPI partition interrupt-partition-0[0] { /cpus/cpu@0[0]
     /cpus/cpu@1[1] /cpus/cpu@2[2] /cpus/cpu@3[3] }
      Γ
           0.000000] GIC: PPI partition interrupt-partition-1[1] { /cpus/cpu@100[4]
255
     /cpus/cpu@101[5] }
256
      Γ
           0.000000] rockchip_clk_register_frac_branch: could not find dclk_vop0_frac as parent
     of dclk_vop0, rate changes may not work
                                                  //CLK初始化
           0.000000] rockchip_clk_register_frac_branch: could not find dclk_vop1_frac as parent
      Γ
```

```
of dclk vop1, rate changes may not work
258
           0.000000] rockchip cpuclk pre rate change: limiting alt-divider 33 to 31
259
      Γ
           0.000000] Architected cp15 timer(s) running at 24.00MHz (phys).
                                                                               //CPU TIMER初
     始化
260
     [ 0.000000] clocksource: arch_sys_counter: mask: 0xfffffffffffff max_cycles:
     0x588fe9dc0, max idle ns: 440795202592 ns
           0.000006] sched_clock: 56 bits at 24MHz, resolution 41ns, wraps every
261
     4398046511097ns
                         //EAS初始化
262
           0.001921] Calibrating delay loop (skipped), value calculated using timer frequency...
     48.00 BogoMIPS (lpj=80000)
263
           0.002907] pid max: default: 32768 minimum: 301
264
        0.003438] Security Framework initialized
265
      [
          0.003838] SELinux: Initializing.
      [ 0.004261] Mount-cache hash table entries: 8192 (order: 4, 65536 bytes)
266
267
         0.004906] Mountpoint-cache hash table entries: 8192 (order: 4, 65536 bytes)
      [ 0.006432] Initializing cgroup subsys freezer
268
        0.006871] Initializing cgroup subsys debug
269
270
      [
          0.008196] sched-energy: Sched-energy-costs installed from DT
271
      [
          0.008759] CPU0: update cpu_capacity 401
272
           0.009218] ASID allocator initialised with 65536 entries
273
      0.026042] PCI/MSI: /interrupt-controller@fee00000/interrupt-controller@fee20000
     domain created
274
      Γ
           0.027297] Platform MSI: /interrupt-controller@fee00000/interrupt-controller@fee20000
     domain created
275
           0.039452] Detected VIPT I-cache on CPU1
276
          0.039484] CPU1: found redistributor 1 region 0:0x000000000fef20000
277
         0.039524] CPU1: using LPI pending table @0x00000000f1c00000
278
          0.039566] CPU1: update cpu_capacity 401
      [ 0.039569] CPU1: Booted secondary processor [410fd034]
279
           0.049447] Detected VIPT I-cache on CPU2
280
      281
      [ 0.049467] CPU2: found redistributor 2 region 0:0x000000000fef40000
        0.049499] CPU2: using LPI pending table @0x00000000f1c30000
282
283
          0.049527] CPU2: update cpu_capacity 401
      [
284
        0.049530] CPU2: Booted secondary processor [410fd034]
285
      Γ
           0.059486] Detected VIPT I-cache on CPU3
286
          0.059505] CPU3: found redistributor 3 region 0:0x000000000fef60000
           0.059537] CPU3: using LPI pending table @0x00000000f1c70000
287
          0.059563] CPU3: update cpu capacity 401
288
      [
289
          0.059566] CPU3: Booted secondary processor [410fd034]
           0.069534] Detected PIPT I-cache on CPU4
290
      Γ
291
          0.069562] CPU4: found redistributor 100 region 0:0x000000000fef80000
           0.069601] CPU4: using LPI pending table @0x00000000f1cb0000
292
293
      [
          0.069643] CPU4: update cpu_capacity 1024
          0.069646] CPU4: Booted secondary processor [410fd082]
294
295
      Γ
           0.079556] Detected PIPT I-cache on CPU5
296
      0.079574] CPU5: found redistributor 101 region 0:0x000000000fefa0000
297
           0.079610] CPU5: using LPI pending table @0x00000000f1cf0000
      [
          0.079637] CPU5: update cpu_capacity 1024
298
      0.079639] CPU5: Booted secondary processor [410fd082]
299
      [
          0.079726] Brought up 6 CPUs
                                                //多核启动结束,已成功启动6核
300
      301
      Γ
           0.092124] SMP: Total of 6 processors activated.
           0.092578] CPU features: detected feature: GIC system register CPU interface
302
      Γ
        0.093264] CPU: All CPU(s) started at EL2
303
```

```
304
           0.0936951 alternatives: patching kernel code
305
           0.095819] devtmpfs: initialized
306
           0.115570] clocksource: jiffies: mask: 0xffffffff max_cycles: 0xffffffff,
     max_idle_ns: 6370867519511994 ns
           0.116548] futex hash table entries: 2048 (order: 5, 131072 bytes)
307
308
           0.117868] pinctrl core: initialized pinctrl subsystem
      Γ
           0.119931] Failed to find legacy iommu devices
309
      Γ
310
      Γ
           0.120748] NET: Registered protocol family 16
311
           0.121502] schedtune: init normalization constants...
      0.122008] schedtune: CLUSTER[0-3]
                                                           56 max_pwr:
312
                                                 min pwr:
                                                                           222
           0.122643] schedtune: CPU[0]
                                                             0 max_pwr:
313
                                                 min pwr:
                                                                           222
          0.123289] schedtune: CPU[1]
                                                             0 max pwr: 222
314
                                                 min pwr:
315
           0.123925] schedtune: CPU[2]
                                                 min pwr:
                                                             0 max pwr:
      Γ
316
           0.124560] schedtune: CPU[3]
                                                 min pwr:
                                                             0 max pwr: 222
      min pwr: 65 max pwr: 1108
317
           0.125196] schedtune: CLUSTER[4-5]
      Γ
           0.125830] schedtune: CPU[4]
318
                                                 min pwr: 0 max pwr: 1108
          0.126465] schedtune: CPU[5]
319
                                                 min pwr:
                                                              0 max pwr: 1108
320
           0.127129] schedtune: SYSTEM
                                                 min pwr: 121 max pwr: 4434
      321
      0.127765] schedtune: using normalization constants mul: 3862781856 sh1: 1 sh2: 12
322
           0.128507] schedtune: verify normalization constants...
      Γ
           0.129023] schedtune: max_pwr/2^0: 4313 => norm_pwr: 1024
323
           0.129565] schedtune: max pwr/2^1: 2156 => norm pwr:
                                                                511
324
325
      Γ
           0.130107] schedtune: max pwr/2^2: 1078 => norm pwr:
                                                                 255
           0.130656] schedtune: max pwr/2^3: 539 => norm pwr:
326
      Γ
           0.131198] schedtune: max_pwr/2^4: 269 => norm_pwr:
327
                                                                 63
      328
           0.131740] schedtune: \max pwr/2^5: 134 => norm pwr:
329
           0.132282] schedtune: configured to support 5 boost groups
                                                         //CPUIDLE初始化
330
           0.140691] cpuidle: using governor ladder
      Γ
331
           0.150696] cpuidle: using governor menu
      0.151091] Registered FIQ tty driver
                                                         //FIO注册
332
      333
           0.151731] vdso: 2 pages (1 code @ ffffff8008b26000, 1 data @ ffffff8009124000)
           0.152470] hw-breakpoint: found 6 breakpoint and 4 watchpoint registers.
334
335
           0.153858] DMA: preallocated 256 KiB pool for atomic allocations
      [
336
           0.175168] console [pstore0] enabled
                                                         //PSTORE用于存储LASTLOG
      337
      0.175768] pstore: Registered ramoops as persistent store backend
338
           0.176374] ramoops: attached 0xf0000@0x110000, ecc: 0/0
           0.177559] sip fiq debugger uart irq tf init error: -2
339
           0.178089] fiq debugger bind fiq to trustzone failed: -2
340
      Γ
341
      <hit enter to activate fiq debugger>
                                                         //FIQ CONSOLE
342
           0.178937] console [ttyFIQ0] enabled
343
           0.178937] console [ttyFIQ0] enabled
            0.179799] bootconsole [uart0] disabled
344
345
      0.179799] bootconsole [uart0] disabled
           0.180707] Registered fiq debugger ttyFIQ0
346
      Γ
347
      Γ
           0.209178] Rockchip hdmi driver version 2.0
348
349
           0.210895] iommu: Adding device ff650000.vpu_service to group 0
      0.210978] iommu: Adding device ff660000.rkvdec to group 1
350
      Γ
           0.211045] iommu: Adding device ff670000.iep to group 2
351
           0.211142] iommu: Adding device ff8f0000.vop to group 3
352
      353
      0.211219] iommu: Adding device ff900000.vop to group 4
354
           0.211935] rk_iommu ff670800.iommu: can't get aclk
      Γ
           0.211955] rk_iommu ff670800.iommu: can't get hclk
355
```

```
356
           0.2125311 SCSI subsystem initialized
357
           0.212706] usbcore: registered new interface driver usbfs
358
           0.212754] usbcore: registered new interface driver hub
      0.212826] usbcore: registered new device driver usb
359
      [
           0.213164] media: Linux media interface: v0.10
360
           0.213209] Linux video capture interface: v2.00
361
           0.213367] pps core: LinuxPPS API ver. 1 registered
362
363
           0.213378] pps core: Software ver. 5.3.6 - Copyright 2005-2007 Rodolfo Giometti
     <giometti@linux.it>
           0.213404] PTP clock support registered
364
365
           0.214836] Advanced Linux Sound Architecture Driver Initialized.
          0.215365] Bluetooth: Core ver 2.21
366
367
           0.215400] NET: Registered protocol family 31
      Γ
           0.215412] Bluetooth: HCI device and connection manager initialized
368
      Γ
369
           0.215430] Bluetooth: HCI socket layer initialized
           0.215445] Bluetooth: L2CAP socket layer initialized
370
           0.215489] Bluetooth: SCO socket layer initialized
371
372
           0.216592] rockchip-cpuinfo cpuinfo: Serial
                                                              : 00000000000000000
373
           0.217016] clocksource: Switched to clocksource arch sys counter
           0.259836] thermal thermal zone1: power allocator: sustainable power will be
374
      Γ
     estimated
375
      Γ
           0.260090] NET: Registered protocol family 2
376
           0.260552] TCP established hash table entries: 32768 (order: 6, 262144 bytes)
           0.260734] TCP bind hash table entries: 32768 (order: 7, 524288 bytes)
377
      378
           0.260971] TCP: Hash tables configured (established 32768 bind 32768)
      379
           0.261054] UDP hash table entries: 2048 (order: 4, 65536 bytes)
380
           0.261102] UDP-Lite hash table entries: 2048 (order: 4, 65536 bytes)
381
           0.261280] NET: Registered protocol family 1
382
           0.261782] Trying to unpack rootfs image as initramfs...
           0.359789] Freeing initrd memory: 1944K
383
384
           0.360263] hw perfevents: enabled with armv8_cortex_a53 PMU driver, 7 counters
     available
385
           0.360437] hw perfevents: enabled with armv8 cortex a72 PMU driver, 7 counters
      available
386
           0.363044] audit: initializing netlink subsys (disabled)
387
           0.363110] audit: type=2000 audit(0.356:1): initialized
           0.368384] VFS: Disk quotas dquot_6.6.0
388
           0.368523] VFS: Dquot-cache hash table entries: 512 (order 0, 4096 bytes)
389
      [
390
      [
           0.369928] fuse init (API version 7.23)
391
      0.371118]
392
      Γ
           0.371118] TEE Core Framework initialization (ver 1:0.1)
           0.371155] TEE armv7 Driver initialization
393
           0.371483] tz_tee_probe: name="armv7sec", id=0, pdev_name="armv7sec.0"
394
           0.371498] TEE core: Alloc the misc device "opteearmtz00" (id=0)
395
396
           0.371700] TEE Core: Register the misc device "opteearmtz00" (id=0,minor=62)
      Γ
397
      0.375815] Block layer SCSI generic (bsg) driver version 0.4 loaded (major 246)
398
           0.375842] io scheduler noop registered
      [
           0.376010] io scheduler cfq registered (default)
399
      0.379828] backlight supply power not found, using dummy regulator
400
           0.380478] iep: failed to find iep power down clock source.
401
      402
      0.380842] IEP Power ON
403
           0.381000] IEP Power OFF
404
      Γ
           0.381079] IEP Driver loaded succesfully
```

```
405
           0.3811831 Module initialized.
406
           0.381587] rk-vcodec ff650000.vpu service: probe device
                                                                        //RKVDEC初始化
407
           0.381634] rk-vcodec ff650000.vpu service: vpu mmu dec ffffffc0f1f01810
      0.381768] rk-vcodec ff650000.vpu_service: allocator is drm
408
           0.381820] rk-vcodec ff650000.vpu service: checking hw id 0
409
           0.382263] rk-vcodec ff650000.vpu service: init success
410
           0.382816] rk-vcodec ff660000.rkvdec: probe device
411
412
           0.382855] rk-vcodec ff660000.rkvdec: vpu mmu dec ffffffc0f1f02010
413
          0.382986] rk-vcodec ff660000.rkvdec: allocator is drm
         0.383041] rk-vcodec ff660000.rkvdec: checking hw id 6876
414
415
          0.383360] rk-vcodec ff660000.rkvdec: init success
416
      [ 0.384733] dma-pl330 ff6d0000.dma-controller: Loaded driver for PL330 DMAC-241330
                           //DMA PL330初始化
417
           0.384752] dma-pl330 ff6d0000.dma-controller:
                                                            DBUFF-32x8bytes Num Chans-6
     Num Peri-12 Num Events-12
           0.386095] dma-pl330 ff6e0000.dma-controller: Loaded driver for PL330 DMAC-241330
418
419
           0.386113] dma-pl330 ff6e0000.dma-controller: DBUFF-128x8bytes Num Chans-8
     Num Peri�� ˙Z�� Events-16 //console切换 可能显示乱码。
420
           0.387768] Serial: 8250/16550 driver, 5 ports, IRQ sharing disabled
421
           0.389354] console [ttyS0] disabled
422
           0.389403] ff180000.serial: ttyS0 at MMIO 0xff180000 (irq = 36, base baud = 1500000)
     is a 16550A
423
      Γ
           0.389971] ff1a0000.serial: ttyS2 at MMIO 0xff1a0000 (irq = 37, base baud = 1500000)
     is a 16550A
424
          0.390400] [drm:drm_core init] Initialized drm 1.1.0 20060810
425
          0.394776] ff960000.dsi.0 supply power not found, using dummy regulator
426
         0.395401] mali ff9a0000.gpu: Failed to get regulator
                                                                         //GPU初始化
427
          0.395423] mali ff9a0000.gpu: Power control initialization failed
      [ 0.395709] Unable to detect cache hierarchy from DT for CPU 0
428
429
           0.403629] brd: module loaded
      430
      [ 0.408410] loop: module loaded
         0.408957] zram: Added device: zram0
431
432
          0.409523] SCSI Media Changer driver v0.25
      [
433
          0.410130] tun: Universal TUN/TAP device driver, 1.6
434
      Γ
           0.410148] tun: (C) 1999-2004 Max Krasnyansky <maxk@qualcomm.com>
435
      Γ
           0.411221] rk gmac-dwmac fe300000.ethernet: clock input or output? (input). //GMAC初
     始化
           0.411251] rk gmac-dwmac fe300000.ethernet: TX delay(0x28).
436
      [
437
      [
           0.411266] rk gmac-dwmac fe300000.ethernet: RX delay(0x11).
438
           0.411294] rk gmac-dwmac fe300000.ethernet: integrated PHY? (no).
      Γ
439
           0.411461] rk_gmac-dwmac fe300000.ethernet: clock input from PHY
           0.416480] rk_gmac-dwmac fe300000.ethernet: init for RGMII
440
           0.416607] stmmac - user ID: 0x10, Synopsys ID: 0x35
441
      [
           0.416617] Ring mode enabled
442
443
           0.416627] DMA HW capability register supported
      Γ
444
      0.416635] Normal descriptors
           0.416647] RX Checksum Offload Engine supported (type 2)
445
      [
           0.416656] TX Checksum insertion supported
446
      0.416664] Wake-Up On Lan supported
447
          0.416705] Enable RX Mitigation via HW Watchdog Timer
448
      449
      0.483193] libphy: stmmac: probed
           0.483230] eth%d: PHY ID 001cc915 at 0 IRQ POLL (stmmac-0:00) active
450
      Γ
        0.483244] eth%d: PHY ID 001cc915 at 1 IRQ POLL (stmmac-0:01)
451
```

```
452
           0.484036] PPP generic driver version 2.4.2
453
           0.484236] PPP BSD Compression module registered
      Γ
454
           0.484252] PPP Deflate Compression module registered
      [
           0.484283] PPP MPPE Compression module registered
455
      0.484307] NET: Registered protocol family 24
456
           0.484349] SLIP: version 0.8.4-NET3.019-NEWTTY (dynamic channels, max=256) (6 bit
457
     encapsulation enabled).
458
      Γ
           0.484361] CSLIP: code copyright 1989 Regents of the University of California.
           0.484386] Rockchip WiFi SYS interface (V1.00) ...
459
           0.484471] usbcore: registered new interface driver catc
460
461
           0.484515] usbcore: registered new interface driver kaweth
           0.484532] pegasus: v0.9.3 (2013/04/25), Pegasus/Pegasus II USB Ethernet driver
462
463
           0.484573] usbcore: registered new interface driver pegasus
      Γ
464
           0.484620] usbcore: registered new interface driver rtl8150
465
           0.484663] usbcore: registered new interface driver r8152
           0.484678] hso: drivers/net/usb/hso.c: Option Wireless
466
           0.484739] usbcore: registered new interface driver hso
467
468
           0.484791] usbcore: registered new interface driver asix
      Γ
469
      Γ
           0.484835] usbcore: registered new interface driver ax88179_178a
           0.484878] usbcore: registered new interface driver cdc_ether
470
           0.484920] usbcore: registered new interface driver cdc_eem
471
472
           0.484963] usbcore: registered new interface driver dm9601
473
      Γ
           0.485014] usbcore: registered new interface driver smsc75xx
           0.485068] usbcore: registered new interface driver smsc95xx
474
      Γ
475
           0.485110] usbcore: registered new interface driver gl620a
      Γ
476
           0.485154] usbcore: registered new interface driver net1080
477
           0.485197] usbcore: registered new interface driver plusb
478
           0.485240] usbcore: registered new interface driver rndis_host
      Γ
           0.485286] usbcore: registered new interface driver cdc_subset
479
      Γ
           0.485329] usbcore: registered new interface driver zaurus
480
      Γ
           0.485373] usbcore: registered new interface driver MOSCHIP usb-ethernet driver
481
           0.485432] usbcore: registered new interface driver int51x1
482
483
           0.485475] usbcore: registered new interface driver kalmia
484
           0.485521] usbcore: registered new interface driver ipheth
485
      Γ
           0.485569] usbcore: registered new interface driver sierra_net
486
      Γ
           0.485613] usbcore: registered new interface driver cx82310 eth
           0.485666] usbcore: registered new interface driver cdc_ncm
487
           0.485709] usbcore: registered new interface driver qmi_wwan
488
489
           0.485756] usbcore: registered new interface driver cdc_mbim
           0.486891] rockchip-dwc3 usb@fe800000: failed to get drvdata dwc3
490
      Γ
491
      Γ
           0.487734] rockchip-dwc3 usb@fe900000: failed to get drvdata dwc3
           0.488412] ehci hcd: USB 2.0 'Enhanced' Host Controller (EHCI) Driver
492
493
           0.488430] ehci-pci: EHCI PCI platform driver
      0.488486] ehci-platform: EHCI generic platform driver
494
495
           0.489042] ohci_hcd: USB 1.1 'Open' Host Controller (OHCI) Driver
      Γ
496
      Γ
           0.489078] ohci-platform: OHCI generic platform driver
497
           0.489898] usbcore: registered new interface driver cdc_acm
      0.489910] cdc acm: USB Abstract Control Model driver for USB modems and ISDN
498
     adapters
499
           0.489968] usbcore: registered new interface driver usblp
      Γ
500
      Γ
           0.490016] usbcore: registered new interface driver cdc_wdm
501
           0.490067] usbcore: registered new interface driver uas
502
      Γ
           0.490122] usbcore: registered new interface driver usb-storage
```

```
503
           0.490163] usbcore: registered new interface driver ums-alauda
504
           0.490204] usbcore: registered new interface driver ums-cypress
505
           0.490246] usbcore: registered new interface driver ums-datafab
      0.490287] usbcore: registered new interface driver ums_eneub6250
506
      0.490328] usbcore: registered new interface driver ums-freecom
507
508
           0.490395] usbcore: registered new interface driver ums-isd200
      Γ
509
      Γ
           0.490439] usbcore: registered new interface driver ums-jumpshot
510
      Γ
           0.490480] usbcore: registered new interface driver ums-karma
511
           0.490521] usbcore: registered new interface driver ums-onetouch
           0.490562] usbcore: registered new interface driver ums-sddr09
512
513
           0.490603] usbcore: registered new interface driver ums-sddr55
           0.490645] usbcore: registered new interface driver ums-usbat
514
515
           0.490735] usbcore: registered new interface driver usbserial
      Γ
516
           0.490773] usbcore: registered new interface driver usbserial generic
517
           0.490804] usbserial: USB Serial support registered for generic
           0.490846] usbcore: registered new interface driver option
518
           0.490875] usbserial: USB Serial support registered for GSM modem (1-port)
519
520
           0.490924] usbcore: registered new interface driver trancevibrator
      521
      Γ
           0.490942] usb20 otg: version 3.10a 21-DEC-2012
           0.491104] usb20 host: version 3.10a 21-DEC-2012
522
      Γ
           0.491571] usbcore: registered new interface driver xpad
523
           0.491622] usbcore: registered new interface driver usb_acecad
524
525
      [
           0.491669] usbcore: registered new interface driver aiptek
           0.491719] usbcore: registered new interface driver gtco
526
      Γ
527
           0.491766] usbcore: registered new interface driver hanwang
      Γ
528
           0.491811] usbcore: registered new interface driver kbtab
529
           0.492208] sensor_register_slave:mma8452,id=17
530
           0.492227] sensor_register_slave:lis3dh,id=7
      531
           0.492243] sensor register slave:mma7660,id=18
      0.492260] sensor register slave:lsm303d,id=22
532
      533
           0.492275] sensor_register_slave:gs_mc3230,id=23
           0.492285] [Gsensor]
                                 gsensor init
534
535
           0.492301] sensor register slave:mpu6880 acc,id=24
      536
           0.492317] sensor register slave:mpu6500 acc,id=25
537
      Γ
           0.492334] sensor register slave:lsm330 acc,id=26
538
      0.492350] sensor register_slave:bma2xx acc,id=27
           0.492367] sensor register slave:akm8975,id=29
539
           0.492383] sensor_register_slave:akm8963,id=30
540
541
           0.492399] sensor_register_slave:13g4200d,id=44
542
      Γ
           0.492416] sensor_register_slave:13g20d,id=45
543
      0.492432] sensor register slave:ewtsa,id=46
           0.492449] sensor register slave:lsm330 gyro,id=50
544
      Γ
           0.492466] sensor_register_slave:cm3217,id=52
545
      0.492482] sensor_register_slave:cm3218,id=53
546
547
           0.492498] sensor register slave: ls stk3410, id=61
      Γ
548
      0.492515] sensor register slave:ps stk3410,id=66
549
           0.493197] i2c /dev entries driver
      0.518694] fusb302 0-0022: port 0 probe success
550
      0.520308] fan53555-regulator 0-0040: FAN53555 Option[8] Rev[1] Detected!
551
      //SYR827初始化
552
      Γ
           0.520446] fan53555-reg: supplied by vcc5v0 sys
553
           0.524987] fan53555-regulator 0-0041: FAN53555 Option[8] Rev[1] Detected!
      Γ
554
      Γ
           0.525055] fan53555-reg: supplied by vcc5v0_sys
```

```
0.5295351 rk808 0-001b: Pmic Chip id: 0x0 //RK808 PMIC初始化
555
556
           0.538833] rk808-regulator rk808-regulator: there is no dvs0 gpio
      Γ
557
           0.538919] rk808-regulator rk808-regulator: there is no dvs1 gpio
      0.539037] DCDC_REG1: supplied by vcc3v3_sys
558
      0.540706] DCDC REG2: supplied by vcc3v3 sys
559
           0.541840] DCDC REG3: supplied by vcc3v3 sys
560
           0.542134] DCDC REG4: supplied by vcc3v3 sys
561
      Γ
562
      Γ
           0.542912] LDO REG1: supplied by vcc3v3 sys
563
           0.544707] LDO REG2: supplied by vcc3v3 sys
      0.546055] LDO REG3: supplied by vcc3v3 sys
564
565
           0.547384] LDO REG4: supplied by vcc3v3 sys
           0.548712] LDO REG5: supplied by vcc3v3 sys
566
567
           0.5500601 LDO REG6: supplied by vcc3v3 sys
      568
           0.551392] LDO REG7: supplied by vcc3v3 sys
      569
           0.552717] LDO REG8: supplied by vcc3v3 sys
           0.554044] SWITCH REG1: supplied by vcc3v3 sys
570
           0.554374] SWITCH REG2: supplied by vcc3v3 sys
571
572
           0.564394] rk808-rtc rk808-rtc: rtc core: registered rk808-rtc as rtc0
      573
      [
           0.565609] rk3x-i2c ff3c0000.i2c: Initialized RK3xxx I2C bus at ffffff800952e000
                  //FF3C0000是I2C0
574
           0.566445] rk3x-i2c ff110000.i2c: Initialized RK3xxx I2C bus at ffffff800953a000
                  //FF110000是I2C1
575
      Γ
           1.567057] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1 //FF120000是I2C2
           2.567080] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1 //FF3D0000是I2C4
576
      Γ
           3.567046] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1 //FF130000是I2C3
577
      578
           4.567044] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1 //FF140000是I2C5
           5.567048] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1 //FF150000是I2C6
579
580
           6.567049] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1 //FF160000是I2C7
581
           7.567043] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
      8.567043] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1 //RK3399 EVB3 I2C6上有
582
      Γ
     FUSB0
      [
583
           9.567044] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
584
        10.567044] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
585
        11.567041] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
586
      12.567042] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
587
      [ 13.567045] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
        14.567041] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
588
        15.567039] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
589
590
        16.567043] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
        17.567041] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
591
      Γ
592
      [ 18.567040] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
         19.567043] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
593
        20.567039] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
594
      [
        21.567040] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
595
596
         22.567045] rk3x-i2c ff150000.i2c: timeout, ipd: 0x00, state: 1
      Γ
597
      [ 22.567368] fusb302 6-0022: port 1 probe success
598
          22.567403] rk3x-i2c ff150000.i2c: Initialized RK3xxx I2C bus at ffffff800953c000
      [
          22.568238] goodix ts probe() start
                                                   //GOODIX是触摸屏,由于机器没有插屏 故触摸屏初
599
      始化I2C通讯失败
600
         22.697884] <<-GTP-ERROR->> I2C Read: 0x8000, 10 bytes failed, errcode: -6! Process
      Γ
     reset.
          22.781209] <<-GTP-ERROR->> I2C Read: 0x8000, 10 bytes failed, errcode: -6! Process
```

```
reset.
602
         22.864541] <<-GTP-ERROR->> I2C Read: 0x8000, 10 bytes failed, errcode: -6! Process
     reset.
     [ 22.947873] <<-GTP-ERROR->> I2C Read: 0x8000, 10 bytes failed, errcode: -6! Process
603
     reset.
     [ 23.031209] <<-GTP-ERROR->> I2C Read: 0x8000, 10 bytes failed, errcode: -6! Process
604
605
     [
         23.114539] <<-GTP-ERROR->> I2C Read: 0x8000, 10 bytes failed, errcode: -6! Process
     reset.
        23.197047] <<-GTP-ERROR->> I2C read 0x8000, 10 bytes, double check failed!
606
607
        23.197068] <<-GTP-ERROR->> Failed to get chip-type, set chip type default: GOODIX_GT9
608
        23.197842] <<-GTP-ERROR->> I2C Read: 0x8047, 1 bytes failed, errcode: -6! Process
     reset.
609
         23.280380] <<-GTP-ERROR->> GTP i2c test failed time 1.
     610
     Γ
         23.294533] <<-GTP-ERROR->> I2C Read: 0x8047, 1 bytes failed, errcode: -6! Process
     reset.
         23.377047] <<-GTP-ERROR->> GTP i2c test failed time 2.
611
612
         23.391199] <<-GTP-ERROR->> I2C Read: 0x8047, 1 bytes failed, errcode: -6! Process
     613
         23.473712] <<-GTP-ERROR->> GTP i2c test failed time 3.
614
     23.487866] <<-GTP-ERROR->> I2C Read: 0x8047, 1 bytes failed, errcode: -6! Process
     reset.
615
        23.570380] <<-GTP-ERROR->> GTP i2c test failed time 4.
     [ 23.584533] <<-GTP-ERROR->> I2C Read: 0x8047, 1 bytes failed, errcode: -6! Process
616
     reset.
617
     [ 23.667045] <<-GTP-ERROR->> GTP i2c test failed time 5.
        618
619
     [ 23.680394]
                      <goodix ts probe> 2817 prob error !!!!!!!!!!!! //GT911初始化失败
     [ 23.681138] input: gsl3673 as /devices/platform/ff3d0000.i2c/i2c-4/4-0040/input/input0
620
     // GSL3673是另一款触摸屏
621
     [ 23.740544] gsl3673 4-0040: GSL3673 test i2c error!
        23.740593] gsl3673 4-0040: gsl probe: init chip failed
622
     [ 23.753842] gsl3673: probe of 4-0040 failed with error -1 //GSL3673也初始化失败
623
624
      [ 23.753920] rk3x-i2c ff3d0000.i2c: Initialized RK3xxx I2C bus at ffffff800953e000
625
      [ 23.754991] IR NEC protocol handler initialized
626
      [ 23.755008] IR RC5(x/sz) protocol handler initialized
        23.755060] IR RC6 protocol handler initialized
627
     [ 23.755079] IR JVC protocol handler initialized
628
      [ 23.755096] IR Sony protocol handler initialized
629
630
      [ 23.755112] IR SANYO protocol handler initialized
631
      [ 23.755127] IR Sharp protocol handler initialized
        23.755143] IR MCE Keyboard/mouse protocol handler initialized
632
     [ 23.755158] IR XMP protocol handler initialized
633
        23.755468] usbcore: registered new interface driver uvcvideo
634
635
      [ 23.755480] USB Video Class driver (1.1.1)
636
      [ 23.755499] CamSys driver version: v0.34.7, CamSys head file version: v0.14.0
637
         23.756126] __power_supply_register: Expected proper parent device for 'test_ac'
         23.756299] power supply register: Expected proper parent device for 'test battery'
638
         23.756615] thermal thermal_zone2: power_allocator: sustainable_power will be
639
     Γ
     estimated
640
     [ 23.756749] __power_supply_register: Expected proper parent device for 'test_usb'
        23.759868] rk_tsadcv2_temp_to_code: Invalid conversion table: code=1023,
```

```
temperature=2147483647
642
          23.760770] device-mapper: uevent: version 1.0.3
643
          23.761226] device-mapper: ioctl: 4.34.0-ioctl (2015-10-28) initialised: dm-
     devel@redhat.com
        23.761475] Bluetooth: HCI UART driver ver 2.3
644
      [ 23.761489] Bluetooth: HCI UART protocol H4 registered
645
      [ 23.761501] Bluetooth: HCI UART protocol LL registered
646
647
        23.761517] rtk btusb: RTKBT RELEASE NAME: 20170109 TV ANDROID 6.x
      [ 23.761527] rtk btusb: Realtek Bluetooth USB driver module init, version 4.1.2
648
        23.761537] rtk btusb: Register usb char device interface for BT driver
649
650
      [ 23.761813] usbcore: registered new interface driver rtk_btusb
      [ 23.762416] cpu cpu0: leakage=0
                                             //CPU LEAKAGE信息
651
652
      [ 23.780434] cpu cpu0: temp=24444, pvtm=144616 (146571 + -1955)
653
      [ 23.781122] cpu cpu0: pvtm-sel=1
654
        23.781571] cpu cpu4: leakage=0
      [ 23.794198] cpu cpu4: temp=24444, pvtm=151939 (153146 + -1207)
655
        23.794359] cpu cpu4: pvtm-sel=1
656
657
      [ 23.801361] sdhci: Secure Digital Host Controller Interface driver
658
      [ 23.801422] sdhci: Copyright(c) Pierre Ossman
659
         23.801443] Synopsys Designware Multimedia Card Interface Driver //EMMC初始化
660
      [ 23.802660] dwmmc rockchip fe310000.dwmmc: IDMAC supports 32-bit address mode.
        23.802820] dwmmc rockchip fe310000.dwmmc: Using internal DMA controller.
661
662
        23.802842] dwmmc rockchip fe310000.dwmmc: Version ID is 270a
      [ 23.802898] dwmmc rockchip fe310000.dwmmc: DW MMC controller at irq 25,32 bit host
663
     data width, 256 deep fifo
664
      23.802933] dwmmc rockchip fe310000.dwmmc: 'clock-freq-min-max' property was
     deprecated.
665
      [ 23.802985] dwmmc_rockchip fe310000.dwmmc: No vmmc regulator found
666
      [ 23.802998] dwmmc rockchip fe310000.dwmmc: No vgmmc regulator found
         23.804134] dwmmc rockchip fe320000.dwmmc: IDMAC supports 32-bit address mode.
667
668
      [ 23.804243] dwmmc rockchip fe320000.dwmmc: Using internal DMA controller.
        23.804263] dwmmc rockchip fe320000.dwmmc: Version ID is 270a
669
670
      [ 23.804312] dwmmc rockchip fe320000.dwmmc: DW MMC controller at irq 26,32 bit host
     data width, 256 deep fifo
671
      Γ
         23.804337] dwmmc_rockchip fe320000.dwmmc: 'clock-freq-min-max' property was
     deprecated.
        23.804461] dwmmc_rockchip fe320000.dwmmc: No vmmc regulator found
672
      [ 23.804774] vcc_sd: unsupportable voltage range: 3300000-30000000V
673
674
        23.804803] rockchip-iodomain ff770000.syscon:io-domains: Setting to 3000000 done
675
        23.804821] rockchip-iodomain ff770000.syscon:io-domains: Setting to 3000000 done
676
         23.817159] mmc host mmc0: Bus speed (slot 0) = 400000Hz (slot req 400000Hz, actual
     400000HZ div = 0)
        23.831508] dwmmc_rockchip fe320000.dwmmc: 1 slots initialized
677
         23.831961] sdhci-pltfm: SDHCI platform and OF driver helper
678
679
        23.833982] sdhci-arasan fe330000.sdhci: No vmmc regulator found
      Γ
680
      [ 23.834038] sdhci-arasan fe330000.sdhci: No vqmmc regulator found
681
         23.860500] mmc1: SDHCI controller on fe330000.sdhci [fe330000.sdhci] using ADMA
      [
      [ 23.861497] hidraw: raw HID events driver (C) Jiri Kosina
682
        23.866060] usbcore: registered new interface driver usbhid
683
      [ 23.866085] usbhid: USB HID core driver
684
685
      [ 23.866274] inv mpu iio: inv mpu init:746
         23.867235] ashmem: initialized
686
      [
        23.869035] rockchip-dmc dmc: unable to get devfreq-event device : dfi //DDR变频初始化
687
```

```
失败
688
         23.872213] ff100000.saradc supply vref not found, using dummy regulator
      Γ
689
          23.873494] rknandbase v1.1 2016-11-08
      23.874014] usbcore: registered new interface driver snd-usb-audio
690
      [
        23.878213] u32 classifier
691
      [ 23.879016]
                         Actions configured
692
      [ 23.879360] Netfilter messages via NETLINK v0.30.
693
694
        23.879840] nf_conntrack version 0.5.0 (16384 buckets, 65536 max)
695
      [ 23.880758] ctnetlink v0.93: registering with nfnetlink.
        23.881841] xt time: kernel timezone is -0000
696
697
      [ 23.883313] ip_tables: (C) 2000-2006 Netfilter Core Team
      [ 23.883978] arp_tables: (C) 2002 David S. Miller
698
699
      [ 23.885031] Initializing XFRM netlink socket
700
      [ 23.885865] NET: Registered protocol family 10
701
        23.887306] mip6: Mobile IPv6
      [ 23.887618] ip6 tables: (C) 2000-2006 Netfilter Core Team
702
      [ 23.889689] sit: IPv6 over IPv4 tunneling driver
703
704
      [ 23.890600] NET: Registered protocol family 17
705
        23.891039] NET: Registered protocol family 15
          23.891484] bridge: automatic filtering via arp/ip/ip6tables has been deprecated.
706
      Update your scripts to load br_netfilter if you need this.
707
         23.893543] Bridge firewalling registered
708
        23.893921] Ebtables v2.0 registered
      [ 23.894547] Bluetooth: RFCOMM TTY layer initialized
709
710
         23.894597] Bluetooth: RFCOMM socket layer initialized
711
      [ 23.894639] Bluetooth: RFCOMM ver 1.11
712
        23.894674] Bluetooth: BNEP (Ethernet Emulation) ver 1.3
713
      [ 23.894686] Bluetooth: BNEP filters: protocol multicast
      [ 23.894704] Bluetooth: BNEP socket layer initialized
714
715
        23.894724] Bluetooth: HIDP (Human Interface Emulation) ver 1.2
716
      [ 23.894739] Bluetooth: HIDP socket layer initialized
        23.894793] 12tp_core: L2TP core driver, V2.0
717
718
      [ 23.894818] l2tp_ppp: PPPoL2TP kernel driver, V2.0
719
      [ 23.894838] [WLAN RFKILL]: Enter rfkill wlan init
                                                                //WIFI初始化
720
        23.895296] [WLAN RFKILL]: Enter rfkill wlan probe
721
      [ 23.895388] [WLAN RFKILL]: wlan platdata parse dt: wifi chip type = ap6354
        23.895400] [WLAN_RFKILL]: wlan_platdata_parse_dt: enable wifi power control.
722
723
        23.895412] [WLAN_RFKILL]: wlan_platdata_parse_dt: wifi power controled by gpio.
724
      [ 23.895519] [WLAN_RFKILL]: wlan_platdata_parse_dt: get property: WIFI,host_wake_irq =
     1003, flags = 0.
725
      [ 23.895530] [WLAN RFKILL]: rfkill wlan probe: init gpio
        23.895545] [WLAN RFKILL]: Exit rfkill wlan probe
726
727
        23.895640] [BT_RFKILL]: Enter rfkill_rk_init
      [ 23.896165] [BT_RFKILL]: bluetooth_platdata_parse_dt: get property: uart_rts_gpios =
728
     1083.
729
      Γ
          23.896221] [BT RFKILL]: bluetooth platdata parse dt: get property: BT, reset gpio =
     1009.
      [ 23.896262] [BT RFKILL]: bluetooth platdata parse dt: get property: BT, wake gpio =
730
     1090
     [ 23.896303] [BT_RFKILL]: bluetooth_platdata_parse_dt: get property: BT,wake_host_irq =
731
     1004.
732
        23.897687] [BT_RFKILL]: Request irq for bt wakeup host
     [ 23.897753] [BT_RFKILL]: ** disable irq
733
```

```
23.897915] [BT RFKILL]: bt default device registered.
734
735
      [ 23.898195] sensor register slave:mpu6500 gyro,id=48
736
          23.898217] sensor_register_slave:mpu6880_gyro,id=49
      [ 23.899908] Registered cp15_barrier emulation handler
737
738
        23.899985] Registered setend emulation handler
739
      [ 23.901466] mmc1: MAN BKOPS EN bit is not set
740
      [ 23.910523] registered taskstats version 1
741
        23.911297] rockchip ion idev is NULL
742
      [ 23.911318] rga2 ff680000.rga: rga ion client create success!
        23.911509] rga: Driver loaded successfully ver:3.02
743
744
      [ 23.912418] rockchip-usb2phy ff770000.syscon:usb2-phy@e450: vbus_drv is not assigned
745
      [ 23.913596] rockchip-usb2phy ff770000.syscon:usb2-phy@e460: vbus drv is not assigned
746
          23.915565] rockchip-drm display-subsystem: bound ff900000.vop (ops vop component ops)
     //DRM显示系统启动
747
         23.915764] rockchip-drm display-subsystem: bound ff8f0000.vop (ops vop component ops)
        23.915833] rockchip-drm display-subsystem: bound ff960000.dsi (ops dw mipi dsi ops)
748
        23.916198] i2c i2c-9: of i2c: modalias failure on /hdmi@ff940000/ports
749
750
      [ 23.916232] dwhdmi-rockchip ff940000.hdmi: registered DesignWare HDMI I2C bus driver
            //HDMI注册
751
          23.916300] dwhdmi-rockchip ff940000.hdmi: Detected HDMI TX controller v2.11a with
     HDCP (DWC HDMI 2.0 TX PHY)
752
          23.917159] rockchip-drm display-subsystem: bound ff940000.hdmi (ops
     dw hdmi rockchip ops)
          23.917791] cdn-dp fec00000.dp: [drm:cdn dp pd event work] Not connected. Disabling
753
      [
     cdn
             //DP注册
754
     [ 23.917833] rockchip-drm display-subsystem: bound fec00000.dp (ops
     cdn_dp_component_ops)
755
      [ 23.917850] [drm:drm vblank init] Supports vblank timestamp caching Rev 2
     (21.10.2013).
        23.917864] [drm:drm vblank init] No driver support for vblank timestamp query.
756
757
      [ 23.917880] mmc1: new HS400 MMC card at address 0001 //eMMC注册成功
        23.918463] mmcblk1: mmc1:0001 AWPD3R 14.6 GiB
758
      [ 23.918712] mmcblk1boot0: mmc1:0001 AWPD3R partition 1 4.00 MiB
759
      [ 23.918946] mmcblk1boot1: mmc1:0001 AWPD3R partition 2 4.00 MiB
760
761
        23.919189] mmcblk1rpmb: mmc1:0001 AWPD3R partition 3 4.00 MiB
762
      [ 23.919645] rkpart: partition size too small (5)
                        uboot: 0x000400000 -- 0x000800000 (4 MB)
        23.919663]
763
      [ 23.919676]
                        trust: 0x000800000 -- 0x000c00000 (4 MB)
764
      [ 23.919687]
765
                          misc: 0x000c00000 -- 0x001000000 (4 MB)
        23.919699] resource: 0x001000000 -- 0x002000000 (16 MB)
766
      Γ
767
      [ 23.919711]
                       kernel: 0x002000000 -- 0x003800000 (24 MB)
                          boot: 0x003800000 -- 0x005800000 (32 MB)
768
        23.919722]
      [
769
      [ 23.919734] recovery: 0x005800000 -- 0x007800000 (32 MB)
                       backup: 0x007800000 -- 0x00e800000 (112 MB)
770
        23.919745]
771
        23.919757]
                        cache: 0x00e800000 -- 0x016800000 (128 MB)
      Γ
772
      [ 23.919769]
                       system: 0x016800000 -- 0x076800000 (1536 MB)
773
         23.919781]
                      metadata: 0x076800000 -- 0x077800000 (16 MB)
      [
        23.919792] verity mode: 0x077800000 -- 0x077808000 (0 MB)
774
        23.919804] baseparamer: 0x077808000 -- 0x077c08000 (4 MB)
775
        23.919816]
                           frp: 0x077c08000 -- 0x077c88000 (0 MB)
776
      777
      [ 23.919827] userdata: 0x077c88000 -- 0x3a3a00000 (12989 MB)
778
          23.919900] mmcblk1: p1 p2 p3 p4 p5 p6 p7 p8 p9 p10 p11 p12 p13 p14 p15 //分区挂载成功
779
     [ 23.960872] rockchip-drm display-subsystem: fb0: frame buffer device
```

```
780
          23.973531] mali ff9a0000.gpu: leakage=0 //GPU LEAKAGE信息
781
          23.999245] mali ff9a0000.gpu: temp=25000, pvtm=121768 (122504 + -736)
782
          24.001483] mali ff9a0000.gpu: pvtm-sel=1
          24.002828] mali ff9a0000.gpu: GPU identified as 0x0860 r2p0 status 0
783
          24.004313] I : [File] : drivers/gpu/arm/midgard/backend/gpu/mali_kbase_devfreq.c;
784
     [Line] : 284; [Func] : kbase_devfreq_init(); success initing power_model_simple.
          24.005638] mali ff9a0000.gpu: Probed as mali0
785
786
          24.012954] xhci-hcd xhci-hcd.8.auto: xHCI Host Controller
787
          24.013918] xhci-hcd xhci-hcd.8.auto: new USB bus registered, assigned bus number 1
          24.014948] xhci-hcd xhci-hcd.8.auto: hcc params 0x0220fe64 hci version 0x110 quirks
788
      0x02030010
789
          24.015836] xhci-hcd xhci-hcd.8.auto: irq 223, io mem 0xfe800000
      790
          24.016617] usb usb1: New USB device found, idVendor=1d6b, idProduct=0002
791
         24.017260] usb usb1: New USB device strings: Mfr=3, Product=2, SerialNumber=1
792
          24.017936] usb usb1: Product: xHCI Host Controller
793
        24.018406] usb usb1: Manufacturer: Linux 4.4.103 xhci-hcd
         24.018926] usb usb1: SerialNumber: xhci-hcd.8.auto
794
795
         24.020251] hub 1-0:1.0: USB hub found
796
         24.020672] hub 1-0:1.0: 1 port detected
797
          24.021534] xhci-hcd xhci-hcd.8.auto: xHCI Host Controller
798
          24.022081] xhci-hcd xhci-hcd.8.auto: new USB bus registered, assigned bus number 2
799
          24.022887] usb usb2: We don't know the algorithms for LPM for this host, disabling
     LPM.
          24.023831] usb usb2: New USB device found, idVendor=1d6b, idProduct=0003
800
      Γ
801
          24.023871] usb usb2: New USB device strings: Mfr=3, Product=2, SerialNumber=1
802
        24.023896] usb usb2: Product: xHCI Host Controller
803
         24.023918] usb usb2: Manufacturer: Linux 4.4.103 xhci-hcd
804
        24.023942] usb usb2: SerialNumber: xhci-hcd.8.auto
805
         24.027441] hub 2-0:1.0: USB hub found
          24.027854] hub 2-0:1.0: 1 port detected
806
807
        24.030758] xhci-hcd xhci-hcd.8.auto: remove, state 1
         24.030827] usb usb2: USB disconnect, device number 1
808
        24.055990] xhci-hcd xhci-hcd.8.auto: Host not halted after 16000 microseconds.
809
810
        24.056015] xhci-hcd xhci-hcd.8.auto: Host controller not halted, aborting reset.
811
          24.057469] xhci-hcd xhci-hcd.8.auto: USB bus 2 deregistered
812
      [ 24.057994] xhci-hcd xhci-hcd.8.auto: remove, state 1
         24.058470] usb usb1: USB disconnect, device number 1
813
        24.059406] xhci-hcd xhci-hcd.8.auto: USB bus 1 deregistered
814
815
         24.065438] xhci-hcd xhci-hcd.9.auto: xHCI Host Controller
816
          24.065523] xhci-hcd xhci-hcd.9.auto: new USB bus registered, assigned bus number 1
817
          24.065818] xhci-hcd xhci-hcd.9.auto: hcc params 0x0220fe64 hci version 0x110 quirks
     0x02030010
          24.065881] xhci-hcd xhci-hcd.9.auto: irq 224, io mem 0xfe900000
818
         24.066070] usb usb1: New USB device found, idVendor=1d6b, idProduct=0002
819
820
         24.066086] usb usb1: New USB device strings: Mfr=3, Product=2, SerialNumber=1
821
        24.066100] usb usb1: Product: xHCI Host Controller
822
          24.066114] usb usb1: Manufacturer: Linux 4.4.103 xhci-hcd
      [
        24.066126] usb usb1: SerialNumber: xhci-hcd.9.auto
823
         24.066757] hub 1-0:1.0: USB hub found
824
        24.066800] hub 1-0:1.0: 1 port detected
825
826
        24.067204] xhci-hcd xhci-hcd.9.auto: xHCI Host Controller
          24.067228] xhci-hcd xhci-hcd.9.auto: new USB bus registered, assigned bus number 2
827
        24.067311] usb usb2: We don't know the algorithms for LPM for this host, disabling
828
```

```
LPM.
829
          24.067437] usb usb2: New USB device found, idVendor=1d6b, idProduct=0003
      Γ
830
          24.067454] usb usb2: New USB device strings: Mfr=3, Product=2, SerialNumber=1
      24.067468] usb usb2: Product: xHCI Host Controller
831
         24.067481] usb usb2: Manufacturer: Linux 4.4.103 xhci-hcd
832
        24.067493] usb usb2: SerialNumber: xhci-hcd.9.auto
833
834
        24.068121] hub 2-0:1.0: USB hub found
835
          24.068160] hub 2-0:1.0: 1 port detected
      Γ
      [ 24.068692] xhci-hcd xhci-hcd.9.auto: remove, state 1
836
         24.068719] usb usb2: USB disconnect, device number 1
837
838
        24.069377] xhci-hcd xhci-hcd.9.auto: USB bus 2 deregistered
839
        24.069396] xhci-hcd xhci-hcd.9.auto: remove, state 1
840
          24.069416] usb usb1: USB disconnect, device number 1
841
        24.070047] xhci-hcd xhci-hcd.9.auto: USB bus 1 deregistered
842
         24.074245] ehci-platform fe380000.usb: EHCI Host Controller
      [ 24.074279] ehci-platform fe380000.usb: new USB bus registered, assigned bus number 1
843
        24.074543] ehci-platform fe380000.usb: irq 28, io mem 0xfe380000
844
845
          24.083919] ehci-platform fe380000.usb: USB 2.0 started, EHCI 1.00
846
        24.084192] usb usb1: New USB device found, idVendor=1d6b, idProduct=0002
847
         24.084209] usb usb1: New USB device strings: Mfr=3, Product=2, SerialNumber=1
848
      [ 24.084223] usb usb1: Product: EHCI Host Controller
        24.084235] usb usb1: Manufacturer: Linux 4.4.103 ehci_hcd
849
850
        24.084247] usb usb1: SerialNumber: fe380000.usb
        24.085166] hub 1-0:1.0: USB hub found
851
852
         24.085259] hub 1-0:1.0: 1 port detected
853
      [ 24.089706] ehci-platform fe3c0000.usb: EHCI Host Controller
854
         24.089763] ehci-platform fe3c0000.usb: new USB bus registered, assigned bus number 2
855
        24.089996] ehci-platform fe3c0000.usb: irq 30, io mem 0xfe3c0000
856
        24.097235] ehci-platform fe3c0000.usb: USB 2.0 started, EHCI 1.00
          24.097515] usb usb2: New USB device found, idVendor=1d6b, idProduct=0002
857
858
      [ 24.097532] usb usb2: New USB device strings: Mfr=3, Product=2, SerialNumber=1
         24.097546] usb usb2: Product: EHCI Host Controller
859
        24.097559] usb usb2: Manufacturer: Linux 4.4.103 ehci_hcd
860
        24.097571] usb usb2: SerialNumber: fe3c0000.usb
861
862
         24.098625] hub 2-0:1.0: USB hub found
      Γ
863
      [ 24.098721] hub 2-0:1.0: 1 port detected
         24.099832] ohci-platform fe3a0000.usb: Generic Platform OHCI controller
864
        24.099865] ohci-platform fe3a0000.usb: new USB bus registered, assigned bus number 3
865
866
        24.100107] ohci-platform fe3a0000.usb: irq 29, io mem 0xfe3a0000
867
          24.154853] usb usb3: New USB device found, idVendor=1d6b, idProduct=0001
868
        24.154918] usb usb3: New USB device strings: Mfr=3, Product=2, SerialNumber=1
869
          24.154933] usb usb3: Product: Generic Platform OHCI controller
        24.154946] usb usb3: Manufacturer: Linux 4.4.103 ohci_hcd
870
871
         24.154959] usb usb3: SerialNumber: fe3a0000.usb
         24.155994] hub 3-0:1.0: USB hub found
872
873
      Γ
        24.156037] hub 3-0:1.0: 1 port detected
874
          24.157125] ohci-platform fe3e0000.usb: Generic Platform OHCI controller
      [
        24.157161] ohci-platform fe3e0000.usb: new USB bus registered, assigned bus number 4
875
         24.157398] ohci-platform fe3e0000.usb: irq 31, io mem 0xfe3e0000
876
         24.214981] usb usb4: New USB device found, idVendor=1d6b, idProduct=0001
877
878
        24.215084] usb usb4: New USB device strings: Mfr=3, Product=2, SerialNumber=1
          24.215114] usb usb4: Product: Generic Platform OHCI controller
879
880
        24.215139] usb usb4: Manufacturer: Linux 4.4.103 ohci_hcd
```

```
881
          24.215163] usb usb4: SerialNumber: fe3e0000.usb
882
         24.216704] hub 4-0:1.0: USB hub found
883
          24.216787] hub 4-0:1.0: 1 port detected
        24.219659] dwmmc_rockchip fe310000.dwmmc: IDMAC supports 32-bit address mode.
884
         24.219915] dwmmc rockchip fe310000.dwmmc: Using internal DMA controller.
885
         24.219954] dwmmc rockchip fe310000.dwmmc: Version ID is 270a
886
          24.220019] dwmmc rockchip fe310000.dwmmc: DW MMC controller at irq 25,32 bit host
887
     data width, 256 deep fifo
888
          24.220069] dwmmc rockchip fe310000.dwmmc: 'clock-freq-min-max' property was
     deprecated.
889
          24.220159] dwmmc_rockchip fe310000.dwmmc: No vmmc regulator found
890
         24.220185] dwmmc rockchip fe310000.dwmmc: No vqmmc regulator found
891
          24.220927] dwmmc rockchip fe310000.dwmmc: allocated mmc-pwrseq
892
          24.234136] mmc host mmc2: Bus speed (slot 0) = 400000Hz (slot req 400000Hz, actual
      Γ
     400000HZ \ div = 0)
          24.247461] dwmmc_rockchip fe310000.dwmmc: 1 slots initialized
893
         24.263666] rockchip-dmc dmc: fail to register notify to vop.
894
895
         24.298732] mmc2: queuing unknown CIS tuple 0x80 (2 bytes)
896
         24.301020] mmc2: queuing unknown CIS tuple 0x80 (3 bytes)
897
          24.303206] mmc2: queuing unknown CIS tuple 0x80 (3 bytes)
898
          24.306738] mmc2: queuing unknown CIS tuple 0x80 (7 bytes)
899
          24.366859] mmc_host mmc2: Bus speed (slot 0) = 150000000Hz (slot req 150000000Hz,
     actual 150000000HZ div = 0)
          24.410437] asoc-simple-card es8316-sound: ES8316 HiFi <-> ff880000.i2s mapping ok
900
      Γ
                       //声卡初始化
901
          24.410560] asoc-simple-card es8316-sound: ASoC: no source widget found for MICBIAS1
902
          24.410592] asoc-simple-card es8316-sound: ASoC: Failed to add route MICBIAS1 ->
     direct -> Mic Jack
903
          24.410627] asoc-simple-card es8316-sound: ASoC: no sink widget found for IN1P
          24.410657] asoc-simple-card es8316-sound: ASoC: Failed to add route Mic Jack ->
904
      direct -> IN1P
905
          24.411211] es8316 1-0011: ASoC: Failed to create Left Hp mixer debugfs file
906
         24.411251] es8316 1-0011: ASoC: Failed to create Right Hp mixer debugfs file
907
         24.411315] es8316 1-0011: ASoC: Failed to create HPCP L debugfs file
908
         24.411350] es8316 1-0011: ASoC: Failed to create HPCP R debugfs file
909
      [ 24.411405] es8316 1-0011: ASoC: Failed to create HPVOL L debugfs file
         24.411439] es8316 1-0011: ASoC: Failed to create HPVOL R debugfs file
910
911
          24.416886] otg wakelock init: No USB transceiver found
912
        24.419733] rk808-rtc rk808-rtc: setting system clock to 2013-01-18 08:50:37 UTC
      Γ
     (1358499037)
913
      [ 24.423036] It doesn't contain Rogue gpu
          24.444988] vendor storage:20160801 ret = 0
914
915
          24.462371] I : [File] : drivers/gpu/arm/mali400/mali/linux/mali_kernel_linux.c;
     [Line] : 414; [Func] : mali_module_init(); svn_rev_string_from_arm of this mali_ko i.
916
         24.464906] Mali: Mali device driver loaded
917
        24.466091] input: rk29-keypad as /devices/platform/rockchip-key/input/input1
918
         24.468279] ALSA device list:
      [
      [ 24.468565] #0: rockchip,es8316-codec
                                                          //声卡初始化成功
919
         24.469767] Freeing unused kernel memory: 832K
920
921
        24.473279] init: init first stage started!
922
      Γ
          24.497729] dwmmc_rockchip fe310000.dwmmc: Successfully tuned phase to 203 //ANDROID启
     动标志
     24.499117] mmc2: queuing unknown CIS tuple 0x91 (3 bytes)
```

```
924
          24.4991501 mmc2: new ultra high speed SDR104 SDIO card at address 0001
925
          24.556542] audit: type=1403 audit(1358499037.633:2): policy loaded auid=4294967295
     ses=4294967295
          24.558434] init: (Initializing SELinux non-enforcing took 0.08s.)
926
         24.563661] init: init second stage started!
927
928
        24.569053] init: Setting ro.rk.soc=rk3399
        24.569575] init: OK, EMMC DRIVERS INIT OK
929
930
         24.569968] init: property_set("ro.boot.mode", "emmc") failed
      Γ
931
      [ 24.570542] init: property set("ro.hardware", "rk30board") failed
         24.573464] init: Running restorecon...
932
933
        24.664426] init: waitpid failed: No child processes
934
        24.664911] init: (Loading properties from /default.prop took 0.00s.)
935
          24.667572] init: (Parsing /init.environ.rc took 0.00s.)
936
        24.668067] init: (Parsing /init.usb.rc took 0.00s.)
937
         24.669185] init: (Parsing init.rk30board.bootmode.emmc.rc took 0.00s.)
        24.669837] init: (Parsing init.rk30board.usb.rc took 0.00s.)
938
         24.669891] init: (Parsing init.rk30board.environment.rc took 0.00s.)
939
940
          24.669971] init: could not import file '/init.stt trace.rc' from '/init.debug.rc': No
      Γ
     such file or directory
         24.670155] init: (Parsing /init.logs.rc took 0.00s.)
941
942
        24.670230] init: (Parsing /init.crashlogd.rc took 0.00s.)
         24.670311] init: (Parsing /init.coredump.rc took 0.00s.)
943
944
        24.670518] init: (Parsing /init.log-watch.rc took 0.00s.)
        24.670576] init: (Parsing /init.kernel.rc took 0.00s.)
945
946
         24.670679] init: (Parsing /init.debug-charging.rc took 0.00s.)
947
      [ 24.670697] init: (Parsing /init.debug.rc took 0.00s.)
         24.670715] init: (Parsing init.rockchip.rc took 0.00s.)
948
949
         24.671121] init: (Parsing init.connectivity.rc took 0.00s.)
950
        24.671162] init: could not import file 'init.box.samba.rc' from '/init.rk30board.rc':
      Γ
     No such file or directory
951
      [ 24.671258] init: (Parsing init.rk3399.rc took 0.00s.)
         24.671362] init: (Parsing init.tablet.rc took 0.00s.)
952
953
         24.671396] init: could not import file 'init.car.rc' from '/init.rk30board.rc': No
      such file or directory
      Γ
          24.671429] init: could not import file 'init.optee.rc' from '/init.rk30board.rc': No
     such file or directory
         24.671447] init: (Parsing /init.rk30board.rc took 0.00s.)
955
        24.672041] init: (Parsing /init.usb.configfs.rc took 0.00s.)
956
957
         24.672131] init: (Parsing /init.zygote64_32.rc took 0.00s.)
         24.672149] init: (Parsing /init.rc took 0.01s.)
958
      Γ
959
      [ 24.672755] init: Starting service 'ueventd'...
          24.677083] audit: type=1400 audit(1358499037.756:3): avc: denied { getattr } for
960
     pid=1 comm="init" path="/sys/kernel/debug/tracing/trace_marker" dev="tracefs" in1
         24.686012] ueventd: ueventd started!
961
962
      Γ
         24.686786] ueventd: invalid gid 'trace'
963
        24.895750] ueventd: Coldboot took 0.20s.
964
         24.919369] init: write_file: Unable to open '/proc/self/coredump_filter': No such
     file or directory
          24.919464] init: write file: Unable to open
965
      '/proc/sys/kernel/panic on stackoverflow': No such file or directory
966
         24.919512] init: Waiting for /dev/.coldboot_done...
          24.919608] init: Waiting for /dev/.coldboot done took 0.00s.
967
      [ 24.919646] init: /dev/hw random not found
968
```

```
969
           24.9202781 keychord: using input dev rk29-keypad for fevent
970
           24.926933] init: write file: Unable to open '/proc/cpu/alignment': No such file or
       Γ
      directory
           24.937454] Registered swp emulation handler
971
           24.937724] init: write file: Unable to open
972
      '/sys/module/rockchip pm/parameters/policy': No such file or directory
         24.938588] fs mgr: Warning: unknown flag resize
973
974
           25.284975] init: /dev/hw random not found
       [ 25.285156] init: write file: Unable to open '/sys/block/mmcblk0/bdi/read ahead kb':
975
      No such file or directory
976
       [ 25.286711] fs mgr: Warning: unknown flag resize
977
         25.939503] fs mgr: Enabling dm-verity for system (mode 2)
978
           25.940195] fs mgr: loading verity table: '1 /dev/block/platform/fe330000.sdhci/by-
      name/system /dev/block/platform/fe330000.sdhci/by-name/system 4096 4096 387072 387'
979
       Γ
           25.969515] EXT4-fs (dm-0): mounted filesystem with ordered data mode. Opts:
      noauto da alloc
980
       [ 25.970723] fs mgr: mount(source=/dev/block/dm-0,target=/system,type=ext4)=0
981
           25.972692] fs mgr: check fs(): mount(/dev/block/platform/fe330000.sdhci/by-
      name/cache,/cache,ext4)=-1: No such file or directory
982
         25.979705] fs_mgr: Running /system/bin/e2fsck on
      /dev/block/platform/fe330000.sdhci/by-name/cache
983
          25.995641] random: e2fsck: uninitialized urandom read (40 bytes read, 75 bits of
      entropy available)
          26.113420] e2fsck: e2fsck 1.42.9 (28-Dec-2013) //文件系统布置
984
       Γ
985
           26.113420]
986
         26.113626] e2fsck: /dev/block/platform/fe330000.sdhci/by-name/cache: recovering
      journal
987
       [ 26.113626]
       [ 26.113754] e2fsck: Superblock last mount time is in the future.
988
          26.113754]
989
990
          26.113806] e2fsck: (by less than a day, probably due to the hardware clock being
      incorrectly set) Fix? yes
991
       [ 26.113806]
992
       [ 26.113852] e2fsck:
993
       [
         26.113852]
994
         26.113897] e2fsck: /dev/block/platform/fe330000.sdhci/by-name/cache: clean, 23/8192
      files, 1611/32768 blocks (check in 4 mounts)
995
       [ 26.113897]
996
       [
         26.121478] EXT4-fs (mmcblk1p9): mounted filesystem with ordered data mode. Opts:
      noauto da alloc, discard
997
           26.126613] fs mgr: mount(source=/dev/block/platform/fe330000.sdhci/by-
      name/cache,target=/cache,type=ext4)=0
998
       [ 26.129054] EXT4-fs (mmcblk1p11): Ignoring removed nomblk_io_submit option
          26.136758] EXT4-fs (mmcblk1p11): recovery complete
999
1000
           26.137805] EXT4-fs (mmcblk1p11): mounted filesystem with ordered data mode. Opts:
      errors=remount-ro, nomblk io submit
1001
           26.138954] fs_mgr: check_fs(): mount(/dev/block/platform/fe330000.sdhci/by-
      name/metadata,/metadata,ext4)=0: Success
1002
           26.150279] fs_mgr: check_fs(): unmount(/metadata) succeeded
1003
           26.150621] fs_mgr: Running /system/bin/e2fsck on
      /dev/block/platform/fe330000.sdhci/by-name/metadata
           26.155247] random: e2fsck: uninitialized urandom read (40 bytes read, 81 bits of
1004
```

```
entropy available)
1005
           26.184481] e2fsck: e2fsck 1.42.9 (28-Dec-2013)
1006
           26.184481]
           26.184710] e2fsck: /dev/block/platform/fe330000.sdhci/by-name/metadata: clean,
1007
       [
      12/1024 files, 1105/4096 blocks (check in 2 mounts)
           26.1847101
1008
1009
       Γ
           26.190749] EXT4-fs (mmcblk1p11): mounted filesystem with ordered data mode. Opts:
      noauto da alloc, discard
1010
           26.190969] fs mgr: mount(source=/dev/block/platform/fe330000.sdhci/by-
      name/metadata,target=/metadata,type=ext4)=0
1011
           26.191173] fs_mgr: Running /system/bin/fsck.f2fs -a
      /dev/block/platform/fe330000.sdhci/by-name/userdata
1012
           26.204001] fsck.f2fs: executing /system/bin/fsck.f2fs failed: No such file or
       Γ
      directory
1013
           26.204001]
         26.204958] fsck.f2fs: fsck.f2fs terminated by exit(255)
1014
1015
          26. 2049581
1016
           26.209577] F2FS-fs (mmcblk1p15): Magic Mismatch, valid(0xf2f52010) - read(0x60fe5652)
1017
         26.210327] F2FS-fs (mmcblk1p15): Can't find valid F2FS filesystem in 1th superblock
           26.211674] F2FS-fs (mmcblk1p15): Magic Mismatch, valid(0xf2f52010) - read(0x9df872fc)
1018
         26.212417] F2FS-fs (mmcblk1p15): Can't find valid F2FS filesystem in 2th superblock
1019
          26.213162] F2FS-fs (mmcblk1p15): Magic Mismatch, valid(0xf2f52010) - read(0x60fe5652)
1020
1021
           26.213899] F2FS-fs (mmcblk1p15): Can't find valid F2FS filesystem in 1th superblock
           26.213938] F2FS-fs (mmcblk1p15): Magic Mismatch, valid(0xf2f52010) - read(0x9df872fc)
1022
       1023
           26.213964] F2FS-fs (mmcblk1p15): Can't find valid F2FS filesystem in 2th superblock
       1024
           26.214215] fs mgr: mount(source=/dev/block/platform/fe330000.sdhci/by-
      name/userdata,target=/data,type=f2fs)=-1
1025
           26.217457] fs mgr: fs mgr mount all(): possibly an encryptable blkdev
      /dev/block/platform/fe330000.sdhci/by-name/userdata for mount /data type f2fs )
1026
           26.225533] init: (Parsing /system/etc/init/atrace.rc took 0.00s.)
1027
           26.226359] init: (Parsing /system/etc/init/audioserver.rc took 0.00s.)
           26.226836] init: (Parsing /system/etc/init/bootanim.rc took 0.00s.)
1028
1029
           26.227458] init: (Parsing /system/etc/init/bootstat.rc took 0.00s.)
1030
           26.227969] init: (Parsing /system/etc/init/cameraserver.rc took 0.00s.)
1031
           26.228449] init: (Parsing /system/etc/init/debuggerd.rc took 0.00s.)
       Γ
1032
           26.228910] init: (Parsing /system/etc/init/debuggerd64.rc took 0.00s.)
           26.229401] init: (Parsing /system/etc/init/drmserver.rc took 0.00s.)
1033
           26.230037] init: (Parsing /system/etc/init/dumpstate.rc took 0.00s.)
1034
1035
           26.230623] init: (Parsing /system/etc/init/gatekeeperd.rc took 0.00s.)
1036
           26.231164] init: (Parsing /system/etc/init/init-debug.rc took 0.00s.)
       Γ
1037
           26.231681] init: (Parsing /system/etc/init/installd.rc took 0.00s.)
           26.232161] init: (Parsing /system/etc/init/keystore.rc took 0.00s.)
1038
       [
1039
           26.232647] init: (Parsing /system/etc/init/lmkd.rc took 0.00s.)
           26.233663] init: (Parsing /system/etc/init/logcatd.rc took 0.00s.)
1040
1041
           26.235914] init: (Parsing /system/etc/init/logd.rc took 0.00s.)
       Γ
1042
           26.236422] init: (Parsing /system/etc/init/mdnsd.rc took 0.00s.)
       Γ
1043
           26.236909] init: (Parsing /system/etc/init/mediacodec.rc took 0.00s.)
       [
           26.237508] init: (Parsing /system/etc/init/mediadrmserver.rc took 0.00s.)
1044
           26.238001] init: (Parsing /system/etc/init/mediaextractor.rc took 0.00s.)
1045
           26.238542] init: ignored duplicate definition of service 'media'init: (Parsing
1046
      /system/etc/init/mediaserver.rc took 0.00s.)
1047
           26.239089] init: (Parsing /system/etc/init/mtpd.rc took 0.00s.)
           26.239574] init: (Parsing /system/etc/init/netd.rc took 0.00s.)
1048
```

```
1049
           26.239959] init: (Parsing /system/etc/init/perfprofd.rc took 0.00s.)
1050
           26.240387] init: (Parsing /system/etc/init/racoon.rc took 0.00s.)
1051
           26.241091] init: ignored duplicate definition of service 'ril-daemon'init: (Parsing
      /system/etc/init/rild.rc took 0.00s.)
1052
           26.241636] init: (Parsing /system/etc/init/servicemanager.rc took 0.00s.)
1053
         26.242115] init: (Parsing /system/etc/init/surfaceflinger.rc took 0.00s.)
       [ 26.242614] init: (Parsing /system/etc/init/uncrypt.rc took 0.00s.)
1054
1055
           26.243115] init: (Parsing /system/etc/init/vdc.rc took 0.00s.)
1056
       [ 26.243614] init: (Parsing /system/etc/init/vold.rc took 0.00s.)
           26.246165] init: Starting service 'logd'...
1057
1058
           26.261334] random: logd: uninitialized urandom read (40 bytes read, 85 bits of
      entropy available)
1059
           26.268730] init: insmod: open("/system/lib/modules/ump.ko") failed: No such file or
       Γ
      directoryinit: insmod: open("/system/lib/modules/mali.ko") failed: No such file e
1060
           26.278412] zram0: detected capacity change from 0 to 533413888
           26.286518] random: mkswap: uninitialized urandom read (40 bytes read, 86 bits of
1061
      entropy available)
1062
           26.324320] random: mkswap: uninitialized urandom read (16 bytes read, 87 bits of
       Γ
      entropy available)
           26.325523] logd.auditd: start
1063
1064
         26.325597] logd.klogd: 26321917163
          26.327870] Adding 520908k swap on /dev/block/zram0. Priority:-1 extents:1
1065
      across:520908k SS
          26.332192] init: property_set("ro.board.platform", "rk3399") failed
1066
       Γ
1067
           26.332978] init: property_set("ro.rk.screenshot_enable", "true") failed
1068
       [ 26.333223] init: (Loading properties from /system/build.prop took 0.00s.)
1069
         26.333311] init: (Loading properties from /vendor/build.prop took 0.00s.)
       [ 26.333405] init: (Loading properties from /factory/factory.prop took 0.00s.)
1070
       [ 26.333558] fs mgr: Warning: unknown flag resize
1071
          26.333740] init: /recovery not specified in fstab
1072
1073
       [ 26.334809] init: Starting service 'debuggerd'...
         26.336563] init: Starting service 'debuggerd64'...
1074
1075
       [ 26.338689] init: Starting service 'vold'...
1076
           26.341710] init: Not bootcharting.
1077
           26.344111] random: debuggerd64: uninitialized urandom read (40 bytes read, 88 bits of
      entropy available)
           26.352356] random: debuggerd: uninitialized urandom read (40 bytes read, 88 bits of
1078
      entropy available)
1079
       [
         26.355525] random: vold: uninitialized urandom read (40 bytes read, 88 bits of
      entropy available)
1080
       26.361691] random: vdc: uninitialized urandom read (40 bytes read, 89 bits of entropy
      available)
1081
       [ 26.495989] fs_mgr: Warning: unknown flag resize
           26.536908] init: Starting service 'exec 1 (/system/bin/tzdatacheck)'...
1082
1083
           26.542318] random: tzdatacheck: uninitialized urandom read (40 bytes read, 94 bits of
      entropy available)
1084
           26.555665] init: Service 'exec 1 (/system/bin/tzdatacheck)' (pid 231) exited with
       [
      status 0
           26.562770] tmpfs: Bad mount option background_gc
1085
1086
           26.563864] type=1400 audit(1358499039.640:4): avc: denied { create } for pid=1
      comm="init" name="cifsmanager" scontext=u:r:init:s0 tcontext=u:object_r:cifsmanager_e1
           26.566680] init: write_file: Unable to open '/proc/sys/kernel/core_pattern': No such
1087
```

```
file or directory
1088
           26.567171] type=1400 audit(1358499039.640:5): avc: denied { setattr } for pid=1
      comm="init" name="cifsmanager" dev="tmpfs" ino=3507 scontext=u:r:init:s0 tcontext=u:1
           26.568042] init: (Loading properties from /data/local.prop took 0.00s.)
1089
           26.570632] init: Starting service 'logd-reinit'...
1090
1091
         26.573275] init: write file: Unable to open '/proc/sys/vm/min free order shift': No
      such file or directory
1092
           26.575905] init: Starting service 'healthd'...
1093
           26.577441] init: cannot find '/system/bin/displayd' (No such file or directory),
      disabling 'displayd'
1094
       [ 26.579263] init: Starting service 'earlylogs'...
1095
         26.581434] binder: 235:235 transaction failed 29189/-22, size 0-0 line 3008
1096
       [ 26.581727] init: Starting service 'lmkd'...
1097
       [ 26.583352] init: Starting service 'servicemanager'...
1098
          26.586345] init: Starting service 'surfaceflinger'...
         26.590300] init: SELinux: Could not stat
1099
      /sys/devices/system/cpu/cpufreq/interactive: No such file or directory.
1100
           26.594621] init: write file: Unable to open
      '/proc/sys/vm/lazy vfree tlb flush all threshold': No such file or directory
1101
           26.603566] init: property 'ro.serialno' doesn't exist while expanding
      '${ro.serialno}'
       [ 26.604450] init: write: cannot expand '${ro.serialno}'
1102
1103
       [ 26.605181] init: Service 'earlylogs' (pid 236) exited with status 0
1104
       [ 26.608201] file system registered
1105
          26.609726] using random self ethernet address
1106
       [ 26.610153] using random host ethernet address
1107
          26.610633] init: write_file: Unable to open
      '/config/usb_gadget/g1/functions/rndis.gs4/wceis': Permission denied
1108
           26.618941] init: Starting service 'console'...
1109
           26.619950] type=1400 audit(1358499039.676:6): avc: denied { relabelto } for pid=1
       comm="init" name="recovery" dev="tmpfs" ino=10040 scontext=u:r:init:s0 tcontext=u:1
           26.620279] type=1400 audit(1358499039.676:7): avc: denied { relabelto } for pid=1
1110
      comm="init" name="boot" dev="tmpfs" ino=10036 scontext=u:r:init:s0 tcontext=u:obje1
       [ 26.621405] logd.daemon: reinit
1111
1112
         26.622083] init: Starting service 'adbd'...
1113
       [ 26.626065] init: Service 'logd-reinit' (pid 234) exited with status 0
         26.627176] init: Starting service 'exec 2 (/system/bin/vdc)'...
1114
           26.642745] init: Service 'exec 2 (/system/bin/vdc)' (pid 243) exited with status 0
1115
1116
       rk3399_mid:/ $ [ 27.338230] init: Starting service 'bootanim'... //ANDROID动画开始
1117
         27.586005] healthd: BatteryCurrentNowPath not found
1118
       [ 27.586044] healthd: BatteryCycleCountPath not found
         27.586486] healthd: battery l=50 v=3 t=2.6 h=2 st=3 fc=100 chg=au
1119
1120
       [ 27.586881] healthd: battery 1=50 v=3 t=2.6 h=2 st=3 fc=100 chg=au
         27.587321] healthd: battery l=50 v=3 t=2.6 h=2 st=3 fc=100 chg=au
1121
1122
         27.587696] healthd: battery 1=50 v=3 t=2.6 h=2 st=3 fc=100 chg=au
1123
          27.709328] init: avc: denied { set } for property=ctl.bootanim pid=224 uid=0 gid=0
      scontext=u:r:vold:s0 tcontext=u:object_r:ctl_bootanim_prop:s0 tclass=property_s1
         27.724849] fs mgr: Running /system/bin/fsck.f2fs -a /dev/block/dm-1
1124
         27.737113] fsck.f2fs: executing /system/bin/fsck.f2fs failed: No such file or
1125
       [
      directory
1126
       [ 27.737113]
1127
           27.738045] fsck.f2fs: fsck.f2fs terminated by exit(255)
1128
     ]
         27.738045]
```

```
1129
           27.8364461 F2FS-fs (dm-1): recover inode: ino = 536, name = .temp.7kN7Pf
1130
           27.837893] F2FS-fs (dm-1): recover dentry: ino = 536, name = .temp.7kN7Pf, dir = 2e,
       Γ
      err = 0
         27.871587] fs_mgr: __mount(source=/dev/block/dm-1,target=/data,type=f2fs)=0
1131
       [
         27.875185] init: (Loading properties from /data/local.prop took 0.00s.)
1132
       [ 27.903178] init: Starting service 'logd-reinit'...
1133
1134
       [ 27.909327] init: Starting service 'ap log srv'...
1135
       [ 27.919508] init: Not bootcharting.
       [ 27.940149] logd.daemon: reinit
1136
          27.943390] init: Service 'logd-reinit' (pid 302) exited with status 0
1137
1138
       Γ
         28.005049] init: Starting service 'exec 3 (/system/bin/tzdatacheck)'... //启动各种
      ANDROID服务
1139
           28.019594] init: Starting service 'apk logfs'...
       Γ
1140
           28.023342] init: Service 'ap log srv' (pid 303) exited with status 0
1141
       Γ
           28.024807] init: Service 'exec 3 (/system/bin/tzdatacheck)' (pid 309) exited with
      status 0
1142
       [ 28.035033] type=1400 audit(1358499041.113:8): avc: denied { setattr } for pid=1
      comm="init" name="cifsmanager" dev="dm-1" ino=86 scontext=u:r:init:s0 tcontext=u:obj1
1143
       [ 28.046055] init: write file: Unable to open '/proc/sys/kernel/core pattern': No such
      file or directory
1144
       [ 28.047219] init: Starting service 'exec 4 (/system/bin/bootstat)'...
          28.075711] init: Service 'exec 4 (/system/bin/bootstat)' (pid 312) exited with status
1145
       Γ
      a
       [ 28.076529] init: cannot find '/system/bin/update verifier' (No such file or
1146
      directory), disabling 'exec 5 (/system/bin/update_verifier)'
1147
           28.076580] init: cannot find '/system/bin/install-recovery.sh' (No such file or
      directory), disabling 'flash_recovery'
1148
         28.077174] init: Starting service 'drmservice'...
1149
           28.079267] init: cannot find '/system/bin/bplus helper' (No such file or directory),
       Γ
      disabling 'bplus_helper'
1150
       [ 28.079915] init: Service up eth0 does not have a SELinux domain defined.
           28.079947] init: cannot find '/system/bin/rk store keybox' (No such file or
1151
      directory), disabling 'rk_store_keybox'
1152
       [ 28.080218] init: Starting service 'akmd'...
1153
       [
         28.084184] init: Starting service 'media'...
1154
       [ 28.088216] init: Starting service 'zygote'...
         28.092223] init: Starting service 'zygote secondary'...
1155
       [ 28.096382] init: Starting service 'audioserver'...
1156
1157
         28.099994] init: Starting service 'cameraserver'...
1158
           28.101635] init: couldn't write 321 to /dev/cpuset/camera-daemon/tasks: No such file
       Γ
      or directory
         28.103584] init: Starting service 'drm'...
1159
       [ 28.107808] init: Starting service 'installd'...
1160
         28.113526] init: Starting service 'keystore'...
1161
1162
         28.121386] init: Starting service 'mediacodec'...
1163
       [ 28.125026] init: Starting service 'mediadrm'...
1164
          28.130230] init: Starting service 'mediaextractor'...
       [
       [ 28.136504] init: Starting service 'netd'...
1165
1166
         28.148010] random: nonblocking pool is initialized
       [ 28.174167] init: Starting service 'crashlogd'...
1167
1168
       [ 28.176240] init: Starting service 'log-watch'...
           28.180606] init: Starting service 'gatekeeperd'...
1169
         28.202351] init: Starting service 'perfprofd'...
1170
      | [
```

```
1171 [ 28.217467] init: Service 'drmservice' (pid 314) exited with status 0
1172
       [ 28.231108] read descriptors
      [ 28.231159] read descriptors
1173
      [ 28.231168] read strings
1174
1175
      [ 28.234740] akmd[315]: unhandled level 1 translation fault (11) at 0x00000000, esr
      0x92000005
                      //应用层非法使用
     [ 28.234780] pgd = ffffffc0e8190000
1176
1177
         28.234787] [00000000] *pgd=000000000000000, *pud=000000000000000
      [ 28.234800]
1178
         28.234811] CPU: 2 PID: 315 Comm: akmd Not tainted 4.4.103 #1185
1179
       [ 28.234818] Hardware name: Rockchip RK3399 Evaluation Board v3 (Android) (DT)
1180
1181
       [ 28.234827] task: ffffffc0e8220000 task.stack: ffffffc0e8210000
      [ 28.234837] PC is at 0x799b4f47d8
1182
      [ 28.234843] LR is at 0x65478a7720
1183
         28.234850] pc : [<000000799b4f47d8>] lr : [<00000065478a7720>] pstate: 60000000
1184
1185
       [ 28.234857] sp : 0000007fc03adce0
       [ 28.234862] x29: 0000007fc03adcf0 x28: 0000000000000000
1186
      [ 28.234873] x27: 0000007fc03add58 x26: e30d94d4d4dd6983
1187
1188
      [ 28.234884] x25: 000000000000000 x24: 000000000000000
         28.234895] x23: 000000000000000 x22: 0000007fc03ae688
1189
1190
       [ 28.234906] x21: 00000065478a6e84 x20: 00000065478b4000
1191
         28.234917] x19: 000000000000000 x18: 000000000000000
      [ 28.234927] x17: 000000799b4f47c8 x16: 00000065478b3fe0
1192
      [ 28.234939] x15: 00001f0ffc89c449 x14: 000b532cf2c194a5
1193
1194
         28.234949] x13: 0000000050f90ce1 x12: 0000000000000018
1195
       [ 28.234960] x11: 000000000000000 x10: 0000007fc03ad790
1196
         28.234971] x9 : 000000000000010 x8 : 000000000000000
      [ 28.234981] x7 : 0000000000000c7c x6 : 000000799b63d000
1197
      [ 28.234992] x5 : 000080000000000 x4 : 000000000000004d
1198
         28.235002] x3 : 000000000000000 x2 : 000000000000000
1199
1200
      [ 28.235013] x1 : 0000007fc03ad600 x0 : 0000000000000000
         28.235023]
1201
     [ 28.257851] init: Service 'akmd' (pid 315) killed by signal 11
1202
1203
         28.451338] Freeing drm logo memory: 660K
      [
1204
      Γ
         31.193137] capability: warning: `main' uses 32-bit capabilities (legacy support in
      use)
      [ 38.191997] healthd: battery 1=50 v=3 t=2.6 h=2 st=3 fc=100 chg=au
1205
      [ 39.993352] android_work: did not send uevent (0 0
1206
1207
         39.993466] configfs-gadget gadget: unbind function 'mtp'/ffffffc0ef13b400
1208
      [ 39.993530] configfs-gadget gadget: unbind function 'Function FS
      Gadget'/ffffffc0e71a6e38
      [ 39.994133] init: Service 'adbd' is being killed...
1209
1210
      [ 39.998168] init: Service 'adbd' (pid 242) killed by signal 9
      [ 39.998282] init: Service 'adbd' (pid 242) killing any children in process group
1211
       [ 40.043397] init: Starting service 'adbd'...
1212
1213
      [ 40.058164] read descriptors
1214
      [ 40.058330] read descriptors
      [ 40.058361] read strings
1215
       [ 40.097118] acc_open
1216
1217
      [ 40.097299] acc_release
1218
      [ 40.507346] rk gmac-dwmac fe300000.ethernet: rk get eth addr: mac address:
      22:9a:18:a4:eb:d9
     [ 40.507445] eth0: device MAC address 22:9a:18:a4:eb:d9
1219
```

```
1220 [ 42.019341] type=1400 audit(1358499055.096:9): avc: denied { read } for pid=320
      comm="AudioOut D" name="audioformat" dev="sysfs" ino=19012 scontext=u:r:audioserver:s1
1221
       [ 42.019794] type=1400 audit(1358499055.096:10): avc: denied { open } for pid=320
      comm="AudioOut_D" path="/sys/devices/platform/display-subsystem/drm/card0/card0-HDMI1
      [ 42.020004] type=1400 audit(1358499055.096:11): avc: denied { getattr } for pid=320
1222
      comm="AudioOut D" path="/sys/devices/platform/display-subsystem/drm/card0/card0-H1
      [ 42.605903] init: Service 'bootanim' is being killed...
1223
                                                                      //ANDROID动画结束
1224
         42.636539] init: cannot find '/system/bin/glgps' (No such file or directory),
      disabling 'gpsd'
       [ 42.636879] init: Starting service 'exec 6 (/system/bin/bootstat)'...
1225
1226
      [ 42.646035] init: Service 'bootanim' (pid 292) killed by signal 9
1227
      [ 42.655098] init: Service 'exec 6 (/system/bin/bootstat)' (pid 1062) exited with
      status 0
1228
      [ 42.656133] init: Starting service 'exec 7 (/system/bin/bootstat)'...
1229
      [ 42.671000] init: Service 'exec 7 (/system/bin/bootstat)' (pid 1065) exited with
      status 0
      [ 42.671989] init: Starting service 'exec 8 (/system/bin/bootstat)'...
1230
1231
      [ 42.688309] init: Service 'exec 8 (/system/bin/bootstat)' (pid 1066) exited with
      [ 42.689272] init: Starting service 'exec 9 (/system/bin/bootstat)'...
1232
1233
      [ 42.731200] init: Service 'exec 9 (/system/bin/bootstat)' (pid 1067) exited with
                   //ANDROID动画结束
      status 0
1234
      [ 53.838543] dw-mipi-dsi ff960000.dsi: vop BIG output to dsi0
      [ 53.838705] dw-mipi-dsi ff960000.dsi: final DSI-Link bandwidth: 1064 x 4 Mbps
1235
         53.849049] dw-mipi-dsi ff960000.dsi: failed to wait for phy lock state
1236
1237
       [ 53.977794] PM: suspend entry 2013-01-18 08:51:07.058334719 UTC //待机启动标志
1238
         53.977892] PM: Syncing filesystems ... done.
1239
      [ 54.025426] Freezing user space processes ... (elapsed 0.005 seconds) done.
      [ 54.031296] Freezing remaining freezable tasks ... (elapsed 0.003 seconds) done.
1240
1241
       [ 54.035404] Suspending console(s) (use no console suspend to debug)
1242
      INFO: sleep mode config[0xfe]:
                     AP PWROFF
1243
      INFO:
1244
      INFO:
                      SLP ARMPD
1245
      INFO:
                      SLP PLLPD
1246
      INFO:
                      DDR RET
1247
      INFO:
                      SLP CENTER PD
      INFO:
                     OSC_DIS
1248
      INFO: wakeup source config[0x4]:
1249
1250
      INFO:
                     GPIO interrupt can wakeup system
1251
       INFO: PWM CONFIG[0x4]:
1252
      INFO:
                      PWM: PWM2D REGULATOR EN
1253
      INFO: APIOS info[0x0]:
1254
      INFO:
                      not config
               GPIO POWER INFO:
1255
      INFO:
1256
       INFO:
                      GPI01 C1
1257
      INFO:
               PMU MODE CONG: 0x1477bf79
1258
       INFO:
               RK3399 the wake up information:
1259
      INFO:
               wake up status: 0x4
1260
       INFO:
                      GPIO interrupt wakeup
1261
       INFO:
                      GPI00: 0x0
1262
       INFO:
                      GPI01: 0x200000
1263
       INFO:
                      GPI02: 0x0
1264
      INFO:
                      GPI03: 0x0
```

```
1265
      ♦[ 54.241088] [WLAN RFKILL]: Enter rfkill wlan suspend
1266
       54.242183] PM: suspend of devices complete after 205.187 msecs
1267
         54.254053] PM: late suspend of devices complete after 2.598 msecs
       [
      [ 54.256545] PM: noirq suspend of devices complete after 2.475 msecs
1268
         54.256553] Disabling non-boot CPUs ...
1269
       [ 54.277766] CPU1: shutdown
1270
       [ 54.290360] psci: Retrying again to check for CPU kill
1271
1272
      [ 54.290365] psci: CPU1 killed.
      [ 54.344261] CPU2: shutdown
1273
         54.357035] psci: Retrying again to check for CPU kill
1274
       [ 54.357039] psci: CPU2 killed.
1275
1276
       [ 54.397515] CPU3: shutdown
1277
      [ 54.410365] psci: Retrying again to check for CPU kill
1278
      [ 54.410369] psci: CPU3 killed.
         54.444054] CPU4: shutdown
1279
       [ 54.457014] psci: Retrying again to check for CPU kill
1280
       [ 54.457018] psci: CPU4 killed.
1281
1282
      [ 54.490618] CPU5: shutdown
1283
      [ 54.503682] psci: Retrying again to check for CPU kill
         54.503686] psci: CPU5 killed.
1284
1285
       [ 54.516595] Enabling non-boot CPUs ...
         54.534909] Detected VIPT I-cache on CPU1
1286
      [ 54.534949] CPU1: found redistributor 1 region 0:0x000000000fef20000
1287
      [ 54.535017] CPU1: update cpu capacity 401
1288
1289
         54.535021] CPU1: Booted secondary processor [410fd034]
1290
       [ 54.535706] CPU1 is up
1291
         54.554700] Detected VIPT I-cache on CPU2
      [ 54.554723] CPU2: found redistributor 2 region 0:0x000000000fef40000
1292
1293
       [ 54.554761] CPU2: update cpu capacity 401
1294
         54.554764] CPU2: Booted secondary processor [410fd034]
       1295
       [ 54.555426] CPU2 is up
         54.574932] Detected VIPT I-cache on CPU3
1296
      [ 54.574955] CPU3: found redistributor 3 region 0:0x000000000fef60000
1297
       [ 54.574994] CPU3: update cpu_capacity 401
1298
1299
       [ 54.574998] CPU3: Booted secondary processor [410fd034]
1300
       [ 54.575801] CPU3 is up
         54.595191] Detected PIPT I-cache on CPU4
1301
1302
      [ 54.595220] CPU4: found redistributor 100 region 0:0x000000000fef80000
1303
       [ 54.595280] CPU4: update cpu_capacity 1024
1304
       [ 54.595283] CPU4: Booted secondary processor [410fd082]
1305
       [ 54.598647] CPU4 is up
         54.622231] Detected PIPT I-cache on CPU5
1306
       [
1307
      [ 54.622249] CPU5: found redistributor 101 region 0:0x000000000fefa0000
       [ 54.622289] CPU5: update cpu_capacity 1024
1308
1309
       [ 54.622292] CPU5: Booted secondary processor [410fd082]
1310
       [ 54.625630] CPU5 is up
1311
         54.627806] PM: noirq resume of devices complete after 2.017 msecs
       [
      [ 54.631002] PM: early resume of devices complete after 2.605 msecs
1312
         54.637408] rk_gmac-dwmac fe300000.ethernet: init for RGMII
1313
       [ 54.716006] [WLAN_RFKILL]: Enter rfkill_wlan_resume
1314
1315
      [ 54.721769] Suspended for 33.201 seconds
       [ 54.722040] cdn-dp fec00000.dp: [drm:cdn_dp_pd_event_work] Not connected. Disabling
1316
```

```
cdn
1317
       [ 54.724641] usb usb1: root hub lost power or was reset
1318
         54.726843] usb usb2: root hub lost power or was reset
       [
      [ 54.784794] usb usb3: root hub lost power or was reset
1319
         54.841509] usb usb4: root hub lost power or was reset
1320
      [ 54.853801] mmc_host mmc2: Bus speed (slot 0) = 400000Hz (slot req 400000Hz, actual
1321
      400000HZ div = 0)
1322
      [ 54.912694] mmc2: queuing unknown CIS tuple 0x80 (2 bytes)
      [ 54.914290] mmc2: queuing unknown CIS tuple 0x80 (3 bytes)
1323
         54.915875] mmc2: queuing unknown CIS tuple 0x80 (3 bytes)
1324
      [ 54.918719] mmc2: queuing unknown CIS tuple 0x80 (7 bytes)
1325
1326
      [ 54.975663] mmc host mmc2: Bus speed (slot 0) = 150000000Hz (slot req 150000000Hz,
      actual 150000000HZ div = 0)
1327
       [ 55.104118] dwmmc rockchip fe310000.dwmmc: Successfully tuned phase to 205
1328
         55.104173] PM: resume of devices complete after 472.044 msecs
      [ 55.105538] [BT_RFKILL]: ** disable irq
1329
       [ 55.109774] Restarting tasks ...
1330
      [ 55.125869] healthd: battery 1=50 v=3 t=2.6 h=2 st=3 fc=100 chg=au
1331
      [ 55.151813] done.
1332
         55.156142] PM: suspend exit 2013-01-18 08:51:41.437918253 UTC
1333
      [ 55.207785] binder: release 1350:1365 transaction 18865 in, still active
1334
       [ 55.207869] binder: send failed reply for transaction 18865 to 603:677
1335
      [ 55.307869] PM: suspend entry 2013-01-18 08:51:41.589653268 UTC
1336
       [ 55.307941] PM: Syncing filesystems ... done.
1337
1338
         55.319202] Freezing user space processes ... (elapsed 0.002 seconds) done.
       1339
      [ 55.322026] Freezing remaining freezable tasks ... (elapsed 0.002 seconds) done.
1340
     [ 55.324154] Suspending console(s) (use no_console_suspend to debug)
```