




(a) Stress overshoot and thermal rise



(b) Slip-system activation



(c) Dislocation-state evolution



(d) Work-heat-storage partition

