NATIONAL UNIVERSITY OF SINGAPORE Department of Electrical and Computer Engineering

CG2028 Computer Organization Tutorial 6 Pipelining Basics

1. Insert NOPs in the code below to ensure correct operation in a 5-stage pipelined ARM processor.

L1: AND R8, R9, R11

L2: ADD R1, R2, #8

L3: SUB R2, R5, R7

L4: LDR R3, [R1, #4]

L5: CMP R0, #0

L6: BNE SKIP

- 2. Can the instructions in the code above be rearranged to reduce the number of NOPs to be inserted to eliminate data hazards?
- 3. What is the total number of cycles required for executing the code you obtained in Q.2 if the branch is not taken?