Team Weekly Report

Team: Bray IIoT Smart Solutions

Week: 6

Members: Aysen De La Cruz, Matthew Livesay, Alex Kearney, Abdiel Rivera, Josh Werner

Status Report

Since our last report, we have slowly been making progress towards the project. Some of the firmware for the project has been written and the final draft of the database design is in the works. We have gotten new hardware that will allow us to more easily test the system for further development. The power supply for one of our components has also broken, but that should be a quick fix.

Current Status

1. What did the team work on this past week?

| Task | Task Lead | Status | Notes |
|---|--|-------------|---|
| Development of web application | Abdiel Rivera/Josh Werner/Alex Kearney | In Progress | Roadblocks in terms of backend structures |
| Development of transmitter firmware | Aysen De La Cruz | In Progress | |
| Update database structures | Josh Werner | In Progress | Delay due to new hardware component complications |
| Planning new software updates and additions | N/A | In Progress | Backend redesign is our main focus area |
| Picked up torque data spoofer hardware from Bray | Matthew Livesay | Done | |
| Configure the R-Pi server for data collection | Alex Kearney | Done | R-Pi server automatically pulls the GitHub repo and runs docker containers |
| Be able to flash a known good version of the firmware to the LoRa board | Matthew Livesay | Done | Waiting for instructions. I think I can do it now but don't want to brick the board |
| Report modifications | Alex Kearney | In Progress | Updated previous descriptions of the |

| | solution to reflect the current direction of the project. |
|--|---|
| | the project. |

2. What feedback has the team received? No feedback was received this week.

| From Whom | Feedback | Next Steps |
|-----------|----------|------------|
| | | |

3. Are any resources needed? If so, what? No resources are needed at this moment.

Plans for Next Week

What are your plans for this next week?

| Task | Task Lead | Notes |
|--|---|--|
| Development of web application | Abdiel Rivera/Josh Werner/Alex Kearney | Database Redesign/Frontend Connection |
| Development of transmitter firmware | Aysen De La Cruz | |
| Consider updates to database structures for torque spoofer | Josh Werner | |
| Planning new software updates and additions | N/A | Continuing to fully understand the project and plan for new tasks as necessary. |
| Understand legacy code for the firmware. It's a mess currently | Matthew Livesay Aysen De La Cruz | |
| Report Modifications | Alex Kearney | Updated previous descriptions of the solution to reflect the current direction of the project. |
| Report: Engineering Standards and Regulations | Alex Kearney | |

|--|