

Heron Service Manual (2nd Edition)

Document: MAN-HER-2

Type: Manual

Model: Heron

Published: 2020-06-15

1 Brakes

Brake system service for all Heron variants.

1.1 Front Brake Pad and Rotor Service

Replace pads with brake pad kit BP-7720. On vehicles with judder complaints, replace rotors BR-7731 in pairs - do not machine.

1.2 Brake Hose Inspection

Inspect front brake hose BH-7745 for abrasion at the strut bracket at every service.

1.3 ABS Diagnosis

Codes C0035 and U0121 - check wheel speed sensor WSS-3300 wiring at the wheel arch before module replacement.

2 Chassis Electrical

Electrical service for chassis systems.

2.1 Wheel Speed Sensor Replacement

Replace wheel speed sensor WSS-3300 and route the harness clear of the spring. Clears code C0035 after relearn.

2.2 Battery and Charging

Battery BAT-1200 and alternator ALT-8810 service points are shared with the Falcon platform.