## Actual - Possible foreign body in R) Eye

Event details				Photo from the event
Physical location	Minerals Australia > Western Australia Iron Ore > Rail > Track > Yards			
Impact type & Severity	Safety Actual (AL1, PL2)			
Date & Time	May 28, 2025 2:30 PM	Event number	1001403591	
Reporting category	Category 1 reportable	Employment status of involved	Contractor	
Risk	N/A	Risk category	N/A	
Event Owner	Melinda McDonald (20039137)	Org unit of Event Owner	Track Maintenance & Flashbutt Execution (30072266)	
Event status	Closed	Investigation status	N/A	
Description	IP was completing prep grinding work at 310SW in Nelson Point. Grinding was being completed with handheld grinder the IP reported feeling a sudden hot sensation in his right eye and eyelid, caused by hot spark from grinding whilst wearing faceshield and foam backed glasses.			
Immediate actions	Stopped work, reported to site RP, attended ESO for review.			

