


## PRO PCB ISSUES 2022-04-06

- 0) The bottom PCB has a slightly larger diameter than the top PCB? Why?
- 1) Connector overlaps the hex standoff
- 2) Component overlaps hex standoff
- 3) Component overlaps hex standoff
- 4) Component overlaps hex standoff
- 5) Component almost overlaps hex standoff (move the two black connectors slightly closer together.



- 6) Component overlaps hex standoff
- 7) Component overlaps hex standoff
- 8) Component overlaps hex standoff
- 9) Component overlaps hex standoff
- 10) Component overlaps hex standoff





11) Component overlaps hex standoff