

Frame 601: 85.2 cm error from weak curb support and source/map geometric disagreement
Controlled diagnosis only; production settings unchanged

