

HERMS & BrewManiacEx

Step 1 - Fill Hot Liquor Tank with Water




Step 2 – Heat Strike Water





- HLT 240V SSR ON
- Water Pump **ON**
- Buzzer **ON** at water temp target


Step 3 – Transfer Strike Water to Mash Tun




BrewPiEx

- HLT 240V SSR ON
- Water Pump **ON**


Step 4 – Mash & Mash-Out




Step 5 – Sparge



Step 6 – Boil









Water
out
in
Water
in
Wort
out

Counter-flow
Heat Exchanger

Water
pump



Wort pump

Boil 240V SSR ON

Step 7 – Chill

