

## **HERMS & BrewManiacEx**

Step 1 - Fill Hot Liquor Tank with Water




Step 2 – Heat Strike Water





- HLT 240V SSR ON
- Water Pump ON
- Buzzer **ON** at water temp target


Step 3 – Transfer Strike Water to Mash Tun




BrewMEx

- HLT 240V SSR ON
- Water Pump ON


Step 4 – Mash & Mash-Out




Step 5 – Sparge




Step 6 – Boil













Wort pump

Boil 240V SSR ON

Step 7 – Chill

