


TODO: Extend the pads of the fuses, electrolitic caps, and proection diods.

TODO: Increase the resistor of the greed +5V LED. It's too bright.



Isolated DC/DC



Edge Connector