







THERMISTOR 2

THERMISTOR 3

TODO: Should MOSI be pulled up or down?

TODO: Add jumpers for two SPI channels.

TODO: Consider to add constant current NTC 50K thermistor inputs.

ADD INPUTS for two thermistors.









