




TODO: Verify 5V LDO power











TODO: VMON signals needed?
TODO: Ok to leave all MPU inputs floating?

