

## Office of Science Washington, DC 20585

September 7, 2011

MEMORANDUM FOR ROGER E. SNYDER

MANAGER, PACIFIC NORTHWEST SITE OFFICE

FROM:

JOSEPH A. MCBREARTY am Brenty 9/1/11

DEPUTY DIRECTOR FOR FIELD OPERATIONS

SUBJECT:

Delegations of Authority for Office of Science

Operations and Safety, and Property Management

Designated authorities assigned through the responsibilities listed in Department of Energy (DOE) Directives and Rules or otherwise delegated to me through DOE Delegation Orders are established to ensure objective and consistent decision making by appropriate levels of line management. This memorandum delegates to you the Office of Science (SC) specific authorities listed on Attachment 1 based upon your qualifications and expertise described in the memorandum from the Deputy Secretary dated December 27, 2005, Delegations of Safety Authorities. Unless otherwise specified, these may not be re-delegated. The authorities listed on the attachment will continue until rescinded, amended or superseded in writing.

Attachment 1

cc: Gene Runkle, SC-3 Carol Sohn, SC-3 Marc Jones, SC-31 Devon Streit, SC-32

## Delegations of Authority for Roger E. Snyder Manager, Pacific Northwest Site Office

## **Operations and Safety**

- Safety Basis functions (10 CFR 830 Subpart B 830.202 (b).(3) and App A F.3): For Pacific Northwest National Laboratory (PNNL), approve final hazard categorization for category 2 and 3 nuclear facilities.
- Safety Basis functions (10 CFR 830 Subpart B 830.203 (b), (c) and (e)): For PNNL
  hazard category 2 and 3 nuclear facilities: approve Unreviewed Safety Question (USQ)
  procedures and processes, changes determined to involve a USQ prior to
  implementation, and continued operations when a USQ is determined to exist.
- Safety Basis functions (10 CFR 830 Subpart B 830.202 (a) and (b) and Subpart B
   Appendix A E. 2; 830.205 (a).(2); 830.207 (b) and (d); and 830.206 (b).(1) and (2)):
   For PNNL hazard category 2 and 3 nuclear facilities approve the safety basis
   documentation.
- 4. Radiation Protection functions (10 CFR 835 Subpart B 835.101 (a) and (b)): Review and approve contractor Radiation Protection Program (RPP) for PNNL.
- Quality Assurance functions (10 CFR 830 Subpart A 830.121 (b).(1), (2), and (3); and DOE O 414.1D, 5.b.(6)(b)): Review and approve contractor Quality Assurance Program (QAP) for PNNL.
- Startup and Restart of Nuclear Facilities functions (DOE O 425.1D, 4.b.(3)): For PNNL, startup authorization authority for restart of facility, activity or operation that has upgraded its hazard categorization to hazard category 3.
- Startup and Restart of Nuclear Facilities functions (DOE O 425.1D, 4.b.(6)): For PNNL, startup authorization authority for the restart of a hazard category 2 nuclear facility, activity or operation following extended shutdown (>12 months).
- Startup and Restart of Nuclear Facilities functions (DOE O 425.1D, 4.b.(7)): For PNNL, startup authorization authority for the restart following shutdown because of substantial process, system or facility modifications of a hazard category 2 nuclear facility, activity or operation.
- Startup and Restart of Nuclear Facilities functions (DOE O 425.1D, 4.c.(4)): For PNNL, approve Startup Notification Reports if you are the startup authorization authority; otherwise, make recommendation regarding approval.

- ES&H Reporting functions (DOE O 231.2, 5.a.(1): Designation as Occurrence Reporting Program Manager for PNNL.
- 11. Nuclear Facility Safety functions (DOE O 420.1B, 5.b.(3)): Review and approve PNNL contractor implementation plans for nuclear safety design criteria.
- Conduct of Operations functions (DOE O 422.1, 5.a.(1)): Determine applicability of Conduct of Operations Order to PNNL facilities other than Hazard Category 1, 2, or 3 nuclear facilities.

## **Property Management**

1. Real Property functions (DOE O 430.1B Chg 2, 4.b.(1). and 5.e.(1).): Take all necessary action to acquire, by purchase, lease, or otherwise, real property interests; take necessary additional action following the initiation of condemnation proceedings and the execution of declarations of taking; and exercise all authority of the Secretary regarding the management and disposal of Departmental real property, excluding the acceptance by donation of real property. This authority does not extend to initiation of condemnation proceedings, executions of declarations of taking, or approval of indemnification provisions or clauses in contracts, subcontracts, leases, or other real property documents. In exercising this authority, all real property actions must be reviewed and approved by a DOE Certified Realty Specialist (CRS) prior to execution in accordance with requirements in DOE O 430.1B, Real Property Asset Management. This authority includes signature approval on real property documents for direct DOE transactions not involving DOE contractor or subcontractor execution. In the case of indirect transactions, certain real property transactions by DOE contractors must be conducted in accordance with the requirements of DEAR 917.74, Acquisition, Use and Disposal of Real Estate, and DEAR 952.217-70, Acquisition of Real Property; and property actions by recipients under DOE financial assistance agreements must satisfy the requirements of 10 CFR 600.132, Real Property, 600.231, Real Property, and 600.321, Real Property and Equipment.

Joseph A. McBrearty

Deputy Director for Field Operations

Office of Science