


Qty. _____

MATERIAL: _____

DRAWN: _____



E-MAIL: ALEX@3DIWELL.COM




Qty. / _____

MATERIAL: / _____

DRAWN: / _____



E-MAIL: ALEX@3DIWELL.COM




Qty. / _____

MATERIAL: / _____

DRAWN: / _____



E-MAIL: ALEX@3DIWELL.COM




Qty. _____

MATERIAL: _____

DRAWN: _____



E-MAIL: ALEX@3DIWELL.COM



Qty. /


MATERIAL: /

DRAWN: /




E-MAIL: ALEX@3DIWELL.COM

need to remove before install



DETAIL A
SCALE 1 : 1




Qty. / _____

MATERIAL: / _____

DRAWN: / _____



E-MAIL: ALEX@3DIWELL.COM



///--Additional components needed to buy--///	Qty
Pulley GT2 20T W6 B4 (18x8.5x12)	4
Flange Bearing F623zz (3x10x4)	4
Belt GT2 6mm (Length 1280mm+)	1
Brass Inserts M3 (D4.6 x L5.7)	32
Hex Socket Screw M3 x5mm	14
Hex Socket Screw M3 x10mm	12
Hex Socket Screw M3 x15mm	11
Hex Socket Screw M3 x16mm	2
Hex Socket Screw M3 x30mm	2
Shaft D2mm x L15mm	2
Shaft D3mm x L15mm	2
Shaft D4mm x L16mm	2
Shaft D4mm x L20mm	1
Shaft D4mm x L25mm	3
Cone Point Hex Socket Screw M3x8mm	2

Qty. / _____
 MATERIAL: / _____
 DRAWN: / _____
 **Edwell**
 E-MAIL: ALEX@3DIWELL.COM