


T = kel

T_s ↓ T_0, ⇐ I ↑ ⇐ winding resistance ⇐ thinner wire

↑ T_0 ⇐ I ↓ ⇐ winding resistance ⇐ thicker wire

T_0 ↓ N_s ⇐ K_e ↑ ⇐ B_{max} ↑ ⇐ magnet with ↑ K_e / airgap ↓

↑ N_s ⇐ K_e ↓ ⇐ B_{max} ↓ ⇐ magnet with ↓ K_e / airgap ↑