Factura NS 1366

CARPON CARPON

CAR FIX AND BEYOND

RFC: CFB190523NF1

No de serie del Certificado del CSD:0000100000700780081

Folio Fiscal: 886A2F37-30BC-5B82-971F-D9DC2FBE96B6

Regimen: 601 - General de Ley Personas Morales

Exportacion: 01

CONTRATO: 801094343

ECONOMICO: 98686

PLACAS: NJ4110B

KILOMETRAJE: 187073

DATOS DEL CLIENTE

EXPEDIDO EN

CFE DISTRIBUCION RFC:CDI160330RC9 Domicilio Fiscal:06600

C.P.58337

Fecha y hora de emisión:2024-06-12T14:10:53

Régimen::601 - General de Ley Personas Morales

Uso CFDI:G03 - Gastos en general

CANTIDAD	U. MEDIDA	DESCRIPCION	V. UNITARIO	% DESCUENTO	IMPORTE	OBJ. DE IMPUESTO
2.000000	H87 - Pieza	26101700 - REEMPLAZO DE TORNILLO ESTABILIZADORES	\$1,159.61	0	\$2,319.22	02
1.000000	H87 - Pieza	26101700 - CAMBIO DE BUJES DE BARRA ESTABILIZADORA (2)	\$723.80	0	\$723.80	02
2.000000	H87 - Pieza	25172001 - CAMBIO DE ROTULAS C/U	\$1,358.94	0	\$2,717.88	02
2.000000	H87 - Pieza	25173900 - CAMBIO DE TERMINAL DE DIRECCION C/U	\$1,362.86	0	\$2,725.72	02
2.000000	H87 - Pieza	25173900 - CAMBIO DE BIELETA C/U	\$1,067.26	0	\$2,134.52	02
2.000000	H87 - Pieza	25173900 - CAMBIO DE AMORTIGUADORES TRASEROS C/U	\$2,168.91	0	\$4,337.82	02
4.000000	H87 - Pieza	25172001 - CAMBIO DE BUJE DE HORQUILLA INFERIOR C/U	\$1,616.31	0	\$6,465.24	02
2.000000	H87 - Pieza	25172001 - CAMBIO DE HORQUILLA SUPERIOR C/U	\$3,866.17	0	\$7,732.34	02
2.000000	H87 - Pieza	25172001 - TORNILLOS ESTABILIZADORES TRASEROS	\$1,116.00	0	\$2,232.00	02

CANTIDAD CON LETRA: TREINTA Y SEIS MIL CUATROCIENTOS DIEZ PESOS 71/100 MXN - PESOS

MONEDA: MXN - PESOS | METODO DE PAGO: PPD - Pago en parcialidades o diferidos | FORMA PAGO: 99 - Por definir.

FECHA TIMBRADO: 2024-06-12T14:10:53

No. de Serie del Certificado del SAT: 0000100000707310321

Sello Digital del CFDi

DXuWslt6UnN8IWJ0CmY3wy5D7eu8iTuzyYit66A8u5K2kMnZDQj8sWRDU5svcy3ShCDkQxgg5E6wKu15lKymkZD9NKztCdg62OSl3E6WbBCHLO5EErO+0vMkUSbJ3VFoJ0e5U6CUZnAGTUPnzMULMm+k0+vmj
olkU5KQBcTejwYlwLBCSITF64YcHRF2WDH-ueP0rFJhBi5jj8v/80WyowA/Q3+4vxv562tu0w9uWGHaYgUlwy5ku58kR3AvuBkpZtAHtV4auevze6Mn958HRDznIDPFvGgyd4EWy8wYDwqC5AHiO38cG9NUWjOhzC
LAQHLl0MneFd7inF0o8XuQ==

Sello Digital del SA

kHIRmoB2ZboVbRlqC2M4oSyeX+QuYyOZf6bxx9cYvJw5QZ3aiFaTMMp3XihoBZjl1QYBwd6vnx679rvJ5AKo2axn241GUCIZhWUU8ss35gK+95cq9kQAVF0TwDtcjH43EwtVAgR/M29N9FosA4yxmEyfnAR803BnDJ
PeTkVETBL9wR2Pd4ukMYdjjLnBJFv7tSi+eHemWCtcpTcH7MymO2gmU45Lbx0mXPJ0YS3tGBnYCBqmh34us5qbjMEw9SEMBLRjxdxm8cwjMPB8+ukAvqeGid5QqtyoYN1TJo+YSAG4mdNF6CwzmTCEXcHaag
x3l na2663xC4+wwx0X168BO==

Cadena Original del complemento de certificación digital del SAT

||4.0|NS|1366||2024-06-12713:10.49||99||00001000000700780081|CONDICIONES|31388.54|0|MXN|36410.71|||01||PPD|58337||CFB190523NF1||CAR FIX AND BEYOND|601||CD1160330RC9||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||CFED||

ESTABILIZADORES|1159.61|2319.22|0|02|2319.22|002|Tasa|0.160000|371.0752|26101700|1368|1.000000||H87|Pieza|CAMBIO DE BUJES DE BARRA ESTABILIZADORA

(2)|723.80|723.80|002|723.80|002|Tasa|0.160000|115.808|25172001|1329|2.000000|H87|Pieza|CAMBIO DE ROTULAS

 $C/U|1358.94|2717.88|0|02|2717.88|002|Tasa|0.160000|434.8608|25173900|1332|2.000000|H87|Pieza|CAMBIO\ DE\ TERMINAL\ DE\ DIRECCION$

 $C/U|1362.86|2725.72|0|02|2725.72|002|Tasa|0.160000|436.1152|25173900|1333|2.000000|H87|Pieza|CAMBIO\ DE\ BIELETA$

Subtotal:	\$31,388.54		
IVA (16%):	\$5,022.17		
Total:	\$36,410.71		

C/U|1067.26|2134.52|0|02|2134.52|002|Tasa|0.160000|341.5232|25173900|1338|2.000000|H87|Pieza|CAMBIO DE AMORTIGUADORES TRASEROS
C/U|2168.91|4337.82|0|02|4337.82|002|Tasa|0.160000|694.0512|25172001|1330|4.00000|H87|Pieza|CAMBIO DE BUJE DE HORQUILLA INFERIOR
C/U|1616.31|6465.24|0|02|6465.24|002|Tasa|0.160000|1034.4384|25172001|1328|2.000000|H87|Pieza|CAMBIO DE HORQUILLA SUPERIOR
C/U|3866.17|7732.34|0|02|7732.34|002|Tasa|0.160000|1237.1744|25172001|10353|2.000000|H87|Pieza|TORNILLOS ESTABILIZADORES
TRASEROS|1116.00|2232.00|0|02|2232.00|002|Tasa|0.160000|357.12|31388.54|002|Tasa|0.160000|5022.17|5022.17||

