Factura T 2017

DIAGNOSTICO Y REPARACION

MARIANO AVALOS VICTORIA

RFC: AAVM800825NK8 Tipo de comprobante : I - Ingreso

No de serie del Certificado del CSD: 0000100000503454131 Folio Fiscal: CE86310C-14D6-4DB4-992C-A888821AB5F8

Régimen: 612 - Personas Físicas con Actividades Empresariales y Profesionales

DATOS DEL CLIENTE EXPEDIDO EN

CAR FIX AND BEYOND CP:59665

RFC: CFB190523NF1 Fecha y hora de emisión: 2023-04-26T16:02:38

PURGAR SISTEMA

Uso CFDi: G03 - Gastos en general Domicilio: 58337 Régimen: 626 - Régimen Simplificado de Confianza

CantidadU MedidaDescripciónV UnitarioImpuestosImporte1E48 - M.O.78181500 - REPARAR MANGUERA DE FRENOS TRASERA, LIQUIDO PARA FRENOS, CAMBIAR MANGUERA Y1,163.8002 Sí objeto de impuesto1,163.80

Condiciones de Pago: CHEVROLET HD 3500

NJ-4118-B ECO: 105071

> SubTotal \$ 1,163.80 +IVA 16% \$ 186.21 =TOTAL \$ 1,350.01

CANTIDAD CON LETRA: MIL TRESCIENTOS CINCUENTA PESOS 01/100 MXN

MONEDA: MXN - Peso Mexicano | METODO PAGO: PPD - Pago en parcialidades o diferido | FORMA PAGO: 99 - Por definir

FECHA TIMBRADO: 2023-04-26T16:04:39

No de Serie del Certificado del SAT : 00001000000504204971

Sello Digital del CFDi

i1TCUsCThFPYq1LJqCnJsW9v0hTlijOWJk+V6UwNn5wLD2kYweltdf8LC/9+KrDlKholqGra2Rq4HUGNHLbj71S5RrNwkNl18BrBUo2G+6QX7MaFfW/nn/OKY9ikWfFGkrx1ovc9LVtdqc/4yNdOeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4po1bzXNa69bcZ3HPL87Ad7R+bmowsyw/n4SJnMcryJS1DcnUUZIPm8UomiP2Pgu/z1kVi7AqsPyktdTTwLncbiQidCug9+8HgWQrO49y1tBM+i3ig07BHU605D91Qb6rn1+9NZMvlLCUMag0xeoNXxz3j95KFA==

Sello Digital del SAT

 $XHVtlAwS4lX/X1wGldut0DdJEbrzhA1EfxJjQWhK7gaqFf+9TLfH+bKqFlCoz5Ozqqv24YJyn5OfMrDN/SsFldgP1laV8lY+lwSSpTYXi8Mc\\ 4uXlxQuftA70G1sU1fTi9WSHythsSyh673lOYrDbxt+5EVAq6COerx0dRw9PdEREfD0XhBKawwZFXNxpv1ZjMh26Y90R72ScOMowukH\\ 6UGqY6GbVwQby6u4WUbONZQXYEMnull5AyG6pz7ldmgAQg1402jQAAPDUELm2D/URWFyQoONVblkPOLcnBHji/P/NDJpjJzHevon RiUssrdkCxXRjTGthT09/avKxJdimVg==$

Cadena Original del complemento de certificación digital del SAT

||1.1|CE86310C-14D6-4DB4-992C-A888821AB5F8|2023-04-

26T16:04:39|PPD101129EA3|i1TCUsCThFPYq1LJqCnJsW9v0hTlijOWJk+V6UwNn5wLD2kYweltdf8LC/9+KrDlKholqGra2Rq4HUGNHLbj71S5RrNwkNl18BrBUo2G+6QX7MaFfW/nn/OKY9ikWfFGkrx1ovc9LVtdqc/4yNdOeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv422vbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv42VbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv42VbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv42VbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv42VbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv42VbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv42VbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv42VbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv42VbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv42VbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv42VbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv42VbVNk3/WoB72lBPn02scahOn5EGg4polydcyfyndoeSDv42VbVNc4VbVN

1bzXNa69bcZ3HPL87Ad7R+bmowsyw/n4SJnMcryJS1DcnUUZIPm8UomiP2Pgu/z1kVi7AqsPyktdTTwLncbiQidCug9+8HgWQrO49y1tBM+i3ig07BHU605D91Qb6rn1+9NZMvILCUMag0xeoNXxz3j95KFA==|0001000000504204971||



