Factura T 1973



MARIANO AVALOS VICTORIA

RFC: AAVM800825NK8 Tipo de comprobante : I - Ingreso

No de serie del Certificado del CSD: 00001000000503454131 Folio Fiscal: AA5985FC-6362-4299-BBC7-A80393DEB15C

Régimen: 612 - Personas Físicas con Actividades Empresariales y Profesionales

DATOS DEL CLIENTE

EXPEDIDO EN

CAR FIX AND BEYOND

CP:59665

RFC: CFB190523NF1

1

Fecha y hora de emisión: 2023-03-24T19:03:10

3,782.76

Uso CFDi: G03 - Gastos en general Domicilio: 58337 Régimen: 626 - Régimen Simplificado de Confianza

E48 - M.O.

U Medida Cantidad Descripción V Unitario Impuestos Importe

> 78181500 - CONECTOR PARA BOBINA, 2 SOPORTES DE MOTOR, SOLDAR MULTIPLE DE ESCAPE. CORREGIR FALLA DE MOTOR DE CILINDROS, CAMBIAR CONECTOR DE BOBINA Y CAMBIAR SOPORTES DE MOTOR

02 Sí objeto de impuesto 002 - IVA: 605.24 3,782.76

Condiciones de Pago: F-250

ND-6275-B ECO: 75481 KM. 309,405 SERIE: 5MA07909

> SubTotal \$ 3,782.76 +IVA 16% \$ 605.24 =TOTAL \$ 4,388.00

CANTIDAD CON LETRA: CUATRO MIL TRESCIENTOS OCHENTA Y OCHO PESOS 00/100 MXN

MONEDA: MXN - Peso Mexicano | METODO PAGO: PPD - Pago en parcialidades o diferido | FORMA PAGO: 99 - Por definir

FECHA TIMBRADO: 2023-03-24T19:04:38

No de Serie del Certificado del SAT : 00001000000504204971

Sello Digital del CFDi

MLLjeLTV8lq6SM9eNwh5pitFj87Rd19OwDENoypDYqhNb1zJJ/CJKBAlYt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJl76vlthB1B4zUJ9FBsHTRgMQFZawUVt4DalVt6jJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuHgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyPbeZuhgJUyP3wDDomhkYL/w5DU/4DryDIRIOFJmDSHjqlneexDVu3cBNpa1F6p6eSv3vv1xyKQxecfEjMUmoyuxehfnaW0FuIWBMi6nTVTCTSweJBYfjtBMGnA0UJuFCmdXA9Vf+5Fp4g==

Sello Digital del SAT

y+aKBDY5pllaUEZKZRYRQC6PHJlmw0/UvnC0XKluMJYaSVklZbGEEj2tleEMPr0yoVTDnjexkpuURJTfzVpj02JmUjrCXAaOPns+c2Ho Ji7jLGqFdulZ7YoPlc/5/S14VX8YA==

Cadena Original del complemento de certificación digital del SAT

||1.1|AA5985FC-6362-4299-BBC7-A80393DEB15C|2023-03-

24T19:04:38|PPD101129EA3|aSZxxhfJYT+nM2ym1FZsiFidJb/dhA0EC9anrxfEsz3C/xBW4+JQydl5LPd/XUVeXjiZPt16z0EMQRZDN4URz I1z Zmigj4m4SiHKyzYAXq6MLLjeLTV8lq6SM9eNwh5pitFj87Rd19OwDENoypDYqhNb1zJJ/CJKBAIYt6jJUyPbeZuHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zUHgJI76VthB1B4zU



J9FBsHTRgMQFZawUVt4Da3wDDomhkYL/w5DU/4DryDlRIOFJmDSHjqlneexDVu3cBNpa1F6p6eSv3vv1xyKQxecfEjMUmoyuxehfnaW0FuIWBMi6nTVTCTSweJBYfjtBMGnA0UJuFCmdXA9Vf+5Fp4g==|0000 1000000504204971||

