## DIAGNÓSTICO TÉCNICO



Numbre: CF	E DESTREBULEON	2 9. 102 12	2 3FT 6F 17 W66 MA 16 156
	Marca/Modelo: FORD Pick UP		Places: 4829M 80270 229766

Nombre del Técnico.

FALLAS REPORTADAS:

REUPSPON DE CLUCH VEIOCPDADES NO ENTEAN

REN/RA-			MANO DE	SUBCONTRA
Z I REPARAR	DESCRIPCIÓN	PARTES S	DBRAS	TADO S
1 1	BOMBA COLLAREN DE CLUCH	1378"		
2 1	L'auso FRENOS	76"		
3 440	L'EQUIDO FRENDS ALEITE TRANSMICION	440"	- "	
4 1	MANO DE OBRA		1350"	
5			3244°	
6		IVA	3763	04
7			3763.	04
8				
9	Company to the Control of the Contro			
10				
11				
12				
13				
14				
15				
16				
17		_		
8				
19				
10				
1				
2				
3				
4				
15				
6				
7				
8				
9				
0				

Insp	Acionado por:
/	14
4	die .
	/
20	Firma:

Supervisado por

Luis

Firma: