SYNTHETIC DEMO DATA - FICTIONAL DOCUMENT, NOT REAL

Post-Repair Leak Test Report
Equipment: P-101
Leak test result: PASS. Test pressure: 6.0 bar (fictional value).
Vibration reading after repair: 2.1 mm/s (fictional value).