## Karman vortex flow meter KSL-5/10/30/50LN

- Low-cost with no display
- Which involves no moving parts.
- Highly durable and maintenance-free
- Compatible with high-temperature water
- Flow meter for measuring the fluid flow rate and temperature
- Alarm output
- LCD display



\*Descriptions are based on Japanese Industrial Standards (JIS).

	Specif	ications								
Model	KSL-5LN	KSL-10LN	KSL-30LN	KSL-50LN						
Flow range	0.5-5 L/min	1.5-10 L/min	5-30 L/min	7-50 L/min						
Fluid	d Industrial water or service water									
Temperature detection range	0-100°C									
Maximum working pressure	1.0 MPa									
Flow temperature	0-90°C (No freezing)									
Ambient temperature	0-40 °C									
Power supply	DC 12V ± 5% or DC 24V ± 10%									
Current consumption	n 30 mA max. (70mA max. in 4 to 20mA specification)									
Cable	AWM20276 9 core / 0.2 mm? / 500 mm									
	red	Power supply								
	black Ground									
	white Flow rate output									
	orange Temperature - detection output									
	yellow Flow rate alarm									
	green Temperature - detection alarm									
	gray Flow rate output (Pulse output)									
	blue	COM (Return of alarm output )								
	brown									
Output	DC0-10V or 4-20mA (Flow rate , temperature) / Pulse (Flow rate)									
Alarm output	MOS FET ON or OFF (Flow rate , temperature)									
O ring	Fluoro rubber									
Material of body	PPS,SUS304									
Materials of detector	PPS (Flow rate detector: PPS, temperature detector: SUS304									
Adapter size	e Rc3/8" or Rc1/2"									
Adapter material	SUS304 or BsBM+Ni plating									
Accuracy	FS ±2.0%									
Flow direction	Specified direction									

## Order form

How to order. KSL - 5LN - 24V - V- A - B - S - 3/8- COM

	Flow range		Power Supply		Analog Output		Alarm Output1 Flow rate		Alarm Output2 Temperature		Adapter Material		Adapte Size	2 1 5 5 5 5 5 5	Return of alarm output		
		0.5-5 L/min	NAME OF	DC12	v		e autput -10V		33	Alarm on	A	Alarm on over set value	s	SUS 304	3/8	сом	Do not ground
	10LN	A		±5%	1	Current DC4-2				over set value							
	30LN	Comme		- 197	<b>P</b> *1	Pulse output	٧	DC 0-10V	В	Alarm off over set value	В	Alarm off over set value	В	BsBM * Ni platrig	1/2	100	Connect to ground
	50LN	7-50 L/min	24V		DPM	Connect to DPM	1	DC 4-20mA								G	

<sup>\*1 5</sup>L,30L type only selectable [P](Pulse output).