

HUMAN PERFORMANCE PRE-JOB BRIEFING



DATE & TIME	07.01.2026/8:00Am	SHIFT	G
Task Leader	Mazid	SA ID	100438
Printed RA/SOP No./Title	RA sprocket replacement		
HIGHEST RISK TASK OF THE DAY (Describe what you will do today):	Layer conveyor sprocket replacement		
LOCATION	L2		

ERROR TRAPS VS HUMAN PERFORMANCE TOOLS

DISCUSS ALL AND CHOOSE MINIMUM OF TWO ERROR TRAPS AND THEIR CORRESPONDING HUMAN PERFORMANCE TOOLS
(FOR EACH ERROR TRAPS, IT COULD BE MORE THAN ONE HUMAN PERFORMANCE TOOLS)

ERROR TRAPS	HUMAN PERFORMANCE TOOLS
Time Pressure ☒	☒ STAR (Stop-Think-Act-Review)
Destruction/interruption/Organization Conflict ☐	☒ Three-Way Communication
Fatigue / Low Alertness ☐	☐ Self-Check
Overconfidence / Complacency ☐	☒ Stop-Work Authority/ Stop When Unsure
Poor Communication ☒	☐ Task Preview / Pre-Job Briefs
Lack of Knowledge/Experience /Training ☐	☐ Peer Check (Second Check)
Unclear or Missing Procedures ☐	☐ Use written procedure
Unverified Assumptions ☐	☐ Post-Job Review / Lessons Learned Questioning Attitude (Continuously asking "What could go wrong?")
Stress / Pressure from Others ☐	☐ Effective Handover / Briefings
Unclear Responsibility ☐	☐ Place-Keeping Tools
Adverse Environment Condition ☐	☐ Independent Verification
High workload / Multi-tasking ☒	☐ Time out/Pause for Safety
Unexpected Condition/Equipment Multi-function Condition ☐	☒ High Work Load Redistribution
Confusing Control/Display ☐	☐ Task Participation and Planning
Inaccurate Risk Perception ☐	
Emotional Reaction ☐	

PLEASE CHOOSE ONE ERROR / PERFORMANCE MODE

(Please tick the box near the selected performance mode)

☐ **LACK OF KNOWLEDGE-BASED ERRORS**
Occur when a person faces a situation that is unfamiliar, and they don't have enough knowledge or experience to respond correctly.

☐ **PROCEDURE-BASED ERRORS**
Happen when a person applies a rule or procedure incorrectly, or uses the wrong procedure for the situation.

☒ **ROUTINE-BASED ERRORS**
Occur during familiar, well-practiced tasks that are performed almost automatically – often without much conscious thought.

HUMAN PERFORMANCE PRE-JOB BRIEFING



CRITICAL STEPS	RISKS
* Power isolation	Elec Shock
* Remove master link for chain	Hand injury
* Lifting sprocket	Falling objects
* Dismantle shaft sprocket	Body injury

STOP & SEEK OUT CRITERIA	VERIFIED AT FIELD
* Multiple tasks: No one should work on layer conveyor while lifting layer sprocket.	- Everyone keeps 3 or more meters distance.

EVERYBODY HAS THE RIGHT AND OBLIGATION TO STOP THE WORK WHEN UNSAFE

STOP WHEN UNSURE

☐ I ACKNOWLEDGE THAT I WILL STOP WORK IF IT IS UNSAFE AND I WILL REPORT ANY ABNORMALITY TO MY SUPERVISOR

TEAM MEMBER	NAME	SA ID	SIGNATURE
	Mazid	100248	
	Gayth	101754	
	Mamish	101292	
	Samal	100818	
	Adip	100457	
	Fahad	100449	
	K. Bale	101098	
	Dharma	100978	

WHAT IS THE WORST THING THAT COULD HAPPEN DURING THE EXECUTION OF THE TASK?

Sprocket Fall on Someone

LESSONS LEARNED

Always maintain 3 meter distance.

POST WORK OBSERVATION

DOES THE SOP/RISK ASSESSMENT ADEQUATELY COVER THE TASK REQUIREMENTS

☒ YES ☐ NO IF NO, TALK TO YOUR LEADER TO UPDATE SOP/RA

HAS THE TASK BEEN STOPPED AS A RESULT OF STOP CRITERIA?

☐ YES ☒ NO IF YES, THEN WHAT WAS THE STOP CRITERIA