

HUMAN PERFORMANCE PRE-JOB BRIEFING



DATE & TIME	11.01.2025 20:00	SHIFT	D
Task Leader	Mohammed Dhahe	SA ID	100668
Printed RA/SOP No./Title	CH-OPS- SOP-180	Signature	<i>[Signature]</i>
HIGHEST RISK TASK OF THE DAY (Describe what you will do today):	Metal crucible cleaning.		
LOCATION	Crucible shop area.		


ERROR TRAPS VS HUMAN PERFORMANCE TOOLS

DISCUSS ALL AND CHOOSE MINIMUM OF TWO ERROR TRAPS AND THEIR CORRESPONDING HUMAN PERFORMANCE TOOLS
(FOR EACH ERROR TRAPS, IT COULD BE MORE THAN ONE HUMAN PERFORMANCE TOOLS)

ERROR TRAPS		HUMAN PERFORMANCE TOOLS	
Time Pressure	☐	☐ STAR (Stop-Think-Act-Review)	
Destruction/interruption/Organization Conflict	☐	☐ Three -Way Communication	
Fatigue / Low Alertness	☐	☐ Self-Check	
Overconfidence / Complacency	☐	☐ Stop-Work Authority/ Stop When Unsure	
Poor Communication	☒	☐ Task Preview / Pre-Job Briefs	
Lack of Knowledge/Experience /Training	☐	☐ Peer Check (Second Check)	
Unclear or Missing Procedures	☐	☐ Use written procedure	
Unverified Assumptions	☐	☐ Post-Job Review / Lessons Learned Questioning Attitude (Continuously asking "What could go wrong?")	
Stress / Pressure from Others	☐	☒ Effective Handover / Briefings	
Unclear Responsibility	☐	☐ Place-Keeping Tools	
Adverse Environment Condition	☒	☐ Independent Verification	
High workload / Multi-tasking	☐	☐ Time out/Pause for Safety	
Unexpected Condition/Equipment Multi-function Condition	☐	☐ High Work Load Redistribution	
Confusing Control/Display	☐	☒ Task Participation and Planning	
Inaccurate Risk Perception	☐		
Emotional Reaction	☐		

PLEASE CHOOSE ONE ERROR / PERFORMANCE MODE

(Please tick the box near the selected performance mode)



HUMAN PERFORMANCE PRE-JOB BRIEFING



CRITICAL STEPS	RISKS
Crane inspection letting the crucible from the stand Placing the crucible on the table Start the cleaning.	Slip and tripping hazard Suspended load. splashes
STOP & SEEK OUT CRITERIA	VERIFIED AT FIELD
Abnormality in the crane movement Crane wire rope damages. The crucible looks damages. if the crucible not fully empty contain liquid metal. if the ccm bin water contain water in.	stop- all FR to check. stop call Supervisor. stop- call the SVP to verify. use the correct way to solve the issue. don't use place the another one.

EVERYBODY HAS THE RIGHT AND OBLIGATION
TO STOP THE WORK WHEN UNSAFE

**STOP
WHEN
UNSURE**

☐ I ACKNOWLEDGE THAT I WILL STOP WORK
IF IT IS UNSAFE AND I WILL REPORT ANY
ABNORMALITY TO MY SUPERVISOR

TEAM MEMBER	NAME	Salim Barloshi	SA ID	101011	SIGNATURE	<i>[Signature]</i>
	NAME	Nabham Sahwari	SA ID	100568	SIGNATURE	<i>[Signature]</i>
	NAME	Abdullah Al-Rees	SA ID	100430	SIGNATURE	<i>[Signature]</i>
	NAME	Khafan Al-Kindi	SA ID	100842	SIGNATURE	<i>[Signature]</i>
	NAME	Maktoom Al-Zeed	SA ID	100938	SIGNATURE	<i>[Signature]</i>
	NAME	Ahmed Al-Dhahr	SA ID	101306	SIGNATURE	<i>[Signature]</i>
	NAME	Faiz Al-Baloshi	SA ID	100742	SIGNATURE	<i>[Signature]</i>

WHAT IS THE WORST THING THAT COULD HAPPEN DURING THE EXECUTION OF THE TASK?

*Explosion if the ccm bin contain water in.

LESSONS LEARNED

"Ensure all the time sop is followed"

POST WORK OBSERVATION

DOES THE SOP/RISK ASSESSMENT ADEQUATELY COVER THE TASK REQUIREMENTS

☒ YES ☐ NO IF NO, TALK TO YOUR LEADER TO UPDATE SOP/RA

HAS THE TASK BEEN STOPPED AS A RESULT OF STOP CRITERIA?

☐ YES ☒ NO IF YES, THEN WHAT WAS THE STOP CRITERIA