

Status on HALON contamination

Rémi DELETAIN
Certification Directorate
Powerplant Installation & Fuel
System Expert



Contents of the presentation

- Contaminated halon
 - **X** Status
 - **★ ICAO state letter**



- Background
 - ★ UK based company delivered polluted Halon (H1211 / H1301)
 - **▼ 17 Customers identified**
 - **★ EASA / CAA UK approach individually each company involved in Aviation either as PartM / Part145**
 - ★ Wide variety of applications: handheld, enigne, APU, cargo for General aviation, Helicopters & Large airplanes



- EASA global approach for Halon 1211
 - Identification of the suspected batches
 - **★** Test of the suspected batches
 - **★** According to the results (purity <90%) issuance of AD with defined applicability (P/N, S/N)
 - ➤ For all batches with 90%<purity <99%
 FAA-TC Tests done with different levels of contaminants to determine compliance time for future ADs



- As of today, EASA has issued 7 ADs covering:
 - ★ Portable extinguishers FFE Total number of FE: around 5000
 - ➤ Portable extinguishers Sicli H1-10 AIR (formerly General Incendie MAIP)
 - **Total number of FE: around 1400 FE**
 - **★ L'hotellier**Total number of FE: around 1800 for ATR,

 Eurocopter and Socata)
- Most of batches have now been tested. ADs were issued where no test results available
- New set of ADs might be issued to cover lower levels of purity depending on test results



- Halon 1211 is used also on engine fire extinguishing
 - ➤ Fixed extinguishers L'H

 Total number of FE: around 120
- Risk under EASA assesment for Dassault
- Correctives actions in place for Eurocopter



- Level of risk is still under assessment taking into account:
 - Less toxicity impact for engines and APU
 - ➤ Purity % vs Fire suppression capability o be assessed on a case-by-case basis
 - **★ Compliance with applicable engine fire suppression specifications**
 - **★** Decision on way forward to be taken





References

| AD | Title | Releas. date | Effectiv. date | Comp. | Remark |
|----------------------|---|-----------------|-------------------|-------------------|---|
| EASA 2009-0251-E | FFE H1211 - Handheld | 25.11.0 9 | 26.11.09 | 2d | 483 units |
| EASA 2009-0262 | FFE H1211 - Handheld- | 23.12.09 | 29.12.09 | 30d | FFE ASB-26-115 2317 units |
| EASA 2009-0262 R1 | FFE H1211 - Handheld | 27.01.1 0 | 10.02.10 | 30d from origin | SB ASB-26-115 Revision C for S/N list – 1 more S/N |
| EASA 2009-0278 | SICLI H1211 - Handheld | 22.12.0 9 | 05.01.10 | 30d | 1422 units |
| EASA 2009-0276 | ATR – H1211 – Handheld – L'Hotellier | 23.12.09 | 06.01.10 | 36d | SB 83521-26-001 orign issue 21.12.09 1582 units (L'Hotellier total) |
| EASA 2009-0276 R1 | ATR – H1211 – Handheld – L'Hotellier | 05.02.10 | 05.02.10 | 4m from origin | SB 83521-26-001 revision 1, 28.01.10 |





References

| AD | Title | Releas. date | Effectiv. date | Comp. | Remark |
|----------------------|---|-----------------|-------------------|--|---|
| EASA 2009-0277 | ECF- H1211 - Handheld - L'Hotellier | 23.12.09 | 06.01.10 | 36d | SB 83520-26-001 orign issue 21.12.09 1582 units (L'Hotellier total) |
| EASA 2009-0277 R1 | ECF- H1211 - Handheld - L'Hotellier | 05.02.10 | 05.02.10 | 6m from origin | SB 83520-26-001 |
| EASA 2010-0012 | SOCATA- H1211 - Handheld - L'Hotellier | 05.02.10 | 12.02.10 | 3m | SB 83520-26-001, dated 21.12.09 SB 70-183(26), jan 2010 1582 units (L'Hotellier total) |
| EASA 2010-0061 | ATR - H1211 Handheld - L'hotellier | 31.03.10 | 14.04.10 | 4m from origin 4m (for new S/N) | Supersedes EASA 2009-0276 R1 with same applicability + S/N QL71732 to QL71770 |
| EASA 2010-062 | FFE H1211 – Handheld- | 31.03.10 | 14.04.10 | 4m | SB 26-116 |



References

- Airworthiness Communication from CAA-UK
 - ***AIRCOM 2009/13, dated 12 Oct 2009**
- Flight Ops Communication from CAA-UK
 - **★ FODCOM 30/2009, dated 12 Oct 2009**
- Safety Information Bulletin from EASA
 - **★ SIB 2009-39, dated 23 oct 2009**



European Aviation Safety Agency

Contaminated Halon/ICAO state letter

- ICAO state letter was released on 12th of January 2010
- This letter does not formally require answer
- It requires Member States « to assess halon fire extinguishing supplies and take action as appropriate »
- Based on this letter, the strategy chosen by the Agency in cooperation with the EC is the following:



European Aviation Safety Agency

Contaminated Halon/ICAO state letter / EASA position

- As a short term action
 - ★ The Agency has already issued an SIB to raise awareness of Air operators, AMOs, aviation suppliers and manufacturers. The SIB will be up-dated.
- As a mid/long term action
 - ★ Based on the recent events of falsified documents, reliance on documentation to ensure quality of halon is not enough



European Aviation Safety Agency

Contaminated Halon/ICAO state letter

- ★ The key for quality can only be to determine the adequate test methods
- ★ The Agency plans to draft AMC applicable to Production Organisations and Maintenance organisations for guidance on how to perform the quality inspection of halon at incoming inspection
- The answer to the State letter is under drafting at the Agency/EC and will be released by the European Commission.



Thank you