

Rolling Mill Maintenance Manual

System Description:

The rolling mill reduces slab thickness and improves product quality.

Key Components:

- Work Rolls
- Backup Rolls
- Gearbox
- Drive Motors
- Hydraulic System

Inspection Activities:

- Check roll wear.
- Verify gearbox oil level.
- Measure motor temperature.
- Inspect hydraulic pressure.

Alarm Conditions:

Motor Temperature > 85°C

Gearbox Vibration > 6 mm/s

Hydraulic Pressure < 120 bar

Recommended Actions:

Replace damaged rolls. Inspect bearings. Verify lubrication system.