天气预报 Weather Forecast						发布周期:2018-03-23至2018-03-25	
日期 Date	昼夜 Day/Night	温度 Temperature		天气现象 Weather	风向 Wind Direction	风力 Wind Power	
						沿海及内陆 Coastal and Inland	海面 At Sea
2018-03-23	白天	高温	16℃				
星期五	Day	High temperature	100	晴转阵雨	南风	3-4级	5~6级阵风8级
Friday	夜间	低温	6°C	clear to shower	south wind	wind grade 3-4	wind grade 5-6 gust 8
	Night	Low temperature	00				
2018-03-24	白天	高温	12℃				
星期六	Day	High temperature		阵雨转多云	南风	3-4级	5~6级
Saturday	夜间	低温	5℃	shower to cloudy	south wind	wind grade 3-4	wind grade 5-6
	Night	Low temperature					
2018-03-25	白天	高温	15℃				
星期天	Day	High temperature	15 C	多云转晴	南风	3-4级	5~6级阵风7级
Sunday	夜间	低温		cloudy to clear	south wind	wind grade 3-4	wind grade 5-6 gust 7
	Night	Low temperature	6℃				

为降低对公司的影响范围和程度,请各部门做好以下工作:

Please do the following job in order to reduce damage:

1.各吊机使用部门做好露天吊机的锚固定,当风力达到六级以上或停工下班后,必须将吊机锚固定在防风位置,锁上夹轨器;

Department that use crane in open air should make anchorage reinforcement during strong wind period, anchor in position and put on track lock when wind is over grade 6 or above when finish work;

2.设备部根据600吨吊技术安全要求做好600吨吊的防风工作;

Hoisting Transportation Department to prepare windproof job in accordance with technical safety requirement of 600 tons crane;

3.大雨来临前请各项目做好防积水、防触电、防溢油等安全措施,如舱口加盖防雨棚、露天存放油桶加盖、露天用电设备加防雨淋措施等。并备好潜水泵、水带、砂包等防汛物资;

All projects please make good preparation and anti-water, anti-electric shock, anti-oil spills measures etc. before the rain, for example: put on anti-canopy an on hatch, put on cover onto oil barrel in open air, put on anti-rain measures on electrical equipment in open etc as well as prepare flood prevention materials such as submersible motor pump, hose, sand bag etc.

4.请生产管理部与HSE部做好各登船梯口和危险部位的防摔倒措施.

Production Department and HSE department prepare anti-skid measures on boarding stairs and other dangerous areas;

5.大风、雷雨期间暂停一切室外作业,并做好防护工作,以策安全;

Stop all outdoor operations during period of strong wind and make good preparation for safety reason;

6.其他部门也请根据各自情况做好异常天气期间的防风、防雨、防汛工作;

Other departments should do relevant wind proof job, rain proof and flood job according to their own situations during abnormal period;

7.各相关部门留厂值班的三防人员要坚守岗位,发现异常情况要及时处理和报告。

Three-national defense people on duty of all relevant departments should keep to their posts; any abnormal situation should be processed and reported in time.

HSE