
wMutexWait
wTaskSched
wTaskSwitch
wHooksTaskSwitch
wTaskHighestReady
wBitmapGetFirstSet
wBitmapPosCount
wListFirst
wTaskEnterCritical
wTaskExitCritical
wEventWait
wListAddLast
wTimeTaskWait
wTaskSchedUnRdy
wListCount
wBitmapClear
wListRemove
wTaskSchedRdy
wListAddFirst
wBitmapSet