1-网格分辨率:

2-the tolerance in the linear solver: so the determining factor is just how well

the equations are solved on the mesh. To vary the tolerance for the linear solve, change the parameter linearTolerance.

3-the tolerance for the non-linear:

4-the number of particles