Hikrobot Flat-Field Correction Tool

User Manual

Contents

Chapter 1 Revision History 1
Chapter 2 Correction Operations 2
Chapter 3 Get Support 6

Chapter 1 Revision History

Version	Release Date	Changes
V4.2.0	25th June 2023	Provide reference for operating the flat-field correction tool.

Chapter 2 Correction Operations

The flat field correction tool (hereinafter referred to as "Tool") can get the images before and after the FPN/PRNU calibration, and display the grayscale line of the image before and after the calibration.

Before You Start

Connect the camera and start acquisition.

Steps

1. Get prepared by following the instruction below **Preparation for FPN Calibration**.
2. Click **Acquire Dark Image** to get the image before starting the FPN calibration.
   The grayscale graph of the image is displayed on the left side of the tool, and the execution result and time are displayed under the graph.



Figure 2-1 Acquire Dark Image

3. Go back to the MVS and configure parameters of FPN Calibration.
4. Click **Perform FPN Calibration** to get an image.
   The grayscale graph of the image is displayed on the left side of the tool, and the execution result and time are displayed under the graph.



Figure 2-2 Perform FPN Calibration

5. Get prepared by following the instruction below **Preparation for PRNU Calibration**.
6. Click **Acquire Bright Image** to get the image before starting the PRNU calibration. The grayscale graph of the image is displayed on the left side of the tool, and the execution result and time are displayed under the graph.



Figure 2-3 Acquire Bright Image

7. Go back to the MVS and configure parameters of PRNU Calibration.
8. Click **Perform PRNU Calibration** to get an image.
   The grayscale graph of the image is displayed on the left side of the tool, and the execution result and time are displayed under the graph.



Figure 2-4 Perform PRNU Calibration

Chapter 3 Get Support

You can get support from us in the following ways:

- **Official Website**: visit *https://en.hikrobotics.com/* to get other related documents.
- **Email**: global.support@hikrobotics.com.

Symbol Conventions

The symbols that may be found in this document are defined as follows.

Symbol	Description
Danger	Indicates a hazardous situation which, if not avoided, will or could result in death or serious injury.
Caution	Indicates a potentially hazardous situation which, if not avoided, could result in equipment damage, data loss, performance degradation, or unexpected results.
Note	Provides additional information to emphasize or supplement important points of the main text.