


HEAD faceting remains above the hard gate



Curvature refinement cannot satisfy both targets

