

EMPLOYEE STEP UP CARD

	1	A	e	Signature of Qualifier	Signa			Signature of Trainee	
1 20 4 5	3-	1 20 4 5	3	1 2 04 5	3-	u	Can show and execute the OOL handling process with reference to both Q-Parameters and non- critical parameter		
18345		18345	71	10345		2	Can explain the levels of review of Process Audit sheets		_
12045	- (12045	i e	1 20 4 5	-1	u	Can execute process audit with reference to the time-limit defined		
1 2004 5	(-	12015	11.	12045	(—	J	S Can record appropriate process parameters on the Process audit sheet and Q-Window	FHC PSG OA SOP-PROCESS AUDIT SYSTEM	_
12045	•	12045		1 2 04 5		u	Can define and identify the critical and non-critical parameters		
16345	-2	18345	23	100345	23	2	Can explain the purpose of the Process Audit SOP, his responsibility and executes appropriately		
10345	3	18345		10345		2	Has passed the written qualification of the Process Audit SOP		
Evaluation	Date	Evaluation	Date		Date	Profic.			
Final Evaluation	Final E	First Evaluation	First E	Self Evaluation	Self Ev	Target	Knowledge/Skill	SKIII Block	U/N
								7 :: 7	200

Date of Qualification