

PDF

GTKWa e

N 1410 ns0140

PDFread_eightsatri _ multiplacti ate s nchronise

8826 nsDUTPDF

RTL9fffb67b8b344d9269766f9ee6f4750be714841

0 08 / 0 20 / 0 80 / 0 FF A[i,j] i+2j+1 W21

2 118 NO_ACTIVATION[31 24] 88

ReLU0 09 / 0 21 / 0 91 / 0 FF A[i,j] 4(i-j W 64 C 256(i-j


ReLU8a (0,i-j

196196196GTKWa eGHW56 AXI196

28VHDLVCD11212

PNGPS/PDF.gtkGHW/VCDJSONinde .ht l

/	ns	ns	
eight_instruction_en	4785	4785	1
eight_en0	4825	4955	14
u_load_ eight	4855	4985	14
u_instruction_en	4795	4795	1
buffer_en0	4835	4965	14
reg_ rite_en	5025	5155	14
acti_ation_instruction_en	4975	4975	1
buffer_ rite_en1	5305	5435	14
IRQ	5445	5445	1
R	5505	8805	56



/ 0 80 1 /

MMU

eight_en0


u_load_ eight

0 13

4825 4855 ns


MMU

14



/ 0 80 2 /

SDS MMU buffer_en0 lane reg_rite_en 5025 5155 ns 14
reg_accu ulate 0



				5305	5435 ns		0	13		7		ReLU
lane0	7	lane1	6	lane13	0		0					



/ 0 80 4 / IRQ

5035 5435 ns

IRQ


5435 ns

5445 ns

5445 ns


en_flags_cs 0 1

instruction_en_cs



/ 0 80 5 /

8 AXI AR 5455 ns R 5505 ns 5 56 8805 ns RRESP 0 RDATA RVALID/RREADY



/ 0 80 6 /

PDF


AXI

0 80000

0

WSTRB 0 3

lane12/13 AW W B



ReLU / 0 91 1 /

MMU

eight_en0


u_load_ eight

0 13

4825 4855 ns

MMU


14



ReLU / 0 91 2 /

SDS MMU buffer_en0 lane reg_rite_en 5025 5155 ns 14

reg_accu ulate 0



ReLU / 0 91 3 /

5305 5435 ns


0 13

7

ReLU

lane0 7 lane1 6 lane13 0

0



ReLU / 0 91 4 / IRQ

5035 5435 ns

IRQ


5435 ns

5445 ns

5445 ns


en_flags_cs 0 1

instruction_en_cs



ReLU / 0 91 5 /

8 AXI AR 5455 ns R 5505 ns 5 56 8805 ns RRESP 0 RDATA RVALID/RREADY



ReLU / 0 91 6 /

PDF

AXI

0 80000

0

WSTRB 0 3

lane12/13 AW W B

