

Lift Breakdown Incident Log & Resident Impact Assessment

Harmony Senior Residences · Senior Living · Singapore

Document ID	SL-02
Category	Vertical Transportation
Classification	Maintenance
Date	2026-07
Prepared by	Facility Management Team, Harmony Senior Residences

1. Incident log (January-June 2026)

Date	Lift	Fault	Downtime	Residents affected
08 Jan	Block A L1	Door failed to close	3.5 h	18
21 Jan	Block B L2	Door operator fault	6.0 h	22
04 Feb	Block A L2	Levelling fault	2.0 h	11
17 Feb	Block B L1	Entrapment: door lock fault (resident in wheelchair, 48 min)	5.0 h	20
02 Mar	Block A L1	Door operator fault	4.5 h	18
19 Mar	Block B L2	Drive fault	9.0 h	25
06 Apr	Block A L2	Door failed to close	2.5 h	12
22 Apr	Block B L1	Levelling fault	3.0 h	19
09 May	Block A L1	Door operator fault	5.5 h	17
15 May	Block B L2	Power dip; controller reset	1.0 h	9
28 May	Block A L2	Entrapment: door fault (resident with walker, 35 min)	4.0 h	14
06 Jun	Block B L1	Door operator fault	6.5 h	21
18 Jun	Block A L1	Drive fault	8.0 h	19
27 Jun	Block B L2	Levelling fault	2.5 h	10

Summary: 14 breakdowns and 2 entrapments in six months - 8 door-related faults, 3 levelling faults, 2 drive faults and 1 power dip. Lift contractor duty technician: Ahmad Rizal (hotline 9234 5678).

2. Impact on residents

- 38% of residents use wheelchairs, walkers or other mobility aids. When a block's lift is out of service, residents above level 3 are effectively confined to their floor.
- Three residents missed medical appointments because of breakdowns this half-year.
- Families escalated complaints after the two entrapments; one resident was trapped for 48 minutes.
- In an emergency, residents with limited mobility depend on staff for evacuation when a lift is unavailable.

3. Current maintenance regime

The lift contractor carries out monthly time-based servicing under a standard contract. Door components are replaced only after they fail. The contract measures response time, not lift availability, and there is no condition data on the lifts.

4. Interim measures

- Priority call-out SLA: the contractor must respond within 30 minutes (average achieved: 25 minutes).
- Resident buddy system: staff check on residents above level 3 during outages and deliver meals if needed.
- An evacuation chair on each floor, with staff trained in its use.

5. Open questions

- Can breakdowns be predicted before residents are stranded? Door faults dominate, but there is no data on door condition.
- Would a different contract model give the contractor an incentive to prevent failures rather than respond to them?
- There is no precedent within the senior-living portfolio for monitoring lift condition; options are being evaluated.