



Three layers, one continuous winding

a Complete winding



Hollow support

b Layer order at the end face



A B C