
## **Configuring the Master Station**

In this section, we'll cover connecting your hardware and executing functions to ensure your master station is fully configured before using the POS for the first time. This will be your primary device that the other devices will be dependent upon.

## **Connect and Power on Your Stand**

- 1. Slide the port cover off of the POS terminal on the cashier side.
- 2. Feed the DC port of the power cable through the openings on the bottom of the stand.
- 3. Plug the cable into the far-right matching port.
- 4. Reinstall the port cover.
- 5. Plug the other end of the power brick into a 120v outlet.



## **Connect the Customer-Facing Display (CFD)**

- 1. On the POS terminal, slide the bottom plate on the customer-facing side.
- 2. Locate the CFD port hidden behind this plate.
- 3. Uncoil the USB-C cable that is wrapped underneath the customer-facing display.
- 4. As pictured, the CFD cables will come with blue or black pull tabs. These are intended to provide leverage should the cable ever need to be unplugged.
- 5. Plug the USB-C cable into CFD port.
- 6. Secure the cable to the anchor point with the included zip tie.
- 7. Slide the bottom plate back into the POS stand and secure with the included screw.

